

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 CV 153

SITE IDENTIFICATION

Field Code Moscow Township School Site Name

Map Quad Hannah SW Site Name

LTL TWP 161 R 62 SEC 11 QQQ 7 QQ 7 Q 5

UTM N ZONE UTM E NAD 1927 NAD 1983

City: Street Number: Street Name: 94th Ave NE Urban Legal Description:

Subsection: 1 = N 1/2 2 = E 1/2 3 = S 1/2 4 = W 1/2 5 = NE 1/4 6 = SE 1/4 7 = SW 1/4 8 = NW 1/4

SITE DATA

Total # Architectural Features: 1

Fieldwork Date: 9/20/2016

Reconnaissance Survey Intensive Survey

Project Title & Supervisor: Country Schoolhouse Project

Report Title & Author(s):

Additional Information:

SHSND USE

Area of Significance Ecozone Verified Site CR Type

Recorded By Kathy Wilner Date Recorded 2/19/2017

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Moscow Township SchoolSITS# 32 CV**Complete one Page 2 for each architectural feature at the site.****Architectural Feature #** 1

Construction Date _____

Feature Type 9Condition 4Feature Date 2Context 7Plan Shape 6Structural System 25Primary Exterior 26Style Hipped Roof Box

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Concrete block basement Stories 1.5Roof/Cornice HipWindow Opening, some framing, no glassDating Method(s): Estimate**Feature Preservation Recommendation(s) (Check all that apply):** Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By Kathy Wilner **Date Recorded** 2/19/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**Field Code Moscow Township SchoolSITS# 32 CV**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a basement of concrete blocks. There are few wood shakes remaining on the hip roof of the school as well as the gable bumpout roof on the south slope. A yellow brick chimney has few bricks left and many of the fallen ones are still on the roof in the valley made by the bumpout. Bits of metal capping can be seen on some of the hips. The soffits are closed with beadboard. The building measures 36 feet by 36 feet.

There is a wide trim board located under the soffits on all sides of the school. The remaining siding is 6 inch wood lap with 6 inch corner trim with no paint. The gable bumpout on the south slope has one window opening with no glass. There are two windows on either side of the entry door with little framing and no glass. The broken entry door is reached up 7 concrete steps and there is a transom above the door with no glass. On the south wall there are two basement windows on the left side and a fuel door on the right side. Another small basement window is on the east side. On the west side there are 4 double hung windows, little framing and no glass. There is a door opening at ground level on the west wall that leads to the basement. The north wall is crumbling away and along with that the framing and sills of a bank of 5 window openings. The east wall has one small window near the south side. There were bathrooms in the southeast and southwest corners, through coat rooms to either side of the entry. There is a transom above the center door that gives entry into the school room. The interior walls are lathe and plaster with much falling away. The ceiling has completely fallen in. The floor is tongue and groove hardwood. The entry and school room both have wainscot. There are decorative cornices above the door that I can see. No blackboards remain. Light fixtures suggest electricity.

Recorded By Kathy Wilner Date Recorded 2/19/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code Moscow Township SchoolSITS# 32 CV**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

3. Access (to rural areas):

West of Langdon on Highway 5, 11 miles to 94th Ave NE, turn right and go north about 1 1/2 miles to see the road on the left and you will see the school about 1/2 mile west.

4. Site Area (ft²): _____5. Description of **SETTING**:

There is a large farm to the southwest and a cemetery also southwest. The school sits up on a hill and there are farm fields going all directions.

Recorded By Kathy Wilner Date Recorded 2/19/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Moscow Township School

SITS# 32 CV

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/19/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



South Side

Moscow Township School

9/20/2016

Kathy Wilner

CV



West Side



North Side

Moscow Township School

9/20/2016

Kathy Wilner

CV

East Side



bing maps


Notes

Moscow Township School

9/20/2016

Kathy Wilner

CV



Feature

