NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE 1	SITS# 32	<u>206</u>
SITE IDENTIFICATION			
Field Code Grand Valley Township		and the second second framework is	-
Map Quad <u>Merricourt SE</u> Map Quad	Site Name		
LTL TWP R SEC _ LTL TWP R SEC _	7 QQQ 6 QQQ QQQ QQQ QQQ		Q5 Q Q
UTMN UTME	ZONE NAD 1927	_ NAD 1983	1 1/2
City: Ellendale			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 91st St SE			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1⁄4
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 5/5/2016			
Reconnaissance Survey <u>√</u> Intensi	ive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Verified Site Non-Site	_ CR Type	_2
Recorded By Kathy Wilne (First Name & Last Name)	r Date	Recorded	1/9/2017 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data				
Field Code Grand Valley Township		SITS# 32DI		
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition 3		
Feature Date 2	Context 7	Plan Shape		
Structural System 25	Primary Exterior <u>26</u>	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Rock reinforced with concre	Stories 1			
Roof/Cornice_Gable				
Window Double hung window opeings with a bit of framing				
Dating Method(s): Estimate				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context ——with neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By Kathy (First Name & Last Name)		Recorded 1/9/2017 (mm/dd/year)		

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Grand Valley Township

SITS# 32_DI

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foudation of rocks reinforced with a bit of concrete. This building is in very tough shape with little or no upkeep for many years. The roof was covered with wood shakes, very few remain. There are the remnants of a yellow brick chimney near the north end of the school. There is a metal cap with finails at the peak of the gable roof. At both the north and south end of the school there are eave returns, a nice surprise at this very tired school. The soffits are open. There is the outline of an entry for the school and it has fallen into a heap just at the door end. The building measures 24 1/2 feet east to west and 18 feet north to south.

A wide trim board runs under the peaked ends of the roof with other siding being 6 inch wood lap with 6 inch corner trim. Some area of the school show planking where the siding has either been removed or fallen away. There are only openings remaining for the window locations, a couple have a few pieces of window frame and there is not glass. The interior of the school is wide open with light showing through the holes in the roof as the ceiling is mostly gone. The remaining pieces of the ceiling are pressed tin. The walls were covered with lathe and plaster but today are mostly stripped to the support boards with beadboard wainscot at the bottom 1/3. No blackboards remain and no indication that electricity was ever in the school.

We hiked a half mile into this location, I suspect the school is sitting in the original location .

Recorded By Kathy Wilner Date Recorded 1/9/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Grand Valley Township

SITS# 32__DI_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Geraldine Blumhardt Trust 408 5th Ave S PO Box 704 Ellendale ND 58436

3. Access (to rural areas):

North of Highway 11 on Highway 56, drive 5 miles to 91st St SE. Turn right (east) and drive 4 miles, the last 1/2 mile is minimum maintenance. You will see the school about 1/2 mile south on what would be 73rd Ave SE but there is not road. Hike in to the school.

4. Site Area (ft²): _____

5. Description of SETTING:

This building sits in a pasture set in rolling hills. There is an abandoned farm site to the northwest and wide open prairie all directions.

Recorded By Kathy Wilner Date Recorded 1/9/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Grand Valley Township

SITS# 32_DI

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/9/2017 (First Name & Last Name) (mm/dd/year)



East Side

Grand Valley Township School

5/5/2016 Kathy Wilner DI

North Side





South Side

Grand Valley Township School 5/5/2016

Kathy Wilner DI

West Side



5/15/2016

bing maps

Notes

SA

Grand Valley Township School 5/5/2016 Kathy Wilner VITURE 91-34-35E X



Frature