

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

UPDATE

Field Code \_\_\_\_\_ SITS# 32 DI X122

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_ Feature Type \_\_\_\_\_ Condition 1 \_\_\_\_\_
Feature Date \_\_\_\_\_ Context \_\_\_\_\_ Plan Shape \_\_\_\_\_
Structural System \_\_\_\_\_ Primary Exterior \_\_\_\_\_ Style \_\_\_\_\_
Original Owner's Ethnicity \_\_\_\_\_ Secondary Exterior \_\_\_\_\_ Architect/Builder \_\_\_\_\_

Other Information:

Based on 2009 aerial

Foundation \_\_\_\_\_ Stories \_\_\_\_\_

Window \_\_\_\_\_

Roof/Cornice \_\_\_\_\_

Dating Method(s): \_\_\_\_\_

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Lorna Meidinger Date Recorded 9/16/2010
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS SITE FORM  
ARCHITECTURAL SITES

Page 1

SITS # 3 2 DI X122

Field Code SCHOOL #2 Site Name SCHOOL #2  
Field Code \_\_\_\_\_ Site Name \_\_\_\_\_

Map Quad FULLERTON  
Map Quad \_\_\_\_\_

LTL	<input type="checkbox"/>	Twp	<u>132</u>	R	<u>62</u>	Sec	<u>26</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<input checked="" type="checkbox"/>	Q	<input checked="" type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

City \_\_\_\_\_

Street # \_\_\_\_\_ Street # \_\_\_\_\_

Street Name \_\_\_\_\_ Street Name \_\_\_\_\_

# of Features 1

<input type="checkbox"/> Feature #	<input type="checkbox"/> Feature Type	<input checked="" type="checkbox"/> Condition
<u>1</u> Construction Date	<u>9</u> Context *	
<input checked="" type="checkbox"/> Feature Date	<u>7</u>	<input checked="" type="checkbox"/> Plan Shape *
<u>3</u> Structural System **	<u>26</u> Primary Exterior *	<input type="checkbox"/> Secondary Exterior
<input type="checkbox"/> Ethnic	<input type="checkbox"/> Style *	
<u>11</u> <u>1994</u> Fieldwork Date		<input type="checkbox"/> Architect/Builder
		<input type="checkbox"/> Other Information

<u>45</u> Soil Association	<u>18</u> Ecozone	<input checked="" type="checkbox"/> Area Sign	_____ MS Number
_____ Soil Association	_____ Ecozone	<input type="checkbox"/> Area Sign	_____ MS Number
<input checked="" type="checkbox"/> CR Type	<input type="checkbox"/> Verified Site	<input type="checkbox"/> Non-Site	<input checked="" type="checkbox"/> ECF <input checked="" type="checkbox"/> T F
<input type="checkbox"/> State Registry		<input checked="" type="checkbox"/> National Register	

Coder ROLENE SCHLIESMAN

Date Coded 6 FEB 1995

Reconnaissance Survey \_\_\_\_\_

Intensive Survey \_\_\_\_\_

Manuscript/Report Title: \_\_\_\_\_

Author(s): \_\_\_\_\_

SITE DATA

FEATURE DATA

SHSND USE

**FIELD MANUAL  
NDCRS ARCHITECTURAL SITE FORM**

**FEATURE TYPE**

**AGRICULTURE**

- 82 Animal Shelter/Stable
  - 62 Barn
  - 92 Blacksmith Shop
  - 66 Chicken Coop/Poultry House
  - 3 Clinic, Animal/Veterinarian
  - 43 Corral/Enclosure/Pen
  - 70 Experiment Station
  - 5 Farm, Dairy
  - 1 Farm/Farmstead
  - 61 Granary/Bin
  - 91 Greenhouse/Nursery
  - 12 Hatchery, Ann'l/Bird/Fish
  - 67 Ice/Smoke House/Root Cellar
  - 64 Line Shack
  - 14 Pump/Well
  - 77 Pump House/Well House
  - 4 Ranch
  - 61 Silo/Silage Pit
  - 13 Stock Dam
  - 15 Storage Building
  - 16 Storage Yard
  - 69 Summer Kitchen
  - 14 Well/Pump
  - 17 Windmill
  - 71 Work shop
- ARTS AND ENTERTAINMENT**
- 75 Auditorium/Lecture Hall
  - 74 Cinema/Theater
  - 75 Lecture Hall
  - 99 Museum/Gallery
  - 75 Opera House
  - 73 Studio, Photo/Art/Sculpt
  - 74 Theater
- COMMERCE**
- 76 Bank/S & L/Financial
  - 68 General Store
  - 47 Shopping Center/Mall
  - 47 Store, Retail
  - 68 Trading Post
  - 15 Warehouse
- COMMUNICATIONS**
- 87 Newspaper Office
  - 87 Print Shop
  - 85 Radar Facility
  - 93 Radio/TV Station
  - 89 Teleph./Telegr. Facil.
  - 17 Tower, Radio/TV/Microwave
- EDUCATION**
- 19 Business College
  - 75 Class Room/Lecture Hall
  - 19 College/University
  - 70 Laboratory
  - 20 Library
  - 9 School
  - 19 Seminary
  - 19 Trade/Technical School
- ENGINEERING**
- 21 Bridge/Trestle
  - 22 Canal/Flume

- 13 Dam
  - 17 Tower
- FOOD SERVICE**
- 90 Bakery
  - 28 Bar/Tavern
  - 24 Bottling Plant
  - 24 Brewery/Distillery
  - 90 Butcher Shop
  - 25 Cannery
  - 97 Creamery
  - 97 Dairy Processing Plant
  - 25 Frozen Food Locker
  - 26 Grocery Store
  - 90 Meat Packing Plant
  - 27 Mill, Grist/Flour
  - 23 Restaurant/Cafe/Mess Hall
  - 25 Sugar Refinery
- FUNERARY**
- 29 Cemetery
  - 78 Gravestone
  - 78 Memorial
  - 78 Monument
  - 29 Mortuary
- GOVERNMENT**
- 32 Border Crossing Station
  - 30 City Hall
  - 84 Correctional Facility/Jail
  - 59 Courthouse
  - 32 Customs House
  - 58 Fire Station
  - 59 Government Office
  - 86 Indigent Home
  - 86 Orphanage
  - 33 Pest House
  - 32 Police Station
  - 18 Post Office/Mail Station
  - 10 Sanitary Land Fill
  - 10 Sewage Treatment Plant
  - 32 Sheriff's Office
  - 73 Township Hall
  - 98 Water Treatment Plant
- HEALTH CARE**
- 33 Clinic/Dispensary
  - 33 Hospital/Infirmary
  - 86 Nursing Home
- INDUSTRIAL**
- 34 Brick Manufacturing Plant
  - 88 Bulk Plant
  - 34 Concrete Mfg. Plant
  - 31 Elect. Gener. Facility
  - 36 Elect. Transform. Facility
  - 38 Elect. Transmiss. Facility
  - 34 Factory/Foundry
  - 96 Gas Storage
  - 96 Gas Transmission Facility
  - 14 Gas Well
  - 11 Grain Storage, Commercial
  - 36 Lumber Yard
  - 37 Mill, Saw
  - 37 Mill, Stamp/Minerals Refin.

- 35 Mine/Quarry
  - 96 Oil Refinery
  - 58 Oil Tank Battery
  - 96 Oil Transmission Facility
  - 14 Oil Well
  - 96 Pipeline
  - 71 Repair Shop
  - 16 Storage Yard
  - 38 Tipple
  - 15 Warehouse
  - 92 Welding/Blacksmith Shop
- LANDSCAPE ARCHITECTURE**
- 78 Fountain
  - 78 Garden
  - 78 Monument
  - 39 Park
- MILITARY**
- 79 Army
  - 60 Battlefield
  - 79 Bastion
  - 79 Blockhouse
  - 44 Camp Site, Temporary
  - 8 Camp, Semi-Permanent
  - 79 Defensive Works
  - 8 Fort/Cantonment/Post/Base
  - 79 Missile Site
  - 79 Pallisade
  - 39 Parade Ground
  - 59 Post/Base Exchange(PX/BX)
  - 79 Powder Magazine
  - 51 Rifle Range
  - 68 Sutler's Store
  - 48 Trail
- OFFICE/HEADQUARTERS**
- 45 Administrative
  - 45 Business
  - 80 Fraternal/Sororal
  - 80 Lodge
  - 45 Organizational
  - 46 Professional
  - 80 Social
- RECREATION/SPORTS**
- 52 Arcade/Casino
  - 32 Billiard Parlor/Pool Hall
  - 57 Boat Landing, Recreational
  - 51 Camp/Picnic Grounds
  - 94 Fairgrounds
  - 91 Grandstand
  - 51 Play ground
  - 52 Recreation Area, Indoor
  - 51 Recreation Area, Outdoor
  - 51 Resort
  - 94 Rodeo Grounds
  - 95 Sport Facility, Indoor
  - 81 Sport Facility, Outdoor
- RELIGIOUS**
- 54 Chapel, Non-Denom.
  - 9 Church School
  - 53 Church, Catholic
  - 63 Church, Protestant

- 42 Convent/Monastery
  - 90 Fellowship Hall
  - 40 Parsonage/Manse/Rectory
  - 19 Seminary
  - 78 Shrine
  - 54 Synagog
- RESIDENTIAL**
- 42 Barracks/Dorm./Bunk House
  - 41 Dwelling, Double Unit
  - 42 Dwelling, Multiple Unit
  - 40 Dwelling, Single Unit
  - 55 Garage/Carriage House
  - 64 Hotel/Motel/Inn
  - 65 Mobile Home
  - 50 Privy
- TRANSPORTATION**
- 49 Airport/Airfield/Land. Fld.
  - 56 Boat Landing, Com'c'l/Steam
  - 57 Boat Landing, Recreational
  - 21 Bridge/Trestle
  - 59 Depot/Terminal
  - 82 Ferry
  - 82 Ford
  - 72 Freight Yard
  - 88 Fuel Station/Yard, Coal/Wood, etc.
  - 88 Gasoline Station
  - 55 Hanger
  - 48 Highway
  - 62 Livery
  - 70 Loading Platform
  - 48 Railroad Grade/Tracks
  - 56 Rest Stop
  - 48 Road
  - 73 Roundhouse
  - 48 Siding
  - 78 Signal
  - 62 Stable
  - 48 Spur
  - 56 Stage Station
  - 72 Switch Yard
  - 48 Trail
  - 82 Tunnel
  - 83 Turn-around
- MISCELLANEOUS**
- 2 Accident/Disaster Site
  - 10 Dump
  - 73 Spring
  - 77 Spring House
  - 17 Tower
  - 7 Town/City/Colony/Settlement
  - 99 Other

**STRUCTURAL SYSTEM/EXTERIOR MATERIALS**

- |                              |                             |
|------------------------------|-----------------------------|
| 1. Asbestos Siding/Shingle   | 16. Metal, Sheet            |
| 2. Asphalt Siding/Shingles   | 17. Perma Stone             |
| 3. Brick                     | 18. Plastic, Vinyl          |
| 4. Clay Tile                 | 19. Pole                    |
| 5. Composition Board         | 20. Stone, Cut              |
| 6. Concrete Block            | 21. Stone, Uncut            |
| 7. Concrete, Poured/Cast     | 22. Stucco/Plaster          |
| 8. Earth/Clay                | 23. Tarpaper                |
| 9. Earthen Brick             | 24. Thatch                  |
| 10. Glass, Block             | 25. Wood Frame              |
| 11. Glass, Pigmented         | 26. Wood, Horizontal siding |
| 12. Log                      | 27. Wood, Shingles/Shakes   |
| 13. Metal, Decorative Wood   | 28. Wood, Vertical Siding   |
| 14. Metal, Frame             | 29. Other                   |
| 15. Metal, Horizontal Siding |                             |

**STYLES**

- |                               |                              |
|-------------------------------|------------------------------|
| 1. American Foursquare/Cube   | 20. Prairie Style            |
| 3. Beaux Arts/Neo Classical   | 22. Queen Anne               |
| 4. Boomtown/False Front       | 23. Ranch/Split Level        |
| 5. Bungalow                   | 24. Richardsonian Romanesque |
| 6. Chicago School             | 25. Mansardic/Second Empire  |
| 7. Colonial Revival           | 26. Shingle Style            |
| 8. Craftsman                  | 27. Stick Style              |
| 9. International Style        | 28. Ethnic/Vernacular        |
| 10. Early Brick Commercial    | 29. Other Style              |
| 11. Elizabethan/Tudor Revival | 30. Romanesque               |
| 12. Eastern European Revivals | 31. Hipped Roof Box          |
| 13. Gothic Revival            | 32. Transitional Brick Comm. |
| 14. Gabled Front              | 33. Modular/Lustron          |
| 15. Moderne                   | 34. Plain Residential        |
| 16. Italianate                | 35. Other Contemporary       |
| 17. Mission/Pueblo Revival    |                              |

**ETHNIC**

- 0. Unknown
- 1. African
- 2. American Indian
- 3. Arabic
- 4. British/Celtic
- 5. Canadian
- 6. Czech/Bohemian
- 7. Danish
- 8. Dutch
- 9. Finnish
- 10. French
- 11. German/Austrian/Swiss
- 12. German-Russian
- 13. Greek
- 14. Icelandic
- 15. Irish
- 16. Italian
- 17. Jewish
- 19. Norwegian
- 20. Oriental
- 21. Polish
- 22. Russian
- 23. Scot
- 24. Spanish
- 25. Swedish
- 26. Ukrainian
- 27. Other

**FEATURE DATE**

- 1. pre-1880
- 2. 1880-1900
- 3. 1900-1915
- 4. 1915-1930
- 5. 1930-1945
- 6. post-1945

**CONDITION**

- 1. Destroyed
- 2. Inundated
- 3. Very Poor
- 4. Poor
- 5. Fair
- 6. Good
- 7. Excellent

**PLAN SHAPE**

- 0. Not Applicable
- 1. Circular
- 2. Irregular
- 3. L-Shaped
- 4. Polygonal
- 5. Rectangular
- 6. Square
- 7. T-Shaped
- 8. U-Shaped
- 9. Other

**CONTEXTS**

- 1. Aviation
- 2. Bridges
- 3. Colonization
- 4. Commerce
- 5. Communications
- 6. Depression, the Great
- 7. Education
- 8. Energy Development
- 9. Entertainment
- 10. Exploration
- 11. Farming, Bonanza
- 12. Farming, Dairy
- 13. Farming
- 14. Fur Trade
- 15. Government, National
- 16. Government, Territorial
- 17. Government, State
- 18. Government, Local
- 19. Horticulture
- 20. Industrial Development
- 21. Irrigation and Conservation
- 22. Military
- 23. Mining, Coal
- 24. Petroleum
- 25. Railroads
- 26. Ranching, Open Range
- 27. Ranching, Fee Simple
- 28. Religion
- 29. Roads, Trails, and Highways
- 30. Rural Settlement
- 31. Urban Settlement
- 32. Water Navigation

NDCRS SITE FORM

Photograph

Field # SCHOOL #2 Site # \_\_\_\_\_

TAKEN BY WES ALMQUIST HOPKINS, MN

Photo I.D. Code \_\_\_\_\_

Storage Location NO NEGS

Include direction facing, feature number, and photo caption for each submitted photograph.



1. VIEW FROM SOUTH.



2. EAST ELEV.  
LOOKING SW

NDCRS SITE FORM

Photograph

Field # SCHOOL #2 Site # \_\_\_\_\_

TAKEN BY WES. ALMQUIST, HOPKINS, MN

Photo I.D. Code \_\_\_\_\_

Storage Location NO NEG

Include direction facing, feature number, and photo caption for each submitted photograph.



3. N. ELEV.  
TAKEN FROM  
E-W ROAD.



4. 1925 ENTRY.

NDCRS SITE FORM

Photograph

Field # SCHOOL #2 Site # \_\_\_\_\_

TAKEN BY NEE ALMQUIST

Photo I.D. Code \_\_\_\_\_

Storage Location NO NEG

Include direction facing, feature number, and photo caption for each submitted photograph.



5. LOOKING  
SW.



6. FOLDING  
DOORS

NDCRS SITE FORM      Photograph      Field # SCHOOL#2 Site # \_\_\_\_\_  
TAKEN BY WES AUMONIST, HOPKINS, NJ

Photo I.D. Code \_\_\_\_\_  
Storage Location NO NEBS  
Include direction facing, feature number, and photo caption for each submitted photograph.



7. FOLDING  
DOORS



8. INTERIOR

OVER →



9. VIEW FR. FRONT ROOM TOWARDS  
ENTRY



# PHOTOGRAPH KEY

#. 1

View from the south,.....east-west road in the background....The building looks like it is in a low spot,and it is,water gets in the basement. Originally it was not a low spot,but when the new roads,the one in the background,and the north-south one to the immediate west of the school, were graded up,they were then higher than the level of the school by about four feet.The north-south road is a county road and was raised another two feet when it was graded up and paved about 10 years ago.In wet weather the school basement has three feet of water in it,and access is difficult to get in the building.The furnace (which would not have been useable)is ruined,and some desks that were stored there are beyond restoration.There are others that were stacked one on top of the other, that just the bottom two are ruined.....The steps go to the entry that was constructed in 1925,when the addition was added:The door to the left, (boarded up) goes to the basement.All windows were boarded up,which has helped to preserve the structure.

#2

East side,looking to the SW..(some sun reflection in lens of camera) Except for paint,the exterior is in excellent condition,considering its age.The height of the grading of the county road in the background gives you some idea of how water will stand around the school.

#3

North side of building,taken from the east-west road.I believe the right half is the original part built in 1901.

#4

This is the entry that was added in 1925.(note coat hooks on wall)One of the original??? desks.There are more of these in the basement,some have been in water(as above).

#5

View from NW looking to SE.I think the metal hood that shows up on both east and west sides of the basement was for venting the basement to dry it out,or air for the furnace.

#6

Interior view showing the folding doors used to divide the classrooms. The shelving with the doors is part of a series of bookcases .The white stuff on the floor is plaster that has fallen from the ceiling.

#7

View from the other room,again showing bookcase and door over shelves which probably held paper,paste,and other teaching materials.

#8

View from east half of interior with teachers desk.Note blackboards, probably installed when school was expanded in 1925.Also note shades over windows.Windows show little signs of rot,and most glass is intact.

#9

View from front of room.looking toward entry-way/The windows on the floor were used as storm windows,and were taken off when the plywood was put on.

#10

"Klien and Lee" building,second building north of the Carroll House.Built in the early 1900's.Originally housed a "general store",later a hardware store, grocery store,restaurant etc.,on lower level,with living areas on the second level.Door in center opens to stairway going to upper level.

