

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 DU 2349

SITE IDENTIFICATION

Field Code Hope School #1

Site Name Hope School #1
Site Name _____

Map Quad Dunn Center NE
Map Quad _____

LTL	TWP	<u>146</u>	R	<u>93</u>	SEC	<u>29</u>	QQQ	<u>7</u>	QQ	<u>7</u>	Q	<u>7</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
 UTM _____ E NAD 1927 _____ NAD 1983 _____

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: Dunn Center

Street Number: _____

Street Name: 95th Ave NW

Urban Legal Description: _____

SITE DATA

Total # *Architectural* Features: 1

Fieldwork Date: 4/13/2016

Reconnaissance Survey Intensive Survey

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s):

Additional Information: _____

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>22</u>	Verified Site <u>1</u>	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By Kathy Wilner Date Recorded 1/24/2017
 (First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Hope School #1SITS# 32 DU

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9Condition 5Feature Date 2Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Hipped Roof Box

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Concrete basementStories 1.5Roof/Cornice Hip, gable dormerWindow Double hung, many shutteredDating Method(s): Estimate

Feature Preservation Recommendation(s) (Check all that apply):

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigationRecorded By Kathy Wilner
(First Name & Last Name)Date Recorded 1/24/2017
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**Field Code Hope School #1SITS# 32 DU**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a concrete foundation. The hip roof of the school, the half hip roof of the porch and the gable roof of the dormer are all covered with asphalt shingles with some metal capping at the hips and on the dormer. The south slope of the roof has wood shakes. The soffits were closed, much of the material has fallen away. There is not chimney. There is a dormer on the west facing slope of the roof with two window openings, no glass. At the peak there is a flag pole. The building measures 38 feet east to west and 32 feet north to south with a porch that measures 20 feet north to south and 8 feet east to west.

There is a wide trim board under the soffits on all four sides of the school. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim with waterboard and a wide trim board at the bottom of the walls. The porch on the west wall of the school has three of four posts remaining, the floor is wood and the roof is sagging at the southwest corner. There are no steps to the porch and the entire south half wall has fallen to the ground. There is as 3 panel wood door with 4 pane window at the top. To either side of the entry door are two smaller double hung windows with glass. Beyond the porch, on the west wall, are two smaller fixed pane windows, one is covered. An opening on the south side is covered. The east wall has a bank of 6 double hung, two over two, windows with all but one covered and some framing and no glass in that uncovered window. There is a locked 3 panel wood door on the north wall near the west end, 4 pane fixed window at the top, that is at ground level and leads to the basement. The concrete basement is cracking in places, has a window on the north and east sides and a fuel door near the east end of the north wall.

Interior information came from a former student and she was happy to share. There is a foyer just inside the door and three doors lead to the school room, boys coat room, left, the girls coat room right with bathrooms beyond through the coat rooms. There are doors leading into the school room from each coat room. In the northwest corner of the school room is the inside stairway leading to the basement. There was a floor grate for head with the furnace in the basement. A small library was located in the southwest corner of the school room. A blackboard filled the remainder of the south wall. The floor is tongue and groove hardwood. The walls and ceiling are covered with lathe and plaster. The school was operational until the early 1960's. This former student shared that their teacher had a bed in the classroom.

Recorded By Kathy Wilner Date Recorded 1/24/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code Hope School #1SITS# 32 DU**Complete one Page 4 for the entire site.****2. Owner's Contact Information:**

Beni Paulson
3344 83M AVE SW
Richardton ND 58652

3. Access (to rural areas):

From Dunn Center, go north out of town to 4th St SW, turn right to go 1/2 mile to 97th Ave SW, turn left and go north 3 miles to 1st St SW, turn right and go 2 miles east to 95th Ave SW, turn left and drive north 2 miles to the intersection of 1st St NW and 97th Ave NW. The school is north of the intersection on the right side of the road.

4. Site Area (ft²): _____**5. Description of *SETTING*:**

There is a farm south, trees and pasture north and east, hilly farm land and pasture.

Recorded By Kathy Wilner Date Recorded 1/24/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Hope School #1

SITS# 32 DU

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/24/2017
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



West Side

Dunn Center #1

4/13/2016

Kathy Wilner

DU

North Side





East Side

Dunn Center #1

4/13/2016

Kathy Wilner

DU

South Side



bing maps

Notes

Type your notes here
Dunn Center #1
4/13/2016
Kathy Wilner
DU

