NDCRS 2009

196

NDCRS	ARCHITECTURAL	SITE	FORM	
	PAGE 1			
			OFTO# 20	DV

SITE IDENTIFICATION		5115# 32_0	
Field Code <u>Upland Township School #2</u> Map Quad_ <i>Wild Y05C</i>	Site Name Usiland School ++3		
Map Quad	-		
LTL TWP R SEC . LTL TWP R SEC .	QQQ	QQ <u>6</u> QQ QQ QQ	Q 7 Q Q
UTMN UTME	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 91st St NW			$6 = SE^{1/4}$ 7 = SW^{1/4}
Urban Legal Description:			8 = NW ¹ ⁄ ₄
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 8/21/2016			
Reconnaissance Survey 🖌 Intens	ive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			anna la tarak sana di katana ang pa
SHSND USE Ecozone Area of Significance Ecozone Area of Significance Ecozone Area of Significance Ecozone	Verified Site Non-Site	CR Type	2
Recorded By Kathy Wilne (First Name & Last Name)	r Date R	ecorded	2/2/2017
(First Name & Last Name)			(mm/dd/year)

NDCRS 2009

NDCRS	ARCHITECTURAL SITE F	FORM
	PAGE 2—Feature Data	

	FAGE 2-Feature D	ala				
Field Code Upland Township Sch	Field Code_Upland Township School #2 SITS# 32_DV					
Complete one Page 2 for each architectural feature at the site.						
Architectural Feature #1	_					
Construction Date	Feature Type <u>9</u>	Condition 6				
Feature Date 3	Context 7	Plan Shape 6				
Structural System 25	Primary Exterior 26	Style <u>Other St</u>	yle			
Original Owner's Ethnicity	Secondary Exterior	Architect/Build	der			
Other Information: Foundation Poured concete baseme						
Roof/Cornice_Cross hipped		heren alaran antar se en portan ara fais patriar der auforstationen parta este in				
Dating Method(s): estimat	e		00000000000000000000000000000000000000			
Feature Preservation Recommendation(s) (Check all that apply):						
Individual nomination						
Contributes to a potential dis	strict					
No nomination potential						
Will not contribute to a district						
Potential district—feature would be a contributing element if other properties constitute a district						
Thematic nomination potential						
Component of a historic site or landscape						
recreates original site, orient	e choices)—a) relocation occ tation, landscape, & spatial re d) relocation has damaged e	lationships; c) compa				
Historical associations require further investigation						
Recorded ByKat (First Name & Last Nam	hy Wilner	Date Recorded	2/2/2017 (mm/dd/year)			

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Upland Township School #2

SITS# 32 DV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature, also known as Highland District #3, is a one room school on a poured concrete basement. The cross hipped roof is covered with asphalt shingles. A large red brick chimney is located on the west slope of the entry part of the roof. The soffits are closed with shiplap. The building measures 28 feet north to south by 30 feet east to west.

Siding begins with a wide trim board at the top of the exterior wall just under the soffits. The rest of the siding is 6 inch wood lap with 6 inch wood corner trim with waterboard and a skirting board at the bottom. Below the siding are 4 pane fixed glass windows, 2 on the west side, 2on the east, 2 on the north side and a fuel door on the east wall. There is a porch with a large set of wooden steps leading to a wood stoop under an extension of the entry roof. The west side of the porch has a box wall with siding both sides. There is a column at the southeast corner. A 5 panel wood door opens into the entry. There is a set of steps going to the basement at the left part of the entry and there is a wood stair rail along the right side. On the south west half of the entry there are bathrooms and coatrooms. There are beadboard dividers for the coatrooms and narrow halls leads to narrow, 5 panel wood doors of the bathrooms. The school room is a large room with lathe and plaster on the walls and ceiling with picture railing. The north wall has 8 double hung windows, with glass, and 4 of them have screens windows. The floor is narrow tongue and groove hardwood. There are blackboards on the east wall and the west wall to the school room door and these boards have a 2 foot corkboard above them. Light fixtures suggest electricity. There are benches and a teachers desk in the school.

Recorded By

(First Name & Last Name)

Date Recorded_

2/2/2017 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Upland Township School #2

SITS# 32_DV_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Jess Homer Family Trust ETAL PO 635 Wildrose ND 58795

3. Access (to rural areas):

Crosby, south on Highway 42 14 miles, to turn left and so east on 89th St NW 5 1/2 miles to turn left again and go north on 114th Ave NW and turn right and go 1 1/2 mile to see the school on your left.

4. Site Area (ft²):_____

5. Description of SETTING:

The area around the school is kept mowed and farm sites to the southwest and northeast, pasture land with sloughs.

Recorded By Kathy Wilner Date Recorded 2/2/2017 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM **PAGE 5—SITE DESCRIPTION**

Field Code Upland Township School #2

SITS# 32 DV

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner

Date Recorded

2/2/2017 (mm/dd/year)



South Side

Upland Township School #28/21/2016Kathy WilnerDV

East Side





North Side

Upland Township School #28/21/2016Kathy WilnerDV

West Side



DIVIDE COUNTY

