NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITE IDENTIFICATION			3113# 32_5	
Field Code Roseville School #1	Sit	e Name Rosevil	le School #	
Map Quad CVOSby Map Quad	Sit	e Name		This is no contract and an all an all and an all and an all and an all and an all an all an all and an all
LTL TWP163	SEC	QQQ QQQ	QQ <u>6</u> QQ QQ QQ	Q <u>7</u> Q Q Q
UTM 5418863 UTM 624395	N E	ZONE <u>13N</u> NAD 1927	NAD 1983 <u></u>	Subsection: 1 = N½
City: Crosby				$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:				4 = W½ 5 = NE¼
Street Name: 5th Ave SW				6 = SE¼ 7 = SW¼
Urban Legal Description:				8 = NW1/4
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date: 8/21/2016				
Reconnaissance Survey	Intensive S	urvey		
Project Title & Supervisor: Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
Area of Significance Area of Significance Ecozone Area of Significance Ecozone		Verified Site	. CR Type	2
Recorded By Kat	hy Wilner	Date F	Recorded	2/2/2017 (mm/dd/year)
f. not raine a rast rail	101			() car

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Roseville S	Field Code Roseville School #1 SITS# 32 DV			
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature	#1			
Construction Date190	6 Feature Type	9 Condition 7	T Andrewson and the second sec	
Feature Date 3	Context 7	Plan Shape	5	
Structural System 25	Primary Exterior	26 Style Other	Style	
Original Owner's Ethnicit	y Secondary Exter	rior Architect/Bu	uilder	
Other Information:				
Foundation Concrete		Stories1		
Roof/Cornice Gable				
Window Double hung, sn	nall fixed pane			
Dating Method(s): Sign o	on the school			
Feature Preservation	Recommendation(s) (Chec	k all that apply):		
Individual nomina	ation			
Contributes to a	potential district			
No nomination po	otential			
——Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
——Component of a historic site or landscape				
 Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility 				
Historical associations require further investigation				
Recorded By(First Nam	Kathy Wilner e & Last Name)	Date Recorded _	2/2/2017 (mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Roseville School #1			SITS#	32_DV
--------------------------------	--	--	-------	-------

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The gable roof of the school, half hip of the east addition, pyramidal roof of the bell tower and gable entry are covered with asphalt shingles. There is short red brick chimney at the north end of the roof at the peak. The soffits are closed. There is a bell tower at the west end of the peak. The base is wood constructed with wood lap siding, four corner posts rise up to hole the pyramidal roof. The openings are curved at the top whe it meets the underside of the top. There is a flagpole at the peak of the tower. The building measures 22 feet east to west and 18 feet north to south with the east addition measuring 10 feet by 18 feet and the entry measuring 8 feet by 6 feet.

Siding begins with a wide trim board at the top of the exterior wall just under the soffits. The rest of the siding is 6 inch wood lap with 6 inch wood corner trim. The school has great paint. The 3 panel wood door with three pane vertical fixed pane window at the top is locked. There is a wood stoop for entry. The interior walls of the entry are covered with ship lap. The school walls and ceilign are covered with beadboard. There is an addition on the east end that houses the library as well as bathrooms. The floor is tongue and groove pine. The school has student desks, a teachers desk, many books and items common in a country school. There is a band of 5 double hung windows with all glass on the south side of the school. A smaller window is on the south side of the addition with two small, three vertical fixed pane windows on the east in the bathrooms and yet another fixed window on the north half of the east wall. There are oil lamps hanging from the ceiling in the manner of old. There is exterior wiring on the southeast side that suggests electricity is available.


Recorded By	Kathy Wilner	Date Recorded	2/2/2017
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Roseville School #1	SITS# 32_	DV
Complete one Page 4 <u>for the entire site</u> .		
2. Owner's Contact Information:		
Divide County Museum and Historical Society C/O Kurt Kocher PO Box 130 Crosby ND 58730		
3. Access (to rural areas):		
The Pioneer Village is Crosby is located on the west side,	north of 5th Ave SW and we	st of 3rd St.
4. Site Area (ft²):		
5. Description of SETTING : The school is in a Pioneer Village with other older building	ıs and display buildings all ar	ound.
Recorded By Kathy Wilner	Date Recorded	2/2/2017
(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Roseville School	ol #1	SITS# 32_[OV
6. Summary of ALL Site	e Features & Evaluation of	Significance:	
References/Comments:Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
DOWGOTTND 30410			
Recorded By(First Name & L	Kathy Wilner .ast Name)	_ Date Recorded	2/2/2017 (mm/dd/year)



West Side


Roseville School #1


8/21/2016

Kathy Wilner

DV

North Side






South Side

Roseville School #1

8/21/2016

Kathy Wilner DV

East Side





Rosevile School No. 1

8/21/2016

Kathy Wilner

DV



Imagery ©2016 Google, Map data ©2016 Google 1