**NDCRS 2009** 

State Historical Society of North Dakota

NDCRS ARCHITECTURAL	. SITE	FORM		
PAGE 1				101
		SITS# 32	DV	273

SITE IDENTIFICATION		0110# 02	
Field Code Elkhorn Township School #			
Map Quad SKjermo Lake	Site Name		
LTL TWP63 R102 LTL TWP R LTL TWP R LTL TWP R	SEC QQQ _ SEC QQQ _	2QQ 7 QQ QQ QQ QQ	Q 7 Q Q Q
UTM UTM	N ZONE	927 NAD 1983	1 11/2
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			$4 = W\frac{1}{2}$ 5 = NE $\frac{1}{4}$
Street Name: 149th Ave NW			6 = SE¼ 7 = SW¼
Urban Legal Description:		of management	8 = NW1⁄4
SITE DATA			
Total # Architectural Features:	1		
Fieldwork Date: 8/21/2016	_		
Reconnaissance Survey 🗹	Intensive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Ecozone Area of Significance	21Verified Site Non-Site	CR Type	2
Recorded By Kathy (First Name & Last Name)	Wilner	Date Recorded	2/2/2017 (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data					
Field Code Elkhorn Township School #3		SITS# 32_DV			
Complete one Page 2 for each architectural feature at the site.					
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition 5			
Feature Date 3	Context 7	Plan Shape <u>5</u>			
Structural System 24,25	Primary Exterior <u>26</u>	Style_Other Style			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information: Foundation <u>Rocks and concrete</u>		Stories <u>1</u>			
Roof/Cornice_Gable					
Window Double hung, no glass					
Dating Method(s): Estimate					
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					

- \_No nomination potential
- -Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- ... Thematic nomination potential
- -Component of a historic site or landscape

Moved (specify all applicable choices)-a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

<b>Recorded By</b>	Kathy	Wilner	Date Recorded	2/2/2017
	(First Name & Last Name)			(mm/dd/year)

**NDCRS 2009** 

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Elkhorn Township School #3

SITS# 32 DV

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of rocks and concrete. The building looks to be two separate buildings put together from the outside but the inside looks like one school room. The gable roof is covered with wood shakes. The soffits are closed. There is a red brick chimney at the peak in the middle of the the south part of the building. The building measures 32 feet north to south and 12 feet east to west.

There siding is ship lap with 6 inch wood corner trim. There is a have circle set of concrete steps up to a concrete stoop that lead up to the 5 panel wood entry door. Inside the entry is a coat room to the right and two toilets to the left, vents can be seen on the outside of the entry wall on the west side. Again you step through another wood door into the school proper. Walls in the school room as well as the entry are all covered with wall board. Sheets of wallboard or fiberboard were used for the ceiling and much of that has fallen in. There are two double hung windows at the north end of the room, four more, in some cases three vertical pane, windows on the east wall as well as one on the west side, all with little framing and little glass. The floor is tongue and groove pine. No blackboards remain in the school. Light fixtures and a switch suggest electricity.

Recorded By\_

(First Name & Last Name)

Date Recorded

2/2/2017 (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Elkhorn Township School #3

SITS# 32\_DV\_\_\_\_

#### Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Butch Haugland Haugland's Blooming Prairie LLC 12420 104th St NW Ambrose ND 58833

3. Access (to rural areas):

8 miles west of Fortuna on Highway 5 to 149th Ave NW, turn right and drive north 4 miles to see the school on the right.

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of **SETTING**:

Hilly pasture, cattle and wide open spaces.

Recorded By Kathy Wilner Date Recorded 2/2/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Elkhorn Township School #3

SITS# 32\_DV\_\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/2/2017 (First Name & Last Name) (mm/dd/year)



West Side

Elkhorn Township School #3 8/21/2016

Kathy Wilner DV

# East Side





South Side


Elkhorn Township School #3

8/21/2016

Kathy Wilner

DV

North Side



Google Maps



Elkhorn Township School #3

8/21/2016

Kathy Wilner

DV



Imagery ©2016 Google, Map data ©2016 Google 100 ft