NDCRS 2009

State Historical Society of North Dakota

NDCRS	ARCHITECTURAL	SITE	FORM	
PAGE 1				

	PAGE 1	SITS# 32_[197
SITE IDENTIFICATION		SITS# 32_1	JV <u>~11</u>
Field Code <u>LIncoln Valley Twsp School</u> Map Quad <u>Al-EXANDVIA</u> Map Quad			
LTL		QQ QQ	Q 7 Q Q Q
UTMN UTME	ZONE NAD 1927	7 NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:	with the low of the state of the	-	$3 = S\frac{1}{2}$
Street Number:		-	$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 99th St NW		-	6 = SE¼ 7 = SW¼
Urban Legal Description:		_	8 = NW1/4
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 8/21/2016			
Reconnaissance Survey 🖌 Intens	sive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Z Ecozone ZI Area of Significance Ecozone Ecozone Ecozone Area of Significance Ecozone Ecozone Ecozone	Verified Site Non-Site	CR Type	2
Recorded By Kathy Wilne (First Name & Last Name)	er D	ate Recorded	2/3/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS	ARCHITECTURAL SITE FORM
	PAGE 2—Feature Data

2.0			
Field Code Lincoln Valley Twsp School		SITS# 32_DV	
Complete one Page 2 for each	architectural feature at th	e site.	
Architectural Feature #1			
Construction Date	Feature Type <u>9</u>	Condition 6	
Feature Date 3	Context.7	Plan Shape <u>5</u>	
Structural System 25	Primary Exterior <u>26</u>	Style Other Style	
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder	
Other Information: Foundation <u>Concrete block</u>			
Roof/Cornice_Hip, gable entry			
Window All covered with plywood			
Dating Method(s): Estimate			
Feature Preservation Recommendation(s) (Check all that apply):			
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing element if other properties constitute a district			
Thematic nomination potential			
Component of a historic site or landscape			

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context _____with neighboring structures; d) relocation has damaged eligibility

____Historical associations require further investigation

Recorded By	Kathy	Wilner	Date Recorded	2/3/2017	
	(First Name & Last Name)			(mm/dd/year)	ĺ

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Lincoln Valley Twsp School

SITS# 32 DV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a large prairie school on a poured concrete basement. I suspect this is more than a one room school. The hip roof of the main body, the gable roof of the entry as well as the pyramidal roof of the bell tower all have wood shakes with metal capping. There are rain gutters at the bottom of the walls with downspouts. The is a new, metal chimney pipe on the south slope of the school roof. There is a bell tower at the peak of the entry. The base appears to be an extension of the roof, wood shakes go up the sides to the base that holds the four corner posts. The posts continue up to support the roof and at each of the openings there is a decorative curved piece of wood near the top to finish each opening. There is no bell.

There is a wide trim board under the soffits on all side of the school. Remaining siding is 6 inch wood lap with metal corner capping finished with waterboard and a skirting board. There is a wood step leading up to a wooden stoop with pipe railings on each side. The building has many boarded up windows, 6 on the west side, 5 on the north side and 6 on the south side with 2 either side of the entry and two on the south wall of the entry either side of the door. Above the door is a round window opening that is boarded shut. There door is two pieces of plywood to cover the large opening and it is padlocked shut. There is a space above that door that would have been a transom, also boarded over. The lower level of the building has several windows as well, 6 double hung windows on the west side, 6 on the east side and two on each side of the entry.

There is an outhouse sitting to the northeast of the school.

Recorded By Kathy Wilner Date Recorded 2/3/2017 (First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lincoln Valley Twsp School

SITS# 32_DV_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Urness Family Trust

PO Box 1446 Williston ND 58802

3. Access (to rural areas):

Access is from Highway 85 at the 99th ST NW, go west 1 1/2 miles to see the school on the north side of the road.

4. Site Area (ft²):_____

5. Description of SETTING:

The school is in a field with an old farm site to the east and a large slough east and southeast with farm fields all directions.

Recorded By Kathy Wilner Date Recorded 2/3/2017 (First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Lincoln Valley Twsp School

SITS# 32_DV

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner

Date Recorded

2/3/2017 (mm/dd/year)



West Side

DV

Lincoln Valley Township School	8/21/2016	Kathy Wilner
--------------------------------	-----------	--------------



East Side



South Side

Lincoln Valley Township School8/21/2016Kathy WilnerDV

Land posted so did not photograph the north side.

Google Maps

Google Maps

8/21/2016

Lincoln Valley Township School

Kathy Wilner

DV



Feature

Imagery ©2016 Google, Map data ©2016 Google 500 ft