$7 = SW_{4}$ 8 = NW/₄

NDCRS ARCHITECTURAL SITE FORM PAGE 1

ED 145 **SITS#32**

SITE	IDEN	VTIFIC	ΑΤΙΟΙ	N

Fairville Township School #2 Site Name Fairville Township School #2 Field Code Map Quad New Rockford Map Quad **21 32 000 7** LTL TWP 149N R 66W SEC 00 7 0 7 LTL **TWP** R SEC QQQ QQ Q LTL **TWP** R SEC QQQ QQ Q LTL TWP R SEC QQQ QQ Q **UTM** N ZONE Subsection: **UTM** E NAD 1927 NAD 1983 1 = N1/2 $2 = E\frac{1}{2}$ City: **New Rockford ND** $3 = 5\frac{1}{2}$ 4 = W1/2 Street Number: 5 = NE1/4 18th Street Central North Dakota Steam Threshers 6 = SE1/4 Street Name:

SITE DATA

Total # Architectural Features:

Fieldwork Date: 5-3-2010

Urban Legal Description:

Reconnaissance Survey $\sqrt{}$

Intensive Survey

Project Title & Supervisor:

Country Schoolhouse Project

Report Title & Author(s):

Additional Information:

SHSND USE 2 18 Area of Significance **Ecozone** CR Type **ECF** Area of Significance Ecozone Verified Site Non-Site

1

Recorded By Kathy Wilner **Date Recorded** 9/19/2010 (First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Fairville Township School #2

SITS# 32 ED

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date 1923 Feature Type

Condition

7

Feature Date

Context

Plan Shape

Structural System

Primary Exterior

26

Style Other Style Hipped Roof Box

Original Owner's Ethnicity

0

Secondary Exterior

Architect/Builder unknown

Other Information:

Foundation

Concrete

Stories 1

Roof/Cornice Hip Roof

Window Two fixed pane windows, two small double hung windows, 6 double hung

Dating Method(s): School history

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded

9/19/2010 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code

Fairville Township School #2

SITS# 32

ED

1. Feature Description, Integrity, Eligibility:

This school measures 32 feet by 24 feet and is larger than most of the one room schools I have found. It was built in 1924 to replace an earlier school that was moved from the original school site, Twsp 148N R68W Section 8. It was in the southwest corner of the southeast quarter.

This school was moved its present location in 1993 where it was set on concrete foundation along the east and west sides with a large wood post running the length of the building at the middle. The school has wood lapsiding on the walls and asphalt shingles on the roof. The underside of the overhang I see 4 inch, grooved pieces of wood, set side by side. There is a trim board running along the underside of the roofing. The windows are usually covered but an event at the threshing grounds was reason to uncover them. There are two fixed panes of glass on the east and west sides of the entry, they are located behind doors either side that used to lead to the basement. Two more smaller windows are found either side of the entry. There is a small roof overhang above the wood steps. On the school roof at the front of the school is a small addition that perhaps was a bell tower.

The entry portion of the school has a door to the left and another door to the right (east and west sides of the school) that gave access to the basement. That is enclosed space and used for storage today as there is no basement here. They had indoor toilets without running water. Directly inside the door is a wall with a door at either side that allowed entry into the school. Coat hooks in the entry were visible. The doors into the main body of the school are tall, dark wood with a transom window above each door. The ceilings are very high, covered today with sheet rock. Four light fixtures hang from the ceiling. The walls are lath and plaster. There were chalkboards on three walls with the fourth wall all windows. There are 6 very tall windows on the west wall and they have 6panes of glass in the upper and lower window. A second window, exactly the same, is a storm window. All windows are completely intact. The floor is wood. At the east end of the school there are storage closets in the space that was created by the stairway in the old location. They were used for voting booths as well.

The school closed in 1962. The building is in very good shape and appears well cared for.

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded

9/19/2010 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Fairville Township School #2

SITS#32 ED

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Central North Dakota Steam Threshers President: Jerry Seibold 1109 5th Ave. N New Rockford, ND 58356

Contact for the school: Nancy Ludwig 7669 13th St NE New Rockford, ND 58356

3. Access (to rural areas): Highway 281 north of Carrington, 13 miles. Turn left (west) onto Hwy 15 and drive less that a mile to 66th Ave NE or Eddy County Rd. 14. Turn right (north) and drive 1.9 miles. Turn left (west) at 18th St. NE and drive on gravel .4 miles and you will see the Central North Dakota Steam Thresher grounds. The schoolhouse is with 7 other buildings at the west end of the grounds.

- 4. Site Area (ft²): This school is sitting with a number of other buildings and I have no idea about the area of the site.
- 5. Site Description: The school sits in a grassy area with other buildings near it. To the south there are evergreen trees with a gravel road just beyond. To the north and east there are building that belong to the Central North Dakota Steam Thresher's group.

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded

9/19/2010 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Fairville Township School #2

SITS# 32 ED

6. Summary of ALL Site Features & Evaluation of Significance:

The original location of the school was in Fairville Township in Wells County. Location was Twp148N R68 Sec. 8, 13 miles west of Fessenden ND.

This school is the second Fairlville #2 schoolhouse. The old school was moved from the sight and a new school was built in 1923. The 1923 school is the building that was moved to the threshing grounds. It has been restored and furnished and is open for viewing during the Threshers Reunion held in the fall.


7. References/Comments:

Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded


9/19/2010 (mm/dd/year)



Source=295743 Running Time 0.00 ms

© 2013 Microsoft Corporation. Terms of Use Privacy Statement | Sponsored By WUSGS Research Oing Server=TK2TERRAWEB22

1 of 1






Fairville Township School #2

North Side Entry may 2018 Kathy Wilner



Fairville Township School#2 South Fide may 2010 Kathy Wilher



Fairville Township School # 2 West Side may 2010 Kathy Wilner