NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32

ED 157

SITE IDENTIFICATION Rocky Mountain School #1 Field Code Rocky Mountain School #1 Rocky Mountain School #1 Site Name Site Name Tokio SW Map Quad Map Quad LTL TWP 150 N R 65 W 9 SEC 000 8 QQ 8 Q 5 ETE. TWP R SEC QQQ 00 Q TWP R Q LTL SEC QQQ QQ R 0 LTL TWP SEC 000 00 UTM ZONE Ν Subsection: UTM Ε NAD 1927 NAD 1983 $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$ City: Shevenne ND 58374 $3 = S\frac{1}{2}$ 4 = W1/2 Street Number: $5 = NE^{1}$ $6 = SE^{1}_{4}$ 29th St. NE between 74th Ave NE and 75th Ave NE Street Name: 7 = SW¼ 8 = NW¼ **Urban Legal Description: SITE DATA** Total # Architectural Features: 1 Fieldwork Date: 10/22/2010 **Reconnaissance Survey** √ Intensive Survey Project Title & Supervisor: **Country Schoolhouse Project** Report Title & Author(s): Additional Information: SHSND USE 18 2 Area of Significance Ecozone CR Type ECF Area of Significance Verified Site Ecozone TF Non-Site **Recorded By** Kathy Wilner Date Recorded 4/13/2011 (First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Rocky Mou	Intain School #1	SITS# 32 ED
Complete one Page 2 for each architectural feature at the site.		
Architectural Feature # 1		
Construction Date About 1890	Feature Type 9	Condition 6
Feature Date 2	Context 7	Plan Shape 5
Structural System 25	Primary Exterior 26	Style other style
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder unknown
Other Information:		
Foundation poured concrete basement		Stories 1
Roof/Comice gable		
Window double hung, glass mostly intact		
Dating Method(s): school records		

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district-feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded

4/13/2011 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Rocky Mountain School #1

SITS# 32 ED

1. Feature Description, Integrity, Eligibility:

This main body of this wood framed schoolhouse measures 18 feet 4 inches east to west and 34 feet 4 inches north to south. The school sits on a poured concrete basement. We did not get a look into the basement, I think the second entry door on the east side of the school might have led to the basement but that door was locked. On the west side there was a small trap door that might have been a coal shoot. The school has lap siding with 4inch trim boards at all the corners. The paint is about half gone.

The entry measures 8 feet north to south and 10 feet 5 inches east to west. It sits on a rock foundation. There was a door on the north side of the entry and that was removed and boarded up when a door was cut into the east side of the entry. The door is a modern wood door with glass in the top half of the door. The step into the entry is a wood platform.

There are outside light fixtures at either end of the school building. Another light fixture is attached to the wall beside the door to the entry.

The roof is shingle with wood shakes, some of which are missing. The brick chimney is located at the north end of the school.

Inside the entry coat hooks still hang on the wall. There is also an electric box and a hanging rod on the west side of the entry. The floor of the school is narrow, wood flooring. The walls have wood paneling over lath and plaster with white painted wainscoting on the lower third. You can see the lath and plaster around the chimney. A fuel oil stove is on the north wall and there is a stovepipe sticking out of the chimney. There ceiling tiles over lath and plaster. Four electric lights hang in the school. The windows are trimmed with white painted, 4inch boards.

Bush Township School district (know as Rocky Mountain) was organized about 1989/1990 and the last school reports were received for the school year 1959-60.

Recorded By Kathy Wilner (First Name & Last Name) Date Recorded

4/13/2011 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4---SITE DESCRIPTION

Field Code Rocky Mountain School #1 SITS# 32 ED

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Beverly Soderholm 7456 29St NE Sheyenne ND 58374

3. Access (to rural areas):

From Sheyenne, take 29th St NE east 6 miles. The school will be on your right.

4. Site Area (ft²):

5. Site Description:

The area is rolling country with farmland and pasture. It is part of the Sheyenne River Valley. There is a farmstead to the east as well as another across the road. They make and store hay bales in the school yard.

Recorded By Kathy Wilner (First Name & Last Name) Date Recorded

4/13/2011 (mm/dd/year)

1

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Rocky Mountain School #1 SITS# 32 ED

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Recorder contact information: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner (First Name & Last Name) Date Recorded

4/13/2011 (mm/dd/year)




Rocky Mountain School #1 10/22/2010 North Side Kathy Wilner ED








Rocky Mountain School #1 10/22/2010 West Side Kathy Wilner ED





10

Eddy County Envir Kathy Witner 4-14-2011