

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Grandfield Twsp School #3

SITS# 32^{ED} 418

Map Quad Oberon SW

Site Name _____

Map Quad _____

Site Name Grandfield Twsp School #3

LTL T. 150 N., R. 67 W., Sec. 9 QQQ 5 of the QQ 5 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5297681 Zone 14N

NAD 1983 UTM 482528

City: Sheyenne

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: _____

Street Name: 29th St NE & 63rd Ave NE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 8/22/2022

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component 2 Study Unit 18 Verified Site _____ CR Type 2

Component _____

Component _____

Recorded By: Kathy Wilner Date Recorded: 8/23/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Grandfield Twsp School #3

SITS# 32 ED

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Poor

Plan Shape L-Shaped

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1

Roof/Cornice Gable, shed on the addition

Window Pairs of double hung windows, some glass

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 8/23/2022

NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data**Field Code** Grandfield Twsp School #3**SITS# 32** ED**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a poured concrete foundation. The gable roof of the school and entry and the shed roof of the west addition are covered with failing wood shakes. The gable roof has metal capping with finials. There is a red brick chimney located at the west slope near north end of the school roof. The eaves are open.

The siding begins under the eaves with a rake board at the peaked ends of the school as well as along the walls of the west addition. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. An entry is located at the north end of the school. The walls and ceiling of the entry are finished with beadboard. A concrete platform and step lead to the door opening on the east side of the entry. All the doors are gone. A double hung window opening faces north and has no glass. There is a similar window opening located on the west wall of the addition. The east side has three pairs of double hung, two over two, windows with some glass present. The windows are covered from the inside. The south wall has a large opening, it looks like it was cut to allow entry for equipment. There is no door. The interior walls were finished with lathe and plaster and much of the plaster is gone. The ceiling was finished with wallboard and most of that has fallen in. A blackboard is located on the west half of the south wall. The floor is tongue and groove hardwood and is broken in many places. A light fixture near the entry and light fixtures inside the school are indicative of electricity present at some point.

2. Owner's Contact Information:

Gordon & Colleen Benson
2754 Hwy 281
Sheyenne ND 58374

Recorded By: Kathy Wilner **Date Recorded:** 8/23/2022

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Grandfield Twsp School #3**SITS# 32** ED3. Site Area (ft²):

4. Description of Access and Site Setting:

A farm is located directly north of this school with trees to the south. Farm fields and pasture land are all directions. Access to the school is from the north side of Sheyenne at 29th St NE. Turn left and go west 5 miles to see the school on the south side of the road. It is the intersection with 63rd Ave NE.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 8/23/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



Imagery ©2022 CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2022

200 ft 

Feature



North Side

Grandfield Township School #3

8/22/2022

Kathy Wilner

ED

East Side





West Side

Grandfield Township School #3

8/22/2022

Kathy Wilner

ED

South Side

