

NDCRS SITE FORM  
ARCHITECTURAL SITES

SITS # 32 EM 00246  
State County Site Number

Field Code  
Field Code

Site Name  
Site Name

Map Quad  
Map Quad

ZEELAND NW

LTL 0

Twp 129

Range 074

Section 24

QQQ 5

QQ 6

Q 6

- |           |
|-----------|
| 1. N 1/2  |
| 2. E 1/2  |
| 3. S 1/2  |
| 4. W 1/2  |
| 5. NE 1/4 |
| 6. SE 1/4 |
| 7. SW 1/4 |
| 8. NW 1/4 |
| 9. C      |

City:

Street # and Name

Street # and Name

# of Features 2

262 Soils      19 Ecozone      2 Area Signif  
 0 Soils      Ecozone      Area Signif      P JESSEN Coder  
 2 CR Type   1 Verified Site   0 Non-Site      2 E C F      2 T F      6/5/1980 Date Coded  
 0 State Registry      0 National Register      Update

1 Feature #	40 Feature Type	7 Condition
1906 Construction Date	13 Context	Integrity
Feature Date		5 Plan Shape*
25 Structural System **	26 Primary Exterior *	Secondary Exterior
12 Ethnic	14 Style *	
11/01/79 Fieldwork Date	Fieldwork Date	0 Architect/Builder
	RESIDENCE	Other Information
2 Feature #	9 Feature Type	5 Condition
Construction Date	13 Context	Integrity
Feature Date		5 Plan Shape*
25 Structural System **	26 Primary Exterior *	Secondary Exterior
0 Ethnic	Style *	
11/01/79 Fieldwork Date	Fieldwork Date	0 Architect/Builder
	SCHOOL USED FOR STORAGE	Other Information

F.N. 26

## NORTH DAKOTA CULTURAL RESOURCES SURVEY

## Base Data Form

1. County Emmons 2. Site Number 32EM246
3. Site Name (s) \_\_\_\_\_
4. Type of Resource: A. Archaeological  Historical  Architectural  Paleontological   
B. District  Site  Building  Structure  Object
5. Map Reference: Zeeland NW
6. Location: NE $\frac{1}{4}$ , SE $\frac{1}{4}$ , SE $\frac{1}{4}$  Sec. 24 T 129 N / R 74 W  
Plat: \_\_\_\_\_ Block \_\_\_\_\_ Lot \_\_\_\_\_  
UTMG: A. \_\_\_\_\_ B. \_\_\_\_\_  
C. \_\_\_\_\_ D. \_\_\_\_\_
7. Access: 1 $\frac{1}{2}$  mile east of Haque on FAS 11, four miles south, four miles east, and  $\frac{1}{2}$  mile north; the house is on the east side of the road.
8. A. General description of site: German-Russian clapboard house with 5 sided vorhausl. One and a half story. Typical of this kind of house found in eastern and south-eastern Emmons County and western McIntosh. Maybe common farther east in area not surveyed.
- B. Condition of site: abandoned, fair
9. Owner's name/address: \_\_\_\_\_
10. Occupant's name/address: \_\_\_\_\_
11. Historic Register value: Nat.  State  Untd.  None  On Reg.  In District  District
12. Open to public: Yes  No  13. Preservation Underway: Yes  No
14. Endangered by: Natural deterioration
15. Survey Project: Title Emmons County Survey 1979 Director \_\_\_\_\_  
Other surveys in which included \_\_\_\_\_
16. Recommendations: do historic research
17. Environment: Elevation 1960 Nearest Water: Type int. str.  
Name \_\_\_\_\_ Distance 880 M Direction SW  
Soil conditions: \_\_\_\_\_  
Soil Texture: \_\_\_\_\_



*ZEELAND ND 7.5x30 7000*

EMMONS CO  
MC INTOSH CO

780 000 FEET  
(S. DAK.)

ZEELAND 2.2 MI.

5088

5089

5090

5091

5092

5093

17. Environment, Cont.

Ground Cover: \_\_\_\_\_

Terrain: \_\_\_\_\_

\_\_\_\_\_

18. Local contact person or organization: \_\_\_\_\_

19. Photos: No B/W Color  Prints Slides  Comments/ID code HP3-79-46; 25+26


Negatives stored at: SHSND, Office of A+HP

In space below attach and identify a picture or contact print of the site.

20. Sketch Map of Site:

Scale: \_\_\_\_\_

N



S

Recorded by: LeAnne Baird and Jackie Sluss Date Summer 1979

Revised by: Jackie Sluss Date 11/79

Continuation form: Historic Sites

Site Number 32EM246(FN26)

27. Thematic category vernacular arch./G.R. Sehle 28. Date or period ca. 1906
29. Structures: Number standing 2 Number collapsed 0  
 Number of foundations only not recorded Number of earthworks \_\_\_\_\_  
 Number of basement depressions \_\_\_\_\_ No structural remains observed \_\_\_\_\_
30. Architectural/Structural Detail:
- A. Style or design typical 5-sided vorheisel on 1½ story frame  
 B. Architect/engineer unknown  
 C. Contractor/builder \_\_\_\_\_  
 D. Original use home  
 E. Present use abandoned  
 F. Number of stories 1½ G. Basement: Yes No Partial \_\_\_\_\_  
 H. Foundation Material unknown  
 I. Wall Construction wood frame  
 J. Wall Treatment clapboard  
 K. Roof type and material gable, wood frame and shingles  
 L. Number of bays: Front Side M. Plan shape rectangular
31. Frontage \_\_\_\_\_ 32. Distance from road \_\_\_\_\_
33. Number of outbuildings 1 34. Description of outbuildings  
looks like old schoolhouse being reused as storage
35. Changes \_\_\_\_\_
36. Information sources/References \_\_\_\_\_
37. Reason for significance: German-Russian frame house type.

Recorded by LeAnne Baird and Jackie SlussDate Summer 1979Revised by Jackie SlussDate 11/79



**NDCRS ATTACHMENT SECTION**

**Field Code** \_\_\_\_\_ **SITS# 32** **EM** **246**



From southeast, scanned from AHP Photo Collection, taken 1979



From northeast, scanned from AHP Photo Collection, taken 1979

**Recorded By:** Lorna Meidinger **Date Recorded:** 8/5/2021