State Historical Society of North Dakota

**NDCRS 2020** 

# NDCRS ARCHITECTURAL FORM

		PAGE 1		UPDATE
Field Code Lador School				
Map Quad Hazelton NW		Site Nar	ne Lador School	
Map Quad		Site Nar	ne	
LTL TN., R7				
LTLTN., RV				1 = N½
LTLTN., RV				
LTLTN., RV				$\begin{array}{c c} 3 = 5\frac{1}{2} \\ 4 = W\frac{1}{2} \end{array}$
NAD <u>1983</u> UTM <u>5</u>	14/683	Zone <u>14N</u>		5 = NE¼
NAD <u>1983</u> UTM <u>3</u>			×	6 = SE¼
City:				7 = SW¼ 8 = NW¼
Street Number:				
Street Name:65th St SE				
Urban Legal Description:				
Total Number of Architectural	Features:	1		
Fieldwork Date:10/7/202	1			
Tieldwork Date.				
Reconnaissance Survey		Intensive Surve	У	
Project & Principal Investigator				
Country School House Project Kathy Wilner				
366 43rd Ave SE				
Bowdon ND 58418				
Contracting Firm or Agency Co	mpleting the Fo	rm?		
contracting r inn or rigonoy co	inploting the Fo			
Additional Information:				
SHSND USE				
	ly Unit	Verified Site	CR Type	
Component			0,po	
Component				
	Kothy Miles	2		1/11/0001
Recorded By:	Kathy Wilner		Date Recorded: 1	1/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

# NDCRS ARCHITECTURAL FORM

UPDATE

Field Code Lador School	SITS# 3	2 EM	255	
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #				
Construction Date				
Feature Date				
Structural System <u>Wood Frame</u>				
Original Owner's Ethnicity				
Feature Type _9 - School; Church school				
Context Education				
Primary Exterior <u>Wood, Horizontal Siding</u>				
Secondary Exterior				
Condition Fair				
Plan Shape <u>Rectangular</u>				
Style Other Style				
Architect/Builder				
Roof/Cornice				
Window Double hung, 4 over 4				
Dating Method(s) Estimate				
Miscellaneous Information				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if o	ther prope	erties c	onstitute a distri	ct
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred site, orientation, landscape, and spatial relationships; c) comp relocation has damaged eligibility				
Historical associations require further investigation				

Recorded By: Kathy Wilner Date Recorded: 11/11/2
--

### NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

Field Code Lador School

SITS# 32 EM 255

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a cement block foundation. It was moved into a farm yard. The hip roof is covered with wood shakes with metal capping. There is a yellow brick chimney with a flue located on the northwest slope of the roof of the school.

The siding is 6 inch wood lap with 6 inch wood corner trim, all painted red. On the southeast side an ovehead garage door was installed. On the southwest side there is one small 4 pane window near the northwest end of the school. Also on the southwest side are 6 larger, double hung 4 over 4 windows with the glass largely intact. The farm yard was protected by a gate and I did not go in.

2. Owner's Contact Information: Lador Property LLP 4200 Lookout Trail Bismarck ND 58504

#### Recorded By:

Kathy Wilner

Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

#### NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

# Field Code Lador School

SITS# 32 EM 255

3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

Access to this school is south of Hazelton to 65th St SE. Go west on 65th St SE 7 miles to see this school in the farm yard. The school has buildings and trees all around.

5. Summary of ALL Site Features and Evaluation of Significance:

h,


6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

**Recorded By:** 

Kathy Wilner

Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



# Southeast Side

Lador School

Kathy Wilner 10/7/2021 EM

Northeast Side



Southwest Side

Lador School

10/7/2021

Kathy Wilner

EM



Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 500 ft Feature

#### NDCRS SITE FORM ARCHITECTURAL SITES

				SITS #	32 State	EM County	00255 Site Number
Field Code Field Code		Site Name Site Name					
	Map Quad Map Quad	HAZELTON NW					
LTL 0	Twp 135	Range 077	Section 30	QQQ 7	QQ	6 Q	7 1. N 1/2 2. E 1/2 3. S 1/2 4. W 1/2 5. NE 1/4 6. SE 1/4 7. SW 1/4 8. NW 1/4 9. C
City:							
Street # ar	nd Name		Street # and Name				
# of Featur	s 19 Eco		-				
0 Soils		zone Area S	Signif			M VOLK	Coder
2 CR <sup>-</sup> 4 Stat		Site 0 Non-Site ) National Register	2 ECF	2 T F		6/16/1980	Date Coded Update
1 F	eature #	15	Feature Type		6	Condition	
C	Construction Date	13	Context			Integrity	
F	eature Date				5	Plan Shap	be*
25 S	Structural System *	* 26	Primary Exterior *			Secondar	y Exterior
0 6	Ethnic		Style *				
06/21/79 F	ieldwork Date		Fieldwork Date		0	Architect/I	Builder
			UNKNOWN U	JSE	Othe	r Informatio	n

1 1 44

	F.N. 34 NORTH DAKOTA CULTURAL RESOURCES SURVEY
	F.N. 34 NORTH DAKOTA CULTURAL RESOURCES SURVEY Base Data Form
	County Emmons 2. Site Number32EM255
	Site Name (s)
	Type of Resource: A. Archaeological Historical XArchitectural XPaleontological_
	B. District_Site_Building_XStructure_Object
	Map Reference: <u>Hazelton NW 7.5.TOPO</u>
	Location:
	Plat:BlockLot
	UTMG: AB
	CD
	Access: <u>Just north off east-west section line road</u>
	A. General description of site: <u>Unusual outbuilding (original use unknown)</u>
ı	
	1 story with hipped roof with 2 gablets, and square turret with mansard roof;
	1 story with hipped roof with 2 gablets, and square turret with mansard roof;
	1 story with hipped roof with 2 gablets, and square turret with mansard roof;
	1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site.
	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site:</pre>
	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site: good, occupied farmstead Owner's name/address: unknown</pre>
	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site: good, occupied farmstead Owner's name/address: unknown Occupant's name/address:</pre>
D.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site: good, occupied farmstead Owner's name/address: unknown Occupant's name/address: Historic Register value: Nat. State Undt. NoneX On Reg. In District District</pre>
D. 1.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site:good, occupied farmstead Owner's name/address: Occupant's name/address: Historic Register value: NatStateUndtNoneX_On RegIn DistrictDistrict Open to public: YesNo_X_ 13. Preservation Underway: YesNo_X_altered</pre>
D. 1. 2.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site: good, occupied farmstead Owner's name/address: unknown Occupant's name/address: Historic Register value: NatState_UndtNoneX_On RegIn District_District Open to public: YesNo_X_13. Preservation Underway: YesNo_X_altered Endangered by:</pre>
D. 1.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site:good, occupied farmstead Owner's name/address: Occupant's name/address: Historic Register value: NatStateUndtNoneX_On RegIn DistrictDistrict Open to public: YesNo X13. Preservation Underway: YesNo Xaltered Endangered by: Survey Project: TitleEmmons County Survey 1979Director</pre>
D. 1. 2. 4. 5.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site:good, occupied farmstead Owner's name/address: Occupant's name/address: Historic Register value: NatStateUndtNoneX_On RegIn DistrictDistrict Open to public: YesNo_X13. Preservation Underway: YesNo_X_altered Endangered by: Survey Project: TitleEmmons County Survey 1979Director Other surveys in which included</pre>
D. 1. 2.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site. B. Condition of site:good, occupied farmstead Owner's name/address: Occupant's name/address: Historic Register value: NatStateUndtNoneX_On RegIn DistrictDistrict Open to public: YesNo_X13. Preservation Underway: YesNo_X_altered Endangered by: Survey Project: TitleEmmons County Survey 1979Director Other surveys in which included</pre>
D. 1. 2. 4. 5.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site.</pre> B. Condition of site:
D. 1. 2. 4. 5.	1 story with hipped roof with 2 gablets, and square turret with mansard roof;         old school also on site.         B. Condition of site:       good, occupied farmstead         Owner's name/address:       unknown         Occupant's name/address:       unknown         Occupant's name/address:       Historic Register value: NatState_UndtNoneX_On RegIn District_District         Open to public: YesNo_X_13. Preservation Underway: YesNo_X_altered         Endangered by:         Survey Project: TitleEmmons County Survey 1979       Director
D. 1. 2. 4. 5.	<pre>1 story with hipped roof with 2 gablets, and square turret with mansard roof; old school also on site.</pre> B. Condition of site:


.....

·	.1		NORTH DA	кота	CULTURAL	RESOURCES	SURVEY	Page	
• •	17.	Environment, Co	nt.					Site Number 32EM255(FN	134) _
		Ground Cover:						- · · · · · · · · · · · · · · · · · · ·	_
		Terrain:							_
		<u> </u>	<u></u> .						-
	18.	Local contact p	erson or ord	aniza	tion:				

19. Photos: No\_B/WX Color X Prints X Slides X Comments/ID code\_HP3-79-92, 22-25

HP3-79-57, 29-33

Negatives stored at: <u>State Historical Society of North Dakota A&HP office</u> In space below attach and identify a picture or contact print of the site.



Recorded by:	LeAnne Baird	and Jackie	Sluss	Date Summer	1979
Revised by:				_Date	

	NORTH DAKOTA CULTURAL RESOURCES SURVEY	Page <u>3</u>
	Continuation form: Historic Sites Site Number	
27.	Thematic category Verna cular architechure 28. Date or period ?	
29.	Structures: Number standing Several Number collapsed	
	Number of foundations only not Kearded Number of earthworks	
	Number of basement depressions <u>"</u> No structural remains observ	ed
30.	Architectural/Structural Detail:	
	A. Style or design vernacular	
	B. Architect/engineer unknown	
	C. Contractor/builder	
	D. Original use <u>unknown</u>	<u> </u>
	E. Present use granery ?	
	F. Number of stories G. Basement: YesNoPartial	
	H. Foundation Material concrete	
	I. Wall Construction wood frame	
	J. Wall Treatment <u>clapboard</u>	
	K. Roof type and material <u>mansard turret and gabled hip</u>	
	L. Number of bays: Front_Side       M. Plan shape <u>almost square</u> Frontage       32. Distance from road	
31.	Frontage 32. Distance from road	
33.	Number of outbuildings 34. Description of outbuildings	
0.5		
35.	Changes <u>unknown</u>	
36.		
50.	Information sources/References	
37.	Reason for significance: <u>unusual no probable significance</u>	
57.	Reason for significance. <u>unusual no probable significance</u>	
	Recorded by LeAnne Baird and Jackie Sluss Date Summer 19	
	Revised by Date	
	· <u> </u>	

