Recorded By:

| NDCR | S ARCHITECTURAL FORM PAGE 1 | |
|---|--|---|
| Field Code Emmonsburg Township School | SITS# 32 ^{EM} | UPDATE 877 |
| Map Quad Hazelton SW Map Quad | | |
| Map Quad | QQQ 7 of the QQ 8 of the Q 6 QQQ of the QQ of the Q QQQ of the Q of the Q | - Subsection - 1 = N½ 2 = E½ |
| Urban Legal Description: | | - |
| Total Number of Architectural Features: Fieldwork Date:10/7/2021 | | |
| Reconnaissance Survey | Intensive Survey | |
| Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418 | | |
| Contracting Firm or Agency Completing the F | ^c orm: | |
| Additional Information: | | |
| SHSND USE Component Study Unit Component Component | Verified Site CR Type | |

Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM

| PAGE | 2 – | <i>Feature</i> | Data |
|------|-----|----------------|------|
| | | | |

IPDATE

| Field Code Emmonsb | urg Township School | S | TS# 32 EM 8 | 877 |
|-------------------------------|--|----------------------|------------------|---------------------|
| | or each architectural featur | e at the site. | | |
| Architectural Feature #_ | 1 | | | |
| Construction Date | | | | |
| Feature Date <u>1915-1</u> | 930 | | | |
| Structural System | ood Frame | | | |
| Original Owner's Ethnici | ty | | | |
| Feature Type <u>9 - Schoo</u> | l; Church school | | | |
| Context <u>Education</u> | | | <u>×</u> | |
| Primary Exterior | od, Horizontal Siding | | | |
| | | | | |
| Condition Very Poor | | | | |
| Plan ShapeRectance | | | | |
| | | | | |
| | | | | |
| | crete | | | |
| | | | | |
| | framing | | | |
| Dating Method(s) Prev | ious documentation | | | |
| | on | | | |
| | ecommendation(s) (Check | | ÷- | |
| Individual nomin | | | | |
| Contributes to a | potential district | | | |
| No nomination p | otential | | | |
| Will not contribut | e to a district | | | |
| Potential district- | -feature would be a contribu | ting element if othe | er properties co | nstitute a district |
| Thematic nomination | ation potential | | | |
| Component of a | historic site or landscape | | | |
| site, orientation, | all applicable choices)—a) rele landscape, and spatial relation amaged eligibility | | | |
| Historical associ | ations require further investig | ation | | |
| Recorded By: | Kathy Wilner | Date R | ecorded: | 11/11/2021 |

Date Recorded: ____

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

Field Code Emmonsburg Township School

UPDATE

SITS# 32 EM 877

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The roof has only slat board left and there are holes, No chimney. Soffits are open. The building measures 24 feet north to south and 16 feet east to west.

The siding begins with a rake board under the eaves on all sides. The remainder of the siding is 6 inch wood lap with 6 inch corner trim. There is a small window opening on the west side for a fuel door, three double hung window openings on the north side and 5 windows on the east side. There is no glass a bit of farming. One of the east windows would be in the coatroom. The door is gone. The interior walls have some beadboard and the ceiling is entirely gone. The whole building is listing to the east.

2. Owner's Contact Information: John Ohlhausen 7715 2nd AVe SW Linton ND 58552

Recorded By:

Kathy Wilner

Date Recorded: 11/11/2021

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Emmonsburg Township School

SITS# 32 EM 877

UPDATE

3. Site Area (ft²):

4. Description of Access and Site Setting:

Access to this school if from the intersection of Hwy 1804 and Hwy 13 2 miles east to 2nd Ave SW. Turn right (south) and go about 3/4 of a mile and follow the road as it curves to the west. Go west about 1/2 mile to see the school on the north side of the road. On google maps it is labled 6th Ave SW. The land around the school is all farm fields.

5. Summary of ALL Site Features and Evaluation of Significance:


6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By:

Kathy Wilner

Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.




South Side

Emmonsburg Township School


10/7/2021 Kathy Wilner EM

West Side






Emmonsburg Township School



North Side



Feature

% mile south of Highway 13 at Linton on 6th Ave SW

| | NDCRS SITE FORM ARCHITECTURAL SITES | Page 1 |
|--|--|---|
| Field Code <u>C.R.M.2.</u> Field Code <u>1.3.2.7</u> | SITS # <u>6.2/.6.</u> Site Name <u></u> <u>883.</u> Site Name <u></u> | 3.2. E.M B.7.7. State County Site Number |
| Map | Quad <u>Hazelton S.M</u> | |
| LTL ـــ Twp ــــ LTL ــ Twp ـــ LTL ــ Twp ـــ LTL ــ Twp ـــ | Image: R Image: R Image: R Image: R Image: R Image: QQQ Image: R Image: R Image: R Image: R Image: R Image: R Image: QQQ Image: R Image: R Image: R Image: R Image: R Image: QQQ Image: R Image: QQQ Image: R Image: R Image: R Image: R Image: R Image: QQQ Image: R Image: QQQ Image: R Image: R Image: | y QQ L Q L L L L L QQ L Q L L L L L L L |
| | SITE DATA | |
| City | | |
| Street # | Street # Street Name | |
| # of Features | <u> </u> | |
| | FEATURE DATA | |
| ,/"Feature # Const Date .4Feature Date | ∟_ <u>9</u> Feature Type ∟_ <u>7</u> Context | ら、Condition え Significance ら、Plan Shape |
| PORCH | BUILDING MATERIALS | |
| Original Original Addition/Altered Removed/None Fthni | <u>。 えら</u> Structure System 」 <u>こ</u> ら Primary Exterior Finish Secondary Exterior Finish | 3 Main Entrance |
| Style | :Builder Engineer DFieldwork DateDesigner | Architect |
| t | | Uther Information |
| | | |
| Soil Associa | tion <u>1.9</u> .Ecozone 🛆 Area Signf | MS Number |
| | tion لسلس Ecozone سلم Ecozone Verified Site سر Non-Site | MS Number <u>ح</u> -ECF <u>ح-</u> TF |
| 2 | te Registry La Nation | |
| Coder <u>Schu</u> | | Date Coded88 |

| · · · · · · · · · · · · · · · · · · · | de CRM262-16 | | | | SITS NUMBER |
|---|--|--|---|---|---|
| FEATURE | # NAME IN N/ | AME BLOCK | | | |
| ASEMENT | FOUNDATION MATERIALS | STORIES | CORNICE | ROOF TYPE | DATING METHOD |
| yes no unknown other NDOWS Original Altered | Brick Concrete Block Fieldstone Cut Stone Poured Concrete Refaced Unknown Other | $\frac{1}{2} \frac{1}{1} \frac{1}{1/2} \frac{2}{2} \frac{2}{1/2} \frac{1}{3} \frac{1}{1/2} $ | Metal Brick None Wood Other | Gable Hipped Deck Gambrel Flat Other | Plat Map(s) County Atla Date Block Sanborn Map Topo Map(s) X Other |
| ATURE DESC | RIPTION & STATEMENT OF | INTEGRITY _ | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | ······································ | | | i. | |
| | | | | | |
| | | | | | |
| | | | | | |
| | ······································ | | | | |
| | | | | | |
| | | SIGNIF | CANCE | × | |
| | SIGNIFICANT | | | × | X NOT SIGNIFICANT |
| Rep. of ty | ster Vis tic Values Ass pe, period, Ass | <u>SIGNIF</u> ual Landmark ociated with ociated with ociated with | significan devel. of | locality | Too new |
| High Artis Rep. of ty method of Other | sterVis tic ValuesAss pe, period,Ass constructionAss | ual Landmark ociated with ociated with | significan devel. of | locality | Too new <u>Y</u> Lacking integrit <u>X</u> Not High Style |
| High Artis Rep. of ty method of Other | ster Vis tic Values Ass pe, period, Ass | ual Landmark ociated with ociated with | significan devel. of | locality | Too new <u>Y</u> Lacking integrit <u>X</u> Not High Style |
| High Artis Rep. of ty method of Other | sterVis tic ValuesAss pe, period,Ass constructionAss | ual Landmark ociated with ociated with | significan devel. of | locality | Too new <u>Y</u> Lacking integrit <u>X</u> Not High Style |
| High Artis Rep. of ty method of Other | sterVis tic ValuesAss pe, period,Ass constructionAss | ual Landmark ociated with ociated with | significan devel. of | locality | Too new <u>Y</u> Lacking integrit <u>X</u> Not High Style |
| High Artis Rep. of ty method of Other | sterVis tic ValuesAss pe, period,Ass constructionAss | ual Landmark ociated with ociated with | significan devel. of | locality | Too new <u>Y</u> Lacking integrit <u>X</u> Not High Style |

NDCRS ARCHITECTURAL SITE FORM

•

.

