

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Danbury Township School

SITS# 32EM 923

Map Quad Hazelton

Site Name Danbury Township School

Map Quad _____

Site Name _____

LTL T. 134 N., R. 76 W., Sec. 4 QQQ 7 of the QQ 7 of the Q 7

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5144153 Zone 14N

NAD 1983 UTM 403812

City: _____

Street Number: _____

Street Name: 67th St SE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 11/07/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component _____ Study Unit _____ Verified Site _____ CR Type _____

Component _____

Component _____

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code Danbury Township SchoolSITS# 32 EM 923Complete one Page 2 for *each* architectural feature at the site.Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition PoorPlan Shape RectangularStyle Other Style

Architect/Builder _____

Foundation Poured Concrete Stories 1Roof/Cornice HipWindow Double hung openings, some framingDating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner Date Recorded: 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data**

UPDATE

Field Code Danbury Township SchoolSITS# 32 EM 923Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The roof is covered with failing wood shakes with some metal capping. Remnants of the yellow brick chimney sit on the south slope of the roof. The soffits are closed. The school measures 24 feet east to west and 32 feet north to south.

The siding begins with a rake board under the eaves on all sides of the school. The rest of the siding is 6 inch wood lap with 6 inch wood corner trim. There is an entry on the south side. One concrete step leads into the entry where the floor is also concrete. Some of the chimney bricks are laying on the roof. The exterior door is gone. Inside the entry a 5 panel wood door, with a transom opening, leads into the school. Another door to the left inside the school leads into a fuel room. A fuel door can be seen on the west wall of this room. On the right is the coatroom with one shuttered window. The interior walls and angled ceiling are all mostly covered with beadboard. The north wall windows were all removed and boarded up. On the east wall there is one set of four double hung window openings with a bit of framing and no glass, one is covered. Another set of 4 windows was also on the east wall and have been removed and boarded up. The floor is narrow hardwood. A blackboard is located on the south wall of the school room to the east of the entry door. It is evident where another blackboard was on the north wall but it is now gone. Electricity was present at some point. An oil burning stove remains in the school.

2. Owner's Contact Information:

Appert Land Enterprises LLLP
755 Hwy 34
Hazelton ND 58544

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description

UPDATE

Field Code Danbury Township School

SITS# 32 EM 923

3. Site Area (ft²):

4. Description of Access and Site Setting:

Access to this school is south of Hazelton on Hwy 83 about 2 1/2 miles to 67th St SE. Turn left (east) and go 1 mile to see the school at the intersection of 67th St SE and 8th Ave SE. A farm site is north and another east of the school with farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Danbury Township School

10/7/2021

Kathy Wilner

EM

West Side





East Side

Danbury Township School

10/7/2021

Kathy Wilner

EM

North Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 500 ft

Feature



view to N



view to NW

32 EM923

19 June 09



view to E



view to SE

32EM923

19 June 09

SITS # 3.2 EM 923
State County Site Number

Field Code C.R.M. 26.2.-2.2. Site Name _____
Field Code 1.3.4.7.6.-4.-3. Site Name _____

Map Quad Hazelton
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>134</u>	R	<u>76</u>	Sec	<u>4</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<input checked="" type="checkbox"/>	Q	<input checked="" type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N
2. E
3. S
4. W
5. NE
6. SE
7. SW
8. NW
9. C

SITE DATA

City _____

Street # _____ Street # _____

Street Name _____ Street Name _____

of Features 2

FEATURE DATA

1 Feature #
_____ Const Date
4 Feature Date

9 Feature Type
7 Context

5 Condition
6 Significance
5 Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

25 Structure System
36 Primary Exterior Finish
_____ Secondary Exterior Finish

3 Main Entrance

_____ Ethnic
31 Style

_____ Builder
_____ Engineer
_____ Designer Architect

7.21.88 Fieldwork Date

_____ Other Information

4 Soil Association 19 Ecozone Area Signf _____ MS Number

_____ Soil Association _____ Ecozone Area Signf _____ MS Number

CR Type Verified Site Non-Site E C F T F

State Registry National Register

Coder Schwartz

Date Coded 1/09/89

SITE I.D.
SITE DATA
FEATURE DATA
SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM 262-22

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>Pro. Judge ment</i>
<input type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

<input type="checkbox"/> Work of Master	<input type="checkbox"/> Visual Landmark	<input type="checkbox"/> Too new
<input type="checkbox"/> High Artistic Values	<input type="checkbox"/> Associated with significant event	<input checked="" type="checkbox"/> Lacking integrity
<input type="checkbox"/> Rep. of type, period, method of construction	<input type="checkbox"/> Associated with devel. of locality	<input checked="" type="checkbox"/> Not High Style
<input type="checkbox"/> Other _____	<input type="checkbox"/> Associated with significant person	<input type="checkbox"/> Other _____

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweiger

Date 7/21/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 13476-4-2 Photo

SITS Number _____



00 41 74