

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Mathieu School

SITS# 32EM 924

Map Quad Hazelton

Site Name Mathieu School

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL    T. 134 N., R. 77 W., Sec. 22 QQQ 8 of the QQ 8 of the Q 8

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5141003 Zone 14N

NAD 1983 UTM 395766

City: \_\_\_\_\_

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: \_\_\_\_\_

Street Name: 69th St SE

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project  
Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component \_\_\_\_\_ Study Unit \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code Mathieu School

SITS# 32 EM 924

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior \_\_\_\_\_

Condition Fair

Plan Shape \_\_\_\_\_

Style Other Style

Architect/Builder \_\_\_\_\_

Foundation Poured concrete Stories 1

Roof/Cornice Hip

Window Double hung openings, farming, no glass

Dating Method(s) Estimate

Miscellaneous Information \_\_\_\_\_

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

**NDCRS ARCHITECTURAL FORM****PAGE 3 – Feature Data****UPDATE****Field Code** Mathieu School**SITS# 32** EM 924**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a poured concrete foundation. The hip roof is covered with asphalt shingles. The soffits are open. A tall yellow and red brick chimney is located on the south slope of the roof. The school measures 30 feet north to south and 20 feet east to west.

This siding is 6 inch wood lap with metal corner trim with waterboard at the bottom. Concrete steps to a porch lead to a plywood door with a window opening. The porch is protected by a portico supported by triangle brackets. Step through the door into a vestibule with doors to the left and right that lead into coatrooms. A door opening straight ahead leads into the school proper. More doors lead into the school from each coatroom. The floor is narrow hardwood. The walls and ceiling in the school are finished with wallboard. Wainscot is on walls in the coatrooms and vestibule and part of the school room. Some has been removed as has some of the door molding. There is a picture rail on all the walls. The north wall has two double hung multipane windows with a bit of framing and no glass. The east wall has four similar windows. To either side of the entry door are smaller double hung windows. A broken blackboard runs the length of the west wall and corners to the windows on the north wall. Light fixtures indicate electricity. An oil burning stove sits in the school.

**2. Owner's Contact Information:**

Annette J mathieu Trust  
Vancouver WA 98683

**Recorded By:** Kathy Wilner **Date Recorded:** 11/10/2021

**NDCRS ARCHITECTURAL FORM****PAGE 4 – Site Description**

UPDATE

Field Code Mathieu SchoolSITS# 32 EM 9243. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

Access to this school is from Hazelton south on Hwy 85 about 4 1/2 miles to 69th St SE. Turn right onto 69th St SE and go west 4 miles to see the school on the south side of the road. A farm site is in the distance to the west with another to the east. There is pasture and farm fields all around.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Mathieu School

10/7/2021

Kathy Wilner

EM

West Side





East Side

Mathieu School

10/7/2021

Kathy Wilner

EM

North Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature





view to SW



view to SE

32EM924

19 June 09





interior from N side



view to NW

32EM924 19 June 09

SITS # 3.2 EM 9.24  
State County Site Number

Field Code C.R.M. 2.62-.2.3. Site Name \_\_\_\_\_  
Field Code 1.3.4.7.7-.2.2.-2 Site Name \_\_\_\_\_

Map Quad H.A.Z.E.L.T.O.N  
Map Quad \_\_\_\_\_

LTL	<input type="checkbox"/>	Twp	<u>13.4</u>	R	<u>7.7</u>	Sec	<u>2.2</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N  $\frac{1}{2}$
2. E  $\frac{1}{2}$
3. S  $\frac{1}{2}$
4. W  $\frac{1}{2}$
5. NE  $\frac{1}{4}$
6. SE  $\frac{1}{4}$
7. SW  $\frac{1}{4}$
8. NW  $\frac{1}{4}$
9. C

SITE DATA

City \_\_\_\_\_

Street # \_\_\_\_\_ Street # \_\_\_\_\_

Street Name \_\_\_\_\_ Street Name \_\_\_\_\_

# of Features 2

FEATURE DATA

<u>1</u> Feature #	<u>9</u> Feature Type	<u>5</u> Condition
_____ Const Date	<u>7</u> Context	<del><u>2</u> Significance</del>
<u>4</u> Feature Date		<u>5</u> Plan Shape

PORCH

BUILDING MATERIALS

<input checked="" type="checkbox"/> Original	<u>25</u> Structure System	<del><u>3</u> Main Entrance</del>
<input checked="" type="checkbox"/> Addition/Altered	<u>26</u> Primary Exterior Finish	
<input checked="" type="checkbox"/> Removed/None	_____ Secondary Exterior Finish	

_____ Ethnic	_____ Builder
<u>3.1</u> Style	_____ Engineer
<u>10.7.2.1.18.8</u> Fieldwork Date	_____ Designer Architect

Other Information \_\_\_\_\_

<u>350</u> Soil Association	<u>1.9</u> Ecozone	<u>2</u> Area Signf	_____ MS Number
<u>239</u> Soil Association	_____ Ecozone	_____ Area Signf	_____ MS Number
<u>2</u> CR Type	<input type="checkbox"/> Verified Site	<input type="checkbox"/> Non-Site	<u>3</u> E C F <u>2</u> T F
<input type="checkbox"/> State Registry	<input type="checkbox"/> National Register		

Coder Schweigert Date Coded 1/9/89

SITE I.D.  
SITE DATA  
FEATURE DATA  
SHSND USE

NDCRS ARCHITECTURAL SITE FORM

Page 2

Field Code CRM762-23

SITS NUMBER \_\_\_\_\_

FEATURE # 1 NAME IN NAME BLOCK \_\_\_\_\_

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<u>Pro. Judgment</u>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY \_\_\_\_\_

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- |                                                                       |                                                             |                                                    |
|-----------------------------------------------------------------------|-------------------------------------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Work of Master                               | <input type="checkbox"/> Visual Landmark                    | <input type="checkbox"/> Too new                   |
| <input type="checkbox"/> High Artistic Values                         | <input type="checkbox"/> Associated with significant event  | <input type="checkbox"/> Lacking integrity         |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____                                  | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____               |

JUSTIFICATION OF SIGNIFICANCE \_\_\_\_\_

Recorded by Schweigert

Date 7/21/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 13477-22-2

Photo

SITS Number \_\_\_\_\_

