

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Volk School

SITS# 32EM 937

Map Quad Senger Lake South

Site Name Volk School

Map Quad

Site Name

LTL T. 130 N., R. 75 W., Sec. 23 QQQ 7 of the QQ 7 of the Q 6

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5101024 Zone 14N

NAD 1983 UTM 419985

City:

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number:

Street Name: 94th St SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component Study Unit Verified Site CR Type

Component

Component

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code Volk School

SITS# 32 EM 937

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1

Roof/Cornice Hip

Window Double hung openings, farming

Dating Method(s) Previous documentation

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

Field Code Volk School

SITS# 32 **EM** 937

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The hip roof is mostly covered with wood shakes with metal capping and finials. The chimney is gone. The soffits are closed.

A rake board starts the siding under the eaves on all four sides. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim and waterboard at the bottom. A concrete porch with one step leads into the school. The exterior door is missing. Just inside the school there is a room to the left that was used for fuel and later storage and to the right is the coatroom. A 5 panel wood door leads into the school room. There are several double hung window openings with some framing and little glass. This includes a set of three windows on the north side and a bank of 6 on the east side. One more window on the south side lights the coatroom. Plywood covers most of the windows openings. On the west side there is a fuel door near the south end. The floor is tongue and groove hardwood. The walls are finished with beadboard and it is evident the blackboard was on the west wall. The ceiling had acoustic tiles but most have fallen away. Electrical fixtures indicate the presence of electricity at some point in the past.

2. Owner's Contact Information:

Mark and Barbara Volk
203 2nd St SE
Linton ND 58552

Recorded By: Kathy Wilner **Date Recorded:** 11/10/2021

NDCRS ARCHITECTURAL FORM**PAGE 4 – Site Description**

UPDATE

Field Code Volk SchoolSITS# 32 EM 9373. Site Area (ft²):

4. Description of Access and Site Setting:

Access to the school is from Hwy 83 south of Strasburg about 8 miles to 96th St SE. Turn left (east) to drive 2 miles to turn left (north) again onto 17th Ave SE. Drive north on 17th Ave SE 2 miles to again turn left (west) onto 94th St SE for 1/2 miles to see the school on the north side of the road. There is an abandoned house across the road to the south, a farm to the east and farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Volk School

10/7/2021

Kathy Wilner

EM

West Side





North Side

Volk School

10/7/2021

Kathy Wilner

EM

East Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature



view to W



view to N

32EM937 12 June 09



view to E



view to S

32EM937

12 June 09



view to SW - context photo

SITS # 3.2 EM 93.7
State County Site Number

Field Code CRM 262-72 Site Name _____
Field Code 1.30.75-23-2 Site Name _____

Map Quad SE 9. EP. LAKE SOUTH
Map Quad _____

LTL <input type="checkbox"/>	Twp <u>130</u>	R <u>75</u>	Sec <u>23</u>	QQQ <input checked="" type="checkbox"/>	QQ <input checked="" type="checkbox"/>	Q <u>6</u>
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ <input type="checkbox"/>	QQ <input type="checkbox"/>	Q <input type="checkbox"/>
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ <input type="checkbox"/>	QQ <input type="checkbox"/>	Q <input type="checkbox"/>
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ <input type="checkbox"/>	QQ <input type="checkbox"/>	Q <input type="checkbox"/>
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ <input type="checkbox"/>	QQ <input type="checkbox"/>	Q <input type="checkbox"/>
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ <input type="checkbox"/>	QQ <input type="checkbox"/>	Q <input type="checkbox"/>

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE DATA

City _____
Street # _____ Street # _____
Street Name _____ Street Name _____
of Features 3

FEATURE DATA

<u>1</u> Feature #	<u>9</u> Feature Type	<u>6</u> Condition
_____ Const Date	<u>7</u> Context	<u>2</u> Significance
<u>4</u> Feature Date		<u>5</u> Plan Shape

~~PORCH~~

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

2.5 Structure System 3 Main Entrance
2.6 Primary Exterior Finish
_____ Secondary Exterior Finish

3.1 Ethnic Style 1.1.1888 Fieldwork Date
 Builder Engineer
 Designer Architect

Other Information _____

_____ Soil Association 1.9 Ecozone Area Signf _____ MS Number
_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 CR Type Verified Site _____ Non-Site _____ E C F T F
 State Registry _____ National Register

Coder K. SCHWEIGERT

Date Coded 1/9/89

SITE I.D.
SITE DATA
FEATURE DATA
SHSND USE

NDCRS ARCHITECTURAL SITE FORM

Page 2

Field Code CRM 262-72

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<u>Pro. Judgement</u>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|---|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweiger T

Date 11/18/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code

13075-23-2

Photo

SITS Number _____

