NDCRS ARCHITECTURAL SITE FORM PAGE 1

| | _ | _ | _ | _ | _ |
|---|---|----------------|---------------|---|---|
| | п | $\overline{}$ | | _ | _ |
| | _ | ., | ш | | _ |
| • | | $oldsymbol{-}$ | $\overline{}$ | | _ |

| Field CodeSITE IDENTIFICATION | SITS# 32 EM 950 | |
|---|---|---|
| Map Quad | | |
| LTLTWP132 | 30 QQQ 6 QQ 6 QQ | Q <u>5</u> Q Q |
| NAD 1983, UTME | ZONE | Subsection: 1 = N½ |
| City: | | $2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$ |
| Street Number: | - | $4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$ |
| Street Name: | | 6 = SE½ 7 = SW½ |
| Urban Legal Description: | | 8 = NW½ |
| SITE DATA | | |
| Total # <u>Architectural</u> Features:1 | | |
| Fieldwork Date:11/21/2016 | | |
| Reconnaissance Survey Intensiv | ve Survey 👱 | |
| Project & Principal Investigator: Emmons County Road SC-CNOB-CNOC-1517 | (001), Wade Burns PI | |
| Report Title & Author(s): Emmons County Road Improvements Project: A Emmons County, North Dakota by Tara Friend | A Class III Intensive Cultural Resource Inv | entory in |
| Contracting firm or Agency completing the form: | | |
| Beaver Creek Archaeology, Inc. | | |
| Additional Information: Site destroyed | | |
| SHSND USE Area of Significance 2 Ecozone Ecozone Area of Significance Ecozone Ecozone Ecozone | _ | . 1 |
| Recorded ByCatherine Bohn | er Date Recorded 1 | 2/08/2016 |
| (First Name & Last Name) | | (mm/dd/year) |

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

UPDATE

(mm/dd/year)

| Field Code | | SITS# 32_E | M 950 |
|---|-------------------------------|---------------------------|---------------------|
| Complete one Page 2 for eac | <i>h</i> architectural featur | e at the site. | |
| Architectural Feature #1 | _ | | |
| Construction Date | Feature Type | Condition | |
| Feature Date | Context | Plan Shape_ | |
| Structural System | Primary Exterior | _ Style Not App | licable |
| Original Owner's Ethnicity | Secondary Exterior N/A | Architect/Build | ler |
| Other Information: | | | |
| Foundation | | Stories | <u>—</u> |
| Roof/Cornice | | | |
| Window | | | |
| Dating Method(s): | | | |
| Feature Preservation RecommeIndividual nomination | ndation(s) (Check all th | nat apply): | |
| Contributes to a potential dist | trict | | |
| No nomination potential | | | |
| Will not contribute to a district | t | | |
| Potential district—feature wor | uld be a contributing eleme | nt if other properties co | nstitute a district |
| Thematic nomination potentia | al | | |
| Component of a historic site of | or landscape | | |
| Moved (specify all applicable recreates original site, orienta with neighboring structures; c | ation, landscape, & spatial r | elationships; c) compat | |
| Historical associations require | e further investigation | | |
| Recorded ByCather | ine Bohner | Date Recorded | 12/08/2016 |

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

(First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

| _ | _ | _ | | _ |
|-------|---|---|---|---|
| | | | _ | |
| | | | | |
| | | | | |
| | | | | |

| Field Code | SITS# 32 EM | 950 |
|------------|-------------|-----|
| | | |

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

No remains of the feature were visible in the field. See the attached aerial photograph that demonstrates that it has been destroyed.

| Recorded By | Catherine Bohner | Date Recorded | 12/08/2016 |
|-------------|--------------------------|---------------|--------------|
| , | (First Name & Last Name) | - | (mm/dd/year) |

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

UPDATE

| Field Code | | SITS# 32_ | EM 950 |
|---------------------|---|--------------------|--------------|
| 6. Summary of A | LL Site Features & Evaluation | n of Significance: | |
| been moved or des | ously recommended as ineligible but stroyed, which has destroyed the remigible to the NRHP. | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 7. References/Comme | ents: | | |
| | | | |
| | | | |
| Recorded By | Catherine Bohner | Date Recorded | 12/08/2016 |
| (First I | Name & Last Name) | | (mm/dd/year) |

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code

SITS# 32 EM 950 UPDATE



Figure 1. Aerial image with survey area and site boundary shown.



Figure 2. Most recent aerial image of site location (black line is a telephone pole).

| - | | |
|--------------|--|---|
| | Field Code (C.R.M. 2.6.21.5.) Site Name Field Code (1.3.2.7.63.02.) Site Name | SITS # 3.2 EM 1950 State County Site Number |
| I.D. | Map Quad S.t.R.A.S.B.W.R.G., | 5 |
| SITE | LTL Twp 132 R 26 Sec 30 Sec 17 R LTL Twp L R L Sec LTL Twp R Sec LTL Twp R Sec LTL Twp R Sec LTL Twp R Sec LTL Sec LTL Twp R Sec LTL S | QQQ & QQ & Q & Q & 5 QQQ \ QQ \ QQ \ QQ \ QQ \ QQ \ QQ \ Q |
| | SITE DATA | |
| | City | |
| 4 | Street # Street | # |
| DATA | Street Name Street | Name |
| SITE | # of Features | |
| | FEATURE DA | Condition Significance Plan Shape |
| FEATURE DATA | Original Addition/Altered Removed/None BUILDING MATERIALS .25. Structure Syste .2.6. Primary Exterio Secondary Exterio | r Finish |
| FEA | Style Style | Builder Engineer Designer Architect |
| | \ | Other Information |
| | | |
| USE | Soil Association 49 Ecozone 3 Area | |
| SHSND | G CR Type ↓ Verified Site ∟ Non-Si | |
| SH | ட State Registry | ∟ National Register |
| | Coder Schweigert | |

NDCRS ARCHITECTURAL SITE FORM Page 2

| Field Cod | de <u>CRM262-15</u> | | | | SITS NUMBER |
|---|-------------------------------------|--|--------------------------------------|---|--|
| FEATURE / | # NAME IN NAME | ME BLOCK | | | |
| yes y no unknown other WINDOWS X Original X Altered | FOUNDATION MATERIALS | STORIES 1 1 1/2 2 2 1/2 3 0ther | CORNICE Metal Brick None Wood Other | ROOF TYPE Gable Hipped Deck Gambrel Flat Other | DATING METHOD Plat Map(s) County Atlas Date Block Sanborn Map(s) Topo Map(s) Other Pro. Judgment |
| | RIPTION & STATEMENT OF | INTEGRITY | | | |
| LATORE DESCR | CIFITON & STATEMENT OF | | | | |
| | | | | • | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | 0.000.000.000 | SIGNIFI | CANCE | | V NOT CICHTEICANT |
| Rep. of ty | tic Values Asso pe, period, Asso | al Landmark ciated with ciated with ciated with | devel. of | locality | <pre> X NOT SIGNIFICANT Too new Lacking integrity X Not High Style Other Other </pre> |
| USTIFICATION | OF SIGNIFICANCE | | | | |
| | (v) | | | | |
| | | | | | |
| | | | | | |
| | | | | | 1 /2= |
| corded by | Schuzeigert | | | | Date 7/21/88 |

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS Photo

Field Code 13276-30-2

SITS Number



Field Number: 13276-30-2

Location: SESENE

Notable Features: School Photo Numbers: 5182 Number of Buildings: 1 Dwelling Type/Materials:

Barn Type:

Outbuilding Types/Materials: Other (school) /

Integrity: Isolated Pre-1945 Bldg(s) /

Significance:

UNITED STATES DEPARTMENT OF THE INTERIOR STRASBURG GEOLOGICAL SURVEY HAZELTON 18 MI. LINTON 1.4 MI. 100° 15′ 404000m E 46° 15′ 5122000m N 19 5121 0 5120 262-1 Linton pal Airport 5119 1781 0 5118 12'30" BM 1788 T. 132 N. 1863 1860 T. 131 N. 1850 5117 0 BM 1807