

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Joe Bush Creek Township School

SITS# 32<sup>EM</sup> 982

Map Quad Pollock NW (SD)

Site Name Joe Bush Creek Township School

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL    T. 129 N., R. 78 W., Sec. 34 QQQ 1 of the QQ 8 of the Q 5

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5090324 Zone 14N

NAD 1983 UTM 389353

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: \_\_\_\_\_

Street Number: \_\_\_\_\_

Street Name: 101st St SW

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey

Intensive Survey \_\_\_\_\_

Project & Principal Investigator:

Country School House Project  
Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component \_\_\_\_\_ Study Unit \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM**

**PAGE 2 – Feature Data**

UPDATE

Field Code Joe Bush Creek Township School

SITS# 32 EM 982

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior \_\_\_\_\_

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder \_\_\_\_\_

Foundation Poured concrete Stories 1

Roof/Cornice Hip

Window Double hung openings, no glass

Dating Method(s) Estimate

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM****PAGE 3 – Feature Data**

UPDATE

Field Code Joe Bush Creek Township SchoolSITS# 32 EM 982Complete one Page 3 for *each* architectural feature at the site.

## 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The hip roof is partially covered with wood shakes. There is a red brick chimney on the south slope and some of the top bricks have fallen off. The soffits are closed.

A rake board begins the siding under the eaves on all four sides of the school. The remaining siding is 6 inch wood lap and 4 inch corner trim with waterboard at the bottom. Three concrete steps lead to a concrete platform which takes you through the entry door opening. The floor is tongue and groove hardwood and it is falling away in the entry. The interior school room floor has old grain covering it. The interior walls and angled ceiling were finished with beadboard. Most of the ceiling beadboard has fallen in. Three double hung window openings are located on the north side, with four more on the east side. The windows have a bit of framing and no glass. One more window opening is located on the east wall near the south end in the coatroom. A small opening near the south side on the west wall was likely a fuel door.

A barn sits to the southwest of the school. I did not document this barn.

## 2. Owner's Contact Information:

Diana Pollock  
409 Lakeshore Dr  
Pollock SD 57648

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

**NDCRS ARCHITECTURAL FORM**

**PAGE 4 – Site Description**

**UPDATE**

**Field Code** Joe Bush Creek Township School

**SITS#** 32 **EM** 982

3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

Access to this school is from Hwy 1804 north of Pollock. Go to 101st St SW and turn right to go east 1/2 mile to see the school where the road curves to the north. There is an abandoned house to the north and hilly fields and pasture all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

**Recorded By:** Kathy Wilner **Date Recorded:** 11/11/2021



South Side

Joe Bush Creek Township School

10/7/2021

Kathy Wilner

EM

West Side





North Side

Joe Bush Creek Township School

10/7/2021

Kathy Wilner

EM

East Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature



view to SW context



view to SW





view to W



view to NE



view to E

SITS # 3.2 EM 9.8.2  
State County Site Number

Field Code C.R. 1.2.6.2-1.2 Site Name \_\_\_\_\_  
Field Code 1.2.9.7.8-3.4-3 Site Name \_\_\_\_\_

Map Quad P.O. 1.1.0.0.11. N.W.  
Map Quad \_\_\_\_\_

LTL	<input type="checkbox"/>	Twp	<u>1.2.9</u>	R	<u>7.8</u>	Sec	<u>3.4</u>	QQQ	<input type="checkbox"/>	QQ	<u>8</u>	Q	<u>5</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE I.D.

SITE DATA

City \_\_\_\_\_  
Street # \_\_\_\_\_ Street # \_\_\_\_\_  
Street Name \_\_\_\_\_ Street Name \_\_\_\_\_  
# of Features 2

FEATURE DATA

1 Feature #      9 Feature Type      5 Condition  
\_\_\_\_\_ Const Date      7 Context      2 Significance  
4 Feature Date      6 Plan Shape

~~PORCH~~

~~Original  
 Addition/Altered  
 Removed/None~~

BUILDING MATERIALS

2.5 Structure System      ~~2 Main Entrance~~  
2.6 Primary Exterior Finish  
\_\_\_\_\_ Secondary Exterior Finish

3.1 Ethnic Style

10.7.2.1.18.8 Fieldwork Date

Builder  
 Engineer  
 Designer Architect

Other Information \_\_\_\_\_

FEATURE DATA

\_\_\_\_\_ Soil Association 1.9 Ecozone 2 Area Signf      \_\_\_\_\_ MS Number  
\_\_\_\_\_ Soil Association \_\_\_\_\_ Ecozone \_\_\_\_\_ Area Signf      \_\_\_\_\_ MS Number  
2 CR Type      1 Verified Site      \_\_\_\_\_ Non-Site      2 E C F      2 T F  
\_\_\_\_\_ State Registry      \_\_\_\_\_ National Register

SHSND USE

Coder Schweigert

Date Coded 7/21/88

NDCRS ARCHITECTURAL SITE FORM  
Page 2

Field Code CRM 262-12 SITS NUMBER \_\_\_\_\_  
 FEATURE # / NAME IN NAME BLOCK \_\_\_\_\_

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>Pro. Judgment</i>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SIGNIFICANCE

- |   |   |
|---|---|
| <input type="checkbox"/> SIGNIFICANT                                  | <input checked="" type="checkbox"/> NOT SIGNIFICANT   |
| <input type="checkbox"/> Work of Master                               | <input type="checkbox"/> Too new                      |
| <input type="checkbox"/> High Artistic Values                         | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input checked="" type="checkbox"/> Not High Style    |
| <input type="checkbox"/> Other _____                                  | <input type="checkbox"/> Other _____                  |
| <input type="checkbox"/> Visual Landmark                              |   |
| <input type="checkbox"/> Associated with significant event            |   |
| <input type="checkbox"/> Associated with devel. of locality           |   |
| <input type="checkbox"/> Associated with significant person           |   |

JUSTIFICATION OF SIGNIFICANCE \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Recorded by Schweigert Date 7/21/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 12978-34-3

Photo

SITS Number \_\_\_\_\_

