

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code _____

SITS# 32 EM 990 _____

Map Quad _____

Site Name _____

Map Quad _____

Site Name _____

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

NAD _____ UTM _____ Zone _____

NAD _____ UTM _____

City: _____

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: _____

Street Name: _____

Urban Legal Description: _____

Total Number of Architectural Features: _____

Fieldwork Date: _____

Reconnaissance Survey _____

Intensive Survey _____

Project & Principal Investigator: _____

Contracting Firm or Agency Completing the Form:

SHSND

Additional Information:

based on map checks by Kathy Wilner and aerial imagery

SHSND USE

Component _____ Study Unit _____ Verified Site _____ CR Type _____

Component _____

Component _____

Recorded By: Lorna Meidinger Date Recorded: 02/02/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code _____

SITS# 32 EM 990 _____

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date _____

Structural System _____

Original Owner's Ethnicity _____

Feature Type _____

Context _____

Primary Exterior _____

Secondary Exterior _____

Condition Destroyed

Plan Shape _____

Style _____

Architect/Builder _____

Foundation _____ Stories _____

Roof/Cornice _____

Window _____

Dating Method(s) _____

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Lorna Meidinger **Date Recorded:** 02/02/2022

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

Field Code _____

SITS# 32 EM 990 _____

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

Based on aerial imagery available online from the ND Historical Map & Aerial Photography Dissemination Service, the school was removed between 7/25/2016 and 9/20/2017.

2. Owner's Contact Information:

Recorded By: _____ **Lorna Meidinger** _____ **Date Recorded:** _____ **02/02/2022** _____

NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description

UPDATE

Field Code _____

SITS# 32 EM 990 _____

3. Site Area (ft²):

4. Description of Access and Site Setting:

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

<http://aerial.swc.nd.gov/>

Recorded By: Lorna Meidinger **Date Recorded:** 02/02/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

SITS # 3.2 EM 99.0
State County Site Number

1. N $\frac{1}{4}$
2. E $\frac{1}{4}$
3. S $\frac{1}{4}$
4. W $\frac{1}{4}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

Field Code CR M262-25 Site Name _____
Field Code 13677-16-1 Site Name _____

Map Quad M.O.F.F.I.T. SE
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>136</u>	R	<u>77</u>	Sec	<u>16</u>	QQQ	<u>7</u>	QQ	<u>6</u>	Q	<u>6</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

SITE DATA

City _____
Street # _____ Street # _____
Street Name _____ Street Name _____
of Features 3

FEATURE DATA

1 Feature # 9 Feature Type 5 Condition
_____ Const Date 7 Context 2 Significance
4 Feature Date 5 Plan Shape

~~PORCH~~

BUILDING MATERIALS

~~Original~~ 25 Structure System 1 Main Entrance
~~Addition/Altered~~ 26 Primary Exterior Finish
~~Removed/None~~ _____ Secondary Exterior Finish

31 Ethnic Style _____ Builder
07/2/88 Fieldwork Date _____ Engineer
_____ Designer Architect

_____ Other Information

_____ Soil Association 19 Ecozone 2 Area Signf _____ MS Number
_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
2 CR Type 1 Verified Site _____ Non-Site 2 E C F 2 T F
_____ State Registry _____ National Register

Coder Schweigert Date Coded 1/9/89

SITE I.D.
SITE DATA
FEATURE DATA
SHSND USE

NDCRS ARCHITECTURAL SITE FORM

Page 2

Field Code CRM 262-25

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input checked="" type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>pro. judgement</i>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

CLOSED IN 1963. TOWNSHIP COUNCIL HAS PLANS TO
SEU- THE BUILDING. ACCORDING TO THEM, THE
BLDG MUST BE MOVED BECAUSE OF THE POOR
CONDITION OF THE FOUNDATION. -- 20 MAR 1996

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|--|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

SITS # 32 EM 990
State County Site Number

Field Code C.R.M. 2, 6, 2, - 25 Site Name _____
Field Code 1.3.6.P.Z - 1.6. - 1 Site Name _____

Map Quad M.O.F.F.I.T. S.E.
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>1.3.6</u>	R	<u>77</u>	Sec	<u>1.6</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<u>6</u>	Q	<u>6</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE DATA

City _____
Street # _____ Street # _____
Street Name _____ Street Name _____
of Features 3

FEATURE DATA

<u>2</u> Feature #	<u>5.0</u> Feature Type	<u>5</u> Condition
_____ Const Date	<u>7</u> Context	<u>2</u> Significance
<u>4</u> Feature Date		<u>5</u> Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

2.5 Structure System
2.6 Primary Exterior Finish
_____ Secondary Exterior Finish

3 Main Entrance

_____ Ethnic
_____ Style
10.7.2.118.8 Fieldwork Date
_____ Builder
_____ Engineer
_____ Designer Architect

Other Information _____

_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 CR Type Verified Site Non-Site E C F T F
 State Registry National Register

Coder Schweigert Date Coded 1/9/89

SITE I.D.
SITE DATA
FEATURE DATA
SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM 762-25

SITS NUMBER _____

FEATURE # 2 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input checked="" type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown			<u>SHED</u>	<u>Pro. Judgment</u>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input type="checkbox"/> Altered	<u>None</u>				

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|--|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

SITS # 3.2 EM _____
State County Site Number

Field Code CRM2.6.2.-25 Site Name _____
Field Code _____ Site Name _____

Map Quad M.O.F.F.I.T. S.E. _____
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>13.6</u>	R	<u>7.7</u>	Sec	<u>16</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<u>6</u>	Q	<u>6</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	_____	Q	_____

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE I.D.

SITE DATA

City _____

Street # _____ Street # _____

Street Name _____ Street Name _____

of Features 3

FEATURE DATA

3 Feature # 5.0 Feature Type 4 Condition
 _____ Const Date 7 Context 2 Significance
 Feature Date _____ Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

25 Structure System 3 Main Entrance
26 Primary Exterior Finish
 _____ Secondary Exterior Finish

_____ Ethnic _____ Builder
 _____ Style _____ Engineer
0.7.2.189 Fieldwork Date _____ Designer Architect

Other Information _____

SITE DATA

FEATURE DATA

_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 _____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 CR Type Verified Site Non-Site _____ E C F T F
 State Registry _____ National Register

SHSND USE

Coder Schweigert Date Coded 1/9/89

NDCRS ARCHITECTURAL SITE FORM

Page 2

Field Code CRM 262-25

SITS NUMBER _____

FEATURE # 3 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input checked="" type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown			<u>SHED</u>	<u>Prop. Judgment</u>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input type="checkbox"/> Altered	<u>None</u>				

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|---|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

Field Report: 13677-16-1

Location: SWSESE

Notable Features:

Photo Numbers: 6697

Number of Buildings: 3

Dwelling Type/Materials:

Barn Type:

Outbuilding Types/Materials: Privy/outhouse / Privy/outhouse / Other
(school) /

Integrity: All Bldgs Pre-1945 /

Significance:

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 13677-16-1

Photo

SITS Number _____





view to W



view to SW



view to SE



view to S