

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Sand Creek Township School

SITS# 32EM 1012

Map Quad Hazelton SW

Site Name Sand Creek Township School

Map Quad

Site Name

LTL T. 133 N., R. 77 W., Sec. X9 QQQ 7 of the QQ 7 of the Q 8

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5133797 Zone 14N

NAD 1983 UTM 394000

City:

Street Number:

Street Name: 2nd Ave SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey [checked]

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component Study Unit Verified Site CR Type

Component

Component

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

Table with 1 column: Subsection. Rows: 1 = N1/2, 2 = E1/2, 3 = S1/2, 4 = W1/2, 5 = NE1/4, 6 = SE1/4, 7 = SW1/4, 8 = NW1/4

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code Sand Creek Township School

SITS# 32 EM 1012

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured Concrete Stories 1

Roof/Cornice Gable

Window Double hung openings

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data**

UPDATE

Field Code Sand Creek Township SchoolSITS# 32 EM 1012Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. An addition on the east side may have been used for a teacherage. The gable roof of the school and entry and the shed roof of the addition are covered with wood shakes with metal capping. There is a broken yellow brick chimney at the north end of the peak. The school measures 18 feet east to west by 24 feet north to south and the addition measures 12 feet east to west by 24 feet north to south. The soffits are closed.

The siding begins with a rake board on the peak ends of the school. All other siding is 6 inch wood lap with 4 inch wood corner trim. A concrete pad leads to a concrete step and porch. The south entry has no door. There are two smaller double hung windows in the entry, one east the other west. A third window opening looks into the school. Inside the school proper there is a a small room to the left that may have been a fuel room. One small window in this room. A bank of 5 double hung window openings is located on the west side. There is some framing and no glass. The addition has three windows, one south, one east and one north. The walls in the entry have beadboard. The walls and angled ceiling in the school room are covered with lathe and plaster with wainscot. The blackboard covers 3/4 of the north wall and 1/2 of the east wall. A broken door in the east wall leads into the addition. The floor is tongue and groove hardwood. The addition walls are stripped to the studs and a hole in the roof is where a chimney sat. Light fixtures indicate the presence of electricity at some point. This school has a barn nearby, I did not document it.

2. Owner's Contact Information:

Patricia Huber, Kathryn Holzer, Lori Kalama

Recorded By: Kathy Wilner Date Recorded: 11/10/2021

NDCRS ARCHITECTURAL FORM**PAGE 4 – Site Description**

UPDATE

Field Code Sand Creek Township School**SITS# 32** EM 10123. Site Area (ft²):

4. Description of Access and Site Setting:

Access to this school if from Hwy 83 north of Linton about 5 and 1/2 miles to 72nd St SE. At 72nd St SE turn left (west) to go 5 miles to a prairie road that would be 2nd Ave SE on a map. The prairie road is very rocky and not user friendly for a car. It is 1 1/2 miles south of on that prairie road to the school. The school is in the middle of farm fields with no farms visible at this location.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 11/10/2021



South Side

Sand Creek Township School

10/7/2021

Kathy Wilner

EM

West Side





North Side

Sand Creek Township School

10/7/2021

Kathy Wilner

EM

East Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature

72nd St SE is 1 ½ miles north of this school.

SITS # 3.2 E.M. 1.D.1.2
State County Site Number

Field Code CRM26.2-1.9 Site Name _____
Field Code 1.3.3.7.7-9-1 Site Name _____

Map Quad Hazelton, S.W.
Map Quad _____

LTL	Twp	<u>1.3.3</u>	R	<u>7.7</u>	Sec	<u>9</u>	QQQ	<u>7</u>	QQ	<u>7</u>	Q	<u>8</u>
LTL	Twp	<u>1.3.3</u>	R	<u>7.7</u>	Sec	<u>9</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>7</u>
LTL	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____

1. N
2. E
3. S
4. W
5. NE
6. SE
7. SW
8. NW
9. C

SITE DATA

City _____
Street # _____ Street # _____
Street Name _____ Street Name _____
of Features 2

FEATURE DATA

1 Feature # 9 Feature Type 5 Condition
_____ Const Date 7 Context 2 Significance
3 Feature Date 5 Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

2.5 Structure System 2 Main Entrance
2.6 Primary Exterior Finish
_____ Secondary Exterior Finish

_____ Ethnic _____ Builder
1.4 Style _____ Engineer
10.5.2.1.13.8 Fieldwork Date _____ Designer Architect

_____ Other Information

_____ Soil Association 1.9 Ecozone 2 Area Signf _____ MS Number
_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
2 CR Type 1 Verified Site _____ Non-Site 2 E C F 2 T F
_____ State Registry _____ National Register

Coder Schwiger Date Coded 7/21/88

SITE I.D.

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM262-19

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>Pro. Judgement</i>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|--|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

SITS # 3.2 EM _____
State County Site Number

Field Code C.R.M.2.6.2.-1.9. Site Name _____
Field Code 1.3.3.7.7.-9.-1. Site Name _____

Map Quad H.9.2.e.1.7.0.n.5.w _____
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>133</u>	R	<u>77</u>	Sec	<u>9</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<input checked="" type="checkbox"/>	Q	<u>8</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE DATA

City _____

Street # _____ Street # _____

Street Name _____ Street Name _____

of Features 2

FEATURE DATA

2 Feature # 6.3 Feature Type 6 Condition
 Const Date 7 Context 2 Significance
 Feature Date Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

2.5 Structure System 2 Main Entrance
 2.6 Primary Exterior Finish
 Secondary Exterior Finish

Ethnic Builder
 Style Engineer
 10.7.12.11.88 Fieldwork Date Designer Architect

Other Information _____

Soil Association Ecozone Area Signf _____ MS Number
 Soil Association Ecozone Area Signf _____ MS Number
 CR Type Verified Site Non-Site _____ E C F T F
 State Registry National Register

Coder Schueigert Date Coded 7/21/88

SITE I.D.

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM 262-19

SITS NUMBER _____

FEATURE # 2 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input type="checkbox"/> Other
<u>WINDOWS</u>	<input checked="" type="checkbox"/> Unknown				<u>no judgement</u>
	<input type="checkbox"/> Other				

Original
 Altered
 NONE

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|--|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

Field Number: 13377-9-1

Location: SWSWNW

Notable Features:

Photo Numbers: 6558

Number of Buildings: 2

Dwelling Type/Materials:

Barn Type: Gabled Wood Frame /

Outbuilding Types/Materials: Other (school) /

Integrity: All Bldgs Pre-1945 /

Significance:

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 13377-9-1

Photo

SITS Number _____





view to SE context



view to SE



view to NE