

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Dekker Creek Township School #1

SITS# 32EM 1032

Map Quad Westfield
Map Quad

Site Name Dekker Creek Township School #1
Site Name

LTL T. 129 N., R. 76 W., Sec. 10 QQQ 7 of the QQ 7 of the Q 7
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q

Subsection
1 = N1/2
2 = E1/2
3 = S1/2
4 = W1/2
5 = NE1/4
6 = SE1/4
7 = SW1/4
8 = NW1/4

NAD 1983 UTM 5094839 Zone 14N
NAD 1983 UTM 407746

City:

Street Number:

Street Name: 98th St SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey [checked]

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component Study Unit Verified Site CR Type
Component
Component

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

## NDCRS ARCHITECTURAL FORM

## PAGE 2 – Feature Data

UPDATE

Field Code Dekker Creek Township School #1SITS# 32 1032

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1900-1915Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Wood, Horizontal Siding

Secondary Exterior \_\_\_\_\_

Condition FairPlan Shape RectangularStyle Other Style

Architect/Builder \_\_\_\_\_

Foundation Poured concrete Stories 1Roof/Cornice GableWindow CoveredDating Method(s) Previous documentation

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):** Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM****PAGE 3 – Feature Data**

UPDATE

Field Code Dekker Creek Township School #1SITS# 32 1032Complete one Page 3 for *each* architectural feature at the site.

## 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The gable roof has little in the way of shingles with only scraps of asphalt left. The chimney is gone. The soffits are open.

Rake boards begin the siding under the eaves at the peak ends of the school. The rest of the siding is 6 inch wood lap with 6 inch corner trim. Some of the trim at the corners is gone. On the west side some of the siding boards are missing and you can see the flax straw that was used for insulation. On the east side there is one covered window opening near the south end. A fuel door is at the south end of the west wall and all the other windows are covered. A door opening is located on the south wall. No information about the interior.

## 2. Owner's Contact Information:

Arnold & Charlotte Huizenga  
2815 385th Ave N  
Aberdeen SD 57401

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

**NDCRS ARCHITECTURAL FORM****PAGE 4 – Site Description**

UPDATE

Field Code Dekker Creek Township School #1SITS# 32 10323. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

Access to this school if from Hwy 83 south of Strasburg at 98th St SE. Turn right (west) and drive 6 miles to see the school at the intersection of 98th St SE and 9th Ave SE. Abandoned farm sites are north and south, a working farm is to the west and there are farm fields all around.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Drekker Township School #1

10/7/2021

Kathy Wilner

EM

South Side





West Side

Dekker Creek Township School #1

10/7/2021

Kathy Wilner

EM

North Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature



view to SE



view to E





view to NW

32EM1032 12 June 09

SITS # 3.2 E.M. 1.03.2  
State County Site Number

1. N  $\frac{1}{2}$
2. E  $\frac{1}{2}$
3. S  $\frac{1}{2}$
4. W  $\frac{1}{2}$
5. NE  $\frac{1}{4}$
6. SE  $\frac{1}{4}$
7. SW  $\frac{1}{4}$
8. NW  $\frac{1}{4}$
9. C

Field Code C.R.M.2.6.2.-.8. Site Name \_\_\_\_\_  
Field Code 1.2.9.7.6.-.1.0.-.1 Site Name \_\_\_\_\_

Map Quad WESTFIELD  
Map Quad \_\_\_\_\_

LTL	<input type="checkbox"/>	Twp	<u>1.2.9</u>	R	<u>7.6</u>	Sec	<u>1.0</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<input checked="" type="checkbox"/>	Q	<input checked="" type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

SITE DATA

City \_\_\_\_\_  
Street # \_\_\_\_\_ Street # \_\_\_\_\_  
Street Name \_\_\_\_\_ Street Name \_\_\_\_\_  
# of Features 2

FEATURE DATA

1 Feature #       9 Feature Type       5 Condition  
 \_\_\_\_\_ Const Date       7 Context       5 Significance  
 3 Feature Date       5 Plan Shape

PORCH

BUILDING MATERIALS

Original       25 Structure System       2 Main Entrance  
 Addition/Altered       26 Primary Exterior Finish  
 Removed/None       Secondary Exterior Finish

74 Ethnic Style       Builder  
 10.12.11.8.8 Fieldwork Date       Engineer  
 \_\_\_\_\_ Designer Architect

Other Information \_\_\_\_\_

Soil Association 1.9 Ecozone  Area Signf      \_\_\_\_\_ MS Number  
 Soil Association \_\_\_\_\_ Ecozone  Area Signf      \_\_\_\_\_ MS Number  
 CR Type       Verified Site       Non-Site       E C F       T F  
 State Registry       National Register

Coder Schweiger      Date Coded 1/8/89

SITE I.D.

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM  
Page 2

Field Code CRM262-8

SITS NUMBER \_\_\_\_\_

FEATURE # 1 NAME IN NAME BLOCK \_\_\_\_\_

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<u>No. Judgement</u>
	<input type="checkbox"/> Other				
<input type="checkbox"/> Original					
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY \_\_\_\_\_

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- |   |   |   |
|---|---|---|
| <input type="checkbox"/> Work of Master                               | <input type="checkbox"/> Visual Landmark                    | <input type="checkbox"/> Too new                      |
| <input type="checkbox"/> High Artistic Values                         | <input type="checkbox"/> Associated with significant event  | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style    |
| <input type="checkbox"/> Other _____                                  | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____                  |

JUSTIFICATION OF SIGNIFICANCE \_\_\_\_\_

Recorded by Schweigert

Date 7/21/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 12976-10-1

Photo

SITS Number \_\_\_\_\_

