

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Dekker Creek Township School #2

SITS# 32EM 1036

Map Quad Herreid NW

Site Name Dekker Creek Township School #2

Map Quad

Site Name

LTL T. 129 N., R. 76 W., Sec. 20 QQQ 5 of the QQ 5 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5093187 Zone 14N

NAD 1983 UTM 406061

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City:

Street Number:

Street Name: 99 th St SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator: Country School House Project, Kathy Wilner, 366 43rd Ave SE, Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
 Component _____ Study Unit _____ Verified Site _____ CR Type _____
 Component _____
 Component _____

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

UPDATE

Field Code Dekker Creek Township School #2

SITS# 32 EM

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior

Condition Poor

Plan Shape Square

Style Other Style

Architect/Builder

Foundation Poured concrete Stories 1

Roof/Cornice Hip

Window Double hung openings

Dating Method(s) Estimate

Miscellaneous Information

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data**

UPDATE

Field Code Dekker Creek Township School #2SITS# 32 EMComplete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The hip roof has remnants of asphalt shingles. There is a hole where the chimney was on the north slope. The soffits are open. There is a sagging portico at the south door.

A rake board begins the siding on all four sides of the school. The rest of the siding is 6 inch wood lap with 6 inch corner trim. There are double hung window openings, two on the north, four on the east and one on the west. Another small window opening is also on the west side. There is no glass left. The north wall is sagging and bowing and looks to be ready to fall off. The door opening is to the south and the door is gone. The walls and ceiling have all been stripped. The floor is hardwood.

2. Owner's Contact Information:

Louis Vander Vorste
742 99th St SE
Pollock SD 57648

Recorded By: Kathy Wilner Date Recorded: 11/11/2021

NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description

UPDATE

Field Code Dekker Creek Township School #2

SITS# 32 EM

3. Site Area (ft²):

4. Description of Access and Site Setting:

Access to this school is from Hwy 83 south of Strasburg to 98th St SE. Turn right (west) on 98th St SE and go 6 miles to 9th Ave SE. Turn left and go 1 mile south to 99th St SE, turn right (west) and go 1 mile to 8th Ave SE. School is on the southeast corner. There are farm sites with farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 11/11/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South side

Dekker Creek Township School #2

10/7/2021

Kathy Wilner

EM

East Side





West Side

Dekker Creek Township School #2

10/7/2021

Kathy Wilner

EM

North Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 100 ft

Feature



view to N



view to W



view to S



view to SE

SITS # 3.2 E.M. 1036
State County Site Number

Field Code C.R.M.2.6.2.-9 Site Name _____
Field Code 1.2.9.7.6.-2.0.-1 Site Name _____

Map Quad H.E.R.R.E.I.D. N.W
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>1.2.9</u>	R	<u>7.6</u>	Sec	<u>2.0</u>	QQQ	<u>5</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	_____	QQ	_____	Q	_____

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

SITE DATA

City _____
Street # _____ Street # _____
Street Name _____ Street Name _____
of Features 2

FEATURE DATA

1 Feature # 9 Feature Type 4 Condition
_____ Const Date 7 Context ~~2 Significance~~
4 Feature Date 6 Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

25 Structure System ~~3 Main Entrance~~
26 Primary Exterior Finish
_____ Secondary Exterior Finish

31 Ethnic Style

0.7.12.18.8 Fieldwork Date

Builder
 Engineer
 Designer Architect

Other Information _____

_____ Soil Association 1.9 Ecozone Area Signf _____ MS Number
_____ Soil Association _____ Ecozone Area Signf _____ MS Number
 CR Type Verified Site Non-Site 3 E C F 3 T F
 State Registry National Register

Coder Schweigert

Date Coded 1/8/89

SITE I.D.
SITE DATA
FEATURE DATA
SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM262-9

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>Pro. Judgment</i>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input checked="" type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|---|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input checked="" type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 7/21/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 12976-20-1

Photo

SITS Number _____

