

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Elzas Township School

SITS# 32EM 1052

Map Quad Herreid NE (SD)

Site Name Elzas Township School

Map Quad _____

Site Name _____

LTL T. 129 N., R. 75 W., Sec. 29 QQQ 5 of the QQ 5 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5091385 Zone 14N

NAD 1983 UTM 415698

City: _____

Street Number: _____

Street Name: 100th St SE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 10/7/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form: _____

Additional Information: _____

SHSND USE

Component _____ Study Unit _____ Verified Site _____ CR Type _____

Component _____

Component _____

Recorded By: Kathy Wilner Date Recorded: 11/11/3031

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM**PAGE 2 – Feature Data**

UPDATE

Field Code Elzas Township SchoolSITS# 32 EM 1052Complete one Page 2 for *each* architectural feature at the site.Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition FairPlan Shape RectangularStyle Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1Roof/Cornice HipWindow Double hung openings, some framingDating Method(s) Previous documentation

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner Date Recorded: 11/11/3031

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data****Field Code** Elzas Township School**SITS#** 32 **EM** 1052**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a poured concrete foundation. The hip roof is partially covered with failing asphalt shingles with metal capping. There is a large, red brick chimney at the peak on the east slope of the roof. Another square opening is at the peak in the middle of the school. I believe that was for getting grain into the building. The soffits are closed.

A rake board begins the siding under the eaves on all four sides. The rest of the siding is 6 inch wood lap and 4 inch corner trim with a waterboard at the bottom. The entry door on the east side is missing. Inside the entry there are door openings to the left and right, leading into coatrooms. Another door opening leads into the school proper. There are two double hung window openings with some framing and not glass near the east side of the school on both the north and south sides that are located in the coatrooms. A bank of 8 windows run along the entire south wall of the school room. Double hung openings have some framing, no glass and are boarded up from the inside as the building was used for a granary. The floor is tongue and groove hardwood. The walls and ceiling are finished with lathe and plaster.

2. Owner's Contact Information:

Todd & Carrie Nieuwsma
9950 13th Ave SE
Herreid SD 57632

Recorded By: Kathy Wilner **Date Recorded:** _____

NDCRS ARCHITECTURAL FORM**PAGE 4 – Site Description**

UPDATE

Field Code Elzas Township School**SITS#** 32 **EM** 10523. Site Area (ft²):

4. Description of Access and Site Setting:

Access to this school is from Strasburg south on Hwy 83 about 12 miles to 100th St SE.

Turn right (west) onto 100th St SE and drive one mile to see it at the southwest corner of the intersection. There is a creek just to the west of the school, farms north, south and west and farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 11/11/3031

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



North Side

Elzas Township School

10/7/2021

Kathy Wilner

EM

West Side





South Side

Elzas Township School

10/7/2021

Kathy Wilner

EM

East Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 100 ft

Feature



view to W



view to NW



view to S



view to SE

SITS # 3.2 EM 105.2
State County Site Number

Field Code C.R.M.26.2-6 Site Name _____
Field Code 129.75-29-1 Site Name _____

Map Quad HERREIDA, NE
Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>129</u>	R	<u>75</u>	Sec	<u>29</u>	QQQ	<u>5</u>	QQ	<u>5</u>	Q	<u>5</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N
2. E
3. S
4. W
5. NE
6. SE
7. SW
8. NW
9. C

SITE DATA

City _____

Street # _____ Street # _____

Street Name _____ Street Name _____

of Features 1

FEATURE DATA

1 Feature # 9 Feature Type 5 Condition
 _____ Const Date 7 Context 2 Significance
3 Feature Date _____ Plan Shape

PORCH

Original
 Addition/Altered
 Removed/None

BUILDING MATERIALS

2.5 Structure System 2 Main Entrance
2.6 Primary Exterior Finish
 _____ Secondary Exterior Finish

_____ Ethnic Style
3.1 _____

10.6 2.3 10.8 Fieldwork Date

_____ Builder
 _____ Engineer
 _____ Designer Architect

_____ Other Information

_____ Soil Association 1.9 Ecozone 3 Area Signf _____ MS Number

_____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number

2 CR Type Verified Site Non-Site 2 E C F 2 T F

State Registry National Register

Coder Schweigert

Date Coded 1/6/89

SITE I.D.

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM
Page 2

Field Code CRM262-6

SITS NUMBER _____

FEATURE # 1 NAME IN NAME BLOCK _____

<u>BASEMENT</u>	<u>FOUNDATION MATERIALS</u>	<u>STORIES</u>	<u>CORNICE</u>	<u>ROOF TYPE</u>	<u>DATING METHOD</u>
<input type="checkbox"/> yes	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> Metal	<input type="checkbox"/> Gable	<input type="checkbox"/> Plat Map(s)
<input checked="" type="checkbox"/> no	<input type="checkbox"/> Concrete Block	<input type="checkbox"/> 1 1/2	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> Hipped	<input type="checkbox"/> County Atlas
<input type="checkbox"/> unknown	<input type="checkbox"/> Fieldstone	<input type="checkbox"/> 2	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Deck	<input type="checkbox"/> Date Block
<input type="checkbox"/> other	<input type="checkbox"/> Cut Stone	<input type="checkbox"/> 2 1/2	<input type="checkbox"/> Wood	<input type="checkbox"/> Gambrel	<input type="checkbox"/> Sanborn Map(s)
	<input checked="" type="checkbox"/> Poured Concrete	<input type="checkbox"/> 3	<input type="checkbox"/> Other	<input type="checkbox"/> Flat	<input type="checkbox"/> Topo Map(s)
	<input type="checkbox"/> Refaced	<input type="checkbox"/> Other		<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other
<u>WINDOWS</u>	<input type="checkbox"/> Unknown				<i>No judgement</i>
<input checked="" type="checkbox"/> Original	<input type="checkbox"/> Other				
<input type="checkbox"/> Altered					

FEATURE DESCRIPTION & STATEMENT OF INTEGRITY _____

SIGNIFICANCE

SIGNIFICANT

NOT SIGNIFICANT

- | | | |
|---|---|---|
| <input type="checkbox"/> Work of Master | <input type="checkbox"/> Visual Landmark | <input type="checkbox"/> Too new |
| <input type="checkbox"/> High Artistic Values | <input type="checkbox"/> Associated with significant event | <input checked="" type="checkbox"/> Lacking integrity |
| <input type="checkbox"/> Rep. of type, period, method of construction | <input type="checkbox"/> Associated with devel. of locality | <input checked="" type="checkbox"/> Not High Style |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Associated with significant person | <input type="checkbox"/> Other _____ |

JUSTIFICATION OF SIGNIFICANCE _____

Recorded by Schweigert

Date 6/23/88

NDCRS ARCHEOLOGICAL AND HISTORICAL SITE FORMS

Field Code 12975-29-1

Photo

SITS Number _____

