

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 FO 69

SITE IDENTIFICATION

Field Code Wyard Township School

Site Name Wyard Township School

Map Quad Carrington West

Site Name _____

LTL	TWP	<u>146</u>	R	<u>67</u>	SEC	<u>22</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
 UTM _____ E NAD 1927 _____ NAD 1983 _____

Subsection:
 1 = N½
 2 = E½
 3 = S½
 4 = W¼
 5 = NE¼
 6 = SE¼
 7 = SW¼
 8 = NW¼

City: Carrington ND

Street Number: approx. 6310

Street Name: Highway 200

Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 9/20/2012

Reconnaissance Survey Intensive Survey

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s): _____

Additional Information: _____

SHSND USE

Area of Significance 2 Ecozone 18 Verified Site _____ CR Type 2
 Area of Significance _____ Ecozone _____ Non-Site _____
 Area of Significance _____

Recorded By Kathy Wilner Date Recorded 9/19/2012
 (First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Wyard Township SchoolSITS# 32 FO

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9Condition 5Feature Date 3Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation concrete block Stories 1Roof/Cornice HipWindow Double hungDating Method(s): County history & school records

Feature Preservation Recommendation(s) (Check all that apply):

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 9/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code Wyard Township SchoolSITS# 32 FO**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

This is a larger, two-room, prairie school building in its original location. This roof on the building has asphalt shingles with a newer looking block chimney on the east facing slope. There are vent pipes on the north and south slopes of the roof. The school has two entry doors, one at the northeast corner and another at the southeast corner. The entries each have a transom window above the door, one with glass. There is 6 inch lap siding with little paint left. Overlapping metal trim pieces finish the corners. The school has several windows with 8 large, double hung windows facing to the west. About half the glass remains on this side. There are two smaller double hung windows on the north wall, 4 on the east wall and a row of 5 fixed pane windows high on the south wall. The school sits on a concrete block basement. The basement sits up high enough for windows to allow light into the basement space. Poured concrete steps with metal railings lead up to each door. Entry lights by each door are indicative of electricity.

Entering the school from either door there is a landing space before turning to the left or right to go into the main body of the school. Straight ahead of the door are wood steps leading to the basement. These steps lead down from both entry doors and meet at a small space at the bottom that then leads into the greater space in the basement. A former student told me they had a lunch room and bathrooms in the basement. It was also a play space on very cold days. The school was heated with fuel oil. Space under the north steps held mechanical equipment was and under the south steps they had a refrigerator for milk.

Upstairs there is a wall dividing the main body of the school into two classrooms. The south side is the larger room with five of the west facing windows and the 5 south windows giving this room lots of light. Beautiful, wide, dark wood trims all the windows. Hard wood tongue and groove flooring with lathe and plaster on the walls and ceiling. The blackboards were on the dividing wall with heat vents along the base of the wall. I also saw cold air return vents in both rooms. There was wainscoting around plumbing on one of the walls. Perhaps a sink was there. The north room was a little smaller with blackboards on both the dividing wall and the north wall between two windows. There was a vent in the ceiling of this room with some sort of a pulley system with a long chain for opening and closing that vent. A closet in the middle of the east wall that had shelving for storage.

The classrooms each had a teacher, one room for grades 1-4 and the other for grades 5-8. This school was operational until 1967 and closed October 14, 1969.

Recorded By Kathy Wilner Date Recorded 9/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code Wyard Township School

SITS# 32 FO

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Dennis Hagel
6375 Hwy 200
Carrington Nd 58421

3. Access (to rural areas):

This school is located three miles east of Carrington ND, on Hwy 200. It is on the south side of the road at Hwy 200 and 63rd Ave NE.

4. Site Area (ft²): _____

5. Description of **SETTING**:

There are two farm sites to the north east of the school and farm fields all other directions. The land is quite flat in this area.

Recorded By Kathy Wilner Date Recorded 9/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Wyard Township School

SITS# 32 FO

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 9/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



Address Carrington, ND 58421

Get Google Maps on your phone
Text the word "GMAPS" to 466453




Wyand Township School

9/20/2010

Kathy Wilner FO



South Side

Wyand Township School 9/20/2010 Kathy Wilner FO

West Side





North Side

Wyand Township School 9/20/2010 Kathy Wilner FO

East Side

