

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Longview Twp School #3

SITS# 32 FO 104

Map Quad Carrington SW
Map Quad

Site Name Longview Township School #3
Site Name

LTL T. 145 N., R. 67 W., Sec. 29 QQQ 8 of the QQ 8 of the Q 5
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q

Table with 1 column: Subsection. Rows: 1 = N1/2, 2 = E1/2, 3 = S1/2, 4 = W1/2, 5 = NE1/4, 6 = SE1/4, 7 = SW1/4, 8 = NW1/4

NAD 1983 UTM 5244696 Zone 14N
NAD 1983 UTM 482300

City:

Street Number:

Street Name: 4th St SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 05/25/2021

Reconnaissance Survey [checked] Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE, Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component Study Unit Verified Site CR Type
Component
Component

Recorded By: Kathy Wilner Date Recorded: 06/03/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data**

Field Code Longview Twp School #3

SITS# 32 FO 104

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1.0

Roof/Cornice Hip

Window Openings most with half covered

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 06/03/2021

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data****Field Code** Longview Twp School #3**SITS# 32 FO** 104**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

This feature is a one room prairie school sitting on a poured concrete foundation. The hip roof is covered with failing wood shakes with some metal capping. There is a red brick chimney on the north slope of the roof. The school measured 16 feet north to south by 28 feet east to west. The soffits were closed.

The siding begins with a rake board under the eaves on all side of the school. The remainder of the siding is 6 inch wood lap siding with metal corner trim. A water board finishes the bottom of the siding. There is an entry on the east side of the school. A concrete step leads into the entry. The exterior door is missing. A 4 panel wood door with two small windows near the top gives entry into a short hallway. There is a coat room to the left and fuel storage right. The walls and ceiling are lathe and plaster, much of the ceiling has fallen in. The floor is tongue and groove hard wood and it is buckling from weather. A bank of 5 double hung window openings run along the south wall. Two more double hung windows on the west wall are covered. All the windows were mostly covered as the building was used for grain storage. There is a blackboard on the north wall and indications that more blackboards were either side of the windows on the west wall. This school has a picture rail running along the walls about a foot from the ceiling. A wide trim board can be seen at the floor level. The school was wired for electricity.

2. Owner's Contact Information:

Kevin, Renne & Kelly Klein
6788 1st St SE
Carrington ND 58421

Recorded By: Kathy Wilner **Date Recorded:** 06/03/2021

NDCRS ARCHITECTURAL FORM**PAGE 4 – Site Description****Field Code** Longview Twp School #3**SITS# 32 FO** 1043. Site Area (ft²):

4. Description of Access and Site Setting:

This school building sits all by itself with farm fields all direction. Access to the school would be from Hwy 200 west of Carrington at 60th Ave SE. Turn left (south) and drive 7 miles to 4th St SE. Turn left again and drive east 1 1/2 miles to see the school on the south side of the road.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 06/03/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Longview Township School #3

5/25/2021

Kathy Wilner

FO

North Side





South Side

Longview Township School #3

5/25/2021

Kathy Wilner

FO

West Side





Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature