

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code _____

SITS# 32 GF 3818

Map Quad Orr

Site Name Agnes Township School

Map Quad _____

Site Name _____

LTL ___ T. 153 N., R. 55 W., Sec. 33 QQQ 8 of the QQ 8 of the Q 7

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

LTL ___ T. ___ N., R. ___ W., Sec. ___ QQQ ___ of the QQ ___ of the Q ___

NAD _____ UTM _____ Zone _____

NAD _____ UTM _____

City: _____

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

Street Number: _____

Street Name: _____

Urban Legal Description: _____

Total Number of Architectural Features: _____

Fieldwork Date: _____

Reconnaissance Survey

Intensive Survey _____

Project & Principal Investigator: _____

Contracting Firm or Agency Completing the Form:

SHSND

Additional Information:

Per communication with Kathy Wilner (8/16/2022) and aerial imagery, this school has been removed/destroyed.

SHSND USE

Component _____ Study Unit _____ Verified Site _____ CR Type _____

Component _____

Component _____

Recorded By: E. Scherr, SHSND Date Recorded: 08/17/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

UPDATE

Field Code _____

SITS# 32 GF 3818 _____

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date _____

Structural System _____

Original Owner's Ethnicity _____

Feature Type _____

Context _____

Primary Exterior _____

Secondary Exterior _____

Condition Destroyed

Plan Shape _____

Style _____

Architect/Builder _____

Foundation _____ Stories _____

Roof/Cornice _____

Window _____

Dating Method(s) _____

Miscellaneous Information Per comm. with Kathy Wilner & aerial imagery, school removed/destroyed ca. 2020-2021

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: E. Scherr, SHSND Date Recorded: 08/17/2022

NDCRS ARCHITECTURAL FORM

PAGE 3 – *Feature Data*

UPDATE

Field Code _____

SITS# 32 GF 3818 _____

Complete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

2. Owner's Contact Information:

Recorded By: _____ **E. Scherr, SHSND** _____ **Date Recorded:** _____ **08/17/2022** _____

NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description

UPDATE

Field Code _____

SITS# 32 GF 3818 _____

3. Site Area (ft²):

4. Description of Access and Site Setting:

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Recorded By: E. Scherr, SHSND **Date Recorded:** 08/17/2022

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ATTACHMENT SECTION

Field Code _____

SITS# 32 GF_ 3818 _____



Figure 1: 2020 aerial imagery of 32GF3818



Figure 2: 2021 aerial imagery of 32GF3818

Recorded By: E. Scherr, SHSND **Date Recorded:** 8/17/2022

NDCRS ARCHITECTURAL FORM

PAGE 1

Field Code Agnes Township School

SITS# 32 GF 3818

Map Quad Orr

Site Name Agnes Township School

Map Quad _____

Site Name _____

LTL T. 153 N., R. 55 W., Sec. 33 QQQ 8 of the QQ ~~X 8~~ of the Q ~~X 7~~

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5320646 Zone 14N

NAD 1983 UTM 594712

City: _____

Street Number: _____

Street Name: 42nd St

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 11/14/2020

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component 2 Study Unit 16 Verified Site _____ CR Type 2

Component _____

Component _____

Recorded By: Kathy Wilner Date Recorded: 11/20/2020

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Agnes Township SchoolSITS# 32 GFComplete one Page 2 for *each* architectural feature at the site.Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church schoolContext EducationPrimary Exterior Wood, Horizontal SidingSecondary Exterior Metal, SheetCondition GoodPlan Shape RectangularStyle Other Style

Architect/Builder _____

Foundation Unknown Stories 1Roof/Cornice GableWindow Double hung, glassDating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigationRecorded By: Kathy Wilner Date Recorded: 11/20/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data****Field Code** Agnes Township School**SITS# 32** GFComplete one Page 3 for *each* architectural feature at the site.**1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school moved to this location. Foundation is unknown as photos were taken from the road. The gable roof is covered with asphalt shingles. An overhang roof on the west side spans the entire end of the building and this is covered with metal sheeting. Located at the west end of the roof is a large bell tower. This peaked bell tower roof is also finished with asphalt shingles. There is a flag pole at the peak of the bell tower roof. Located in the tower is a bell which is surrounded by picket fence half walls. The chimney is gone and the soffits are closed.

A rake board begins the siding under the peak ends of the building. The remaining siding is 6 inch wood lap on most sides with 6 inch corner trim. On the south side of the building there is a sliding door for large equipment access. To the left of this door the exterior wall is covered metal siding. There is one double hung window on the south side to the right of the sliding door. The north side of the school had three double hung windows with the west most window covered with a sheet of plywood. The windows appear to have some glass. On the west wall, above the overhang, is a half moon window. There is an entry on the west under the overhang. The walls of the entry are covered with metal sheeting. There is a door on the south side of the entry and one small, fixed pane window on the west wall.

No information about the interior.

2. Owner's Contact Information:

William M Murphy
2491 42nd St
Larimore ND 58251

Recorded By: Kathy Wilner **Date Recorded:** 11/20/2020

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Agnes Township School**SITS#** 32 GF3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is located in a farm yard with buildings to the south and across the road to the west. Farm fields and trees are all directions. You find this school from McCanna going west on 23rd Ave. to 42nd street. Turn right and go north about 1 1/2 miles to see the farm site on the right. The farm is just south of County road 14 or 25th Avenue.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Photos from Wanda Weber.

Recorded By: Kathy Wilner **Date Recorded:** 11/20/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



North Side

Agnes Township School

11/14/2020

Kathy Wilner

GF

Bell tower with a bell





West and South Side

Agnes Township School

11/14/2020

Kathy Wilner

GF

