NDCRS 2009

200

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITE IDENTIFICATION		511 5# 32_0	
Field Code Bolkan School	· · · · · · · · · · · · · · · · · · ·		
Map Quad Map Quad	Site Name 		
LTLTWPR 58 SEC LTLTWPR RSEC SEC LTLTWPR SEC SEC LTLTWPR SEC SEC	QQQ	QQ QQ	Q 7 Q Q
UTM5250317N UTM572057E	ZONE <u>14N</u> NAD 1927	NAD 1983 🔟	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City: Cooperstown	· · · · · · · · · · · · · · · · · · ·		3 = S ¹ / ₂
Street Number: 90			$4 = W\frac{1}{2}$ 5 = NE ¹ / ₄
Street Name: 117th Ave SE			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW ¹ ⁄ ₄
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date:10/30/2015			
Reconnaissance Survey	sive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:	<u>.</u> .	<u> </u>	
SHSND USE Area of Significance Ecozone Area of Significance Ecozone	Verified Site Non-Site	. CR Type	2
Recorded By Kathy Wiln (First Name & Last Name)	er Date I	Recorded	2/10/2016 (mm/dd/year)

NDCRS	ARCH	ITECTURAL	SITE	FORM
	PAGE	2-Feature	Data	

Field Code Bolkan School		SITS# 32.	GG			
Complete one Page 2 fo	r each architectural fe	ature at the site.				
Architectural Feature #	1					
Construction Date	Feature Type9	Condition 6				
Feature Date 3	Context 7	Plan Shape	5			
Structural System 25	Primary Exterior 2	6 Style_Other	Style			
Original Owner's Ethnicity	Secondary Exterio	r Architect/Bu	ilder			
Other Information:						
Foundation Concrete		Stories1				
Roof/Comice Gable						
Window Double Hung, glass in	ntact					
Dating Method(s):	mate					
Feature Preservation Recommendation(s) (Check all that apply):						
Individual nomination						
Contributes to a poten						
No nomination potentia	al					
—Will not contribute to a district						
Potential districtfeature would be a contributing element if other properties constitute a district						
Thematic nomination potential						
Component of a historic site or landscape						
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility						
Historical associations require further investigation						
Recorded By	Kathy Wilner	Date Recorded	2/10/2016 (mm/dd/year)			

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Bolkan School

SITS# 32 GG

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room pairie school, sitting on concrete pillars, in a farm yard. It was moved to be used for storage and/or a shop. The building measures 32 feet east to west and 22 feet north to south. The roof is covered with asphalt shingles and the chimney, located at the east end, is a newer concrete chimney. A wide header runs under the eaves on all four sides as well as the bottom of the walls. Soffits are closed. Siding is 6 inch lap with 4 inch wood corner trim. The north wall has a large, sliding wood door. A slanted, concrete slab gives access to the building at the large door opening. On the south wall at the north end there is a 5 panel, wood entry door. We did not attempt to enter the school. There is one small, two pane window on the west side to the north of the large door. The east side has two side sliding windows with wood trim on three sides and a cornice at the top. On the north side are three more double hung windows with nice trim boards and a cornice at the top. All the glass in intact. The building is well kept. Looking in the window I observed that there are ceiling tiles with electric light fixtures and a blackboard ont he south wall. Electricity is present in the building.

Recorded By

(First Name & Last Name)

Date Recorded_

2/10/2016 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Bolkan School

SITS# 32 GG

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

David Lunde 90 117th Ave SE Cooperstown ND 58524

3. Access (to rural areas):

Highway 200 east of Cooperstown to 117th Ave NE, turn right and drive south 3 miles. The road will curve to the left and the Lunde farm is on the left side of the road as you get through curve.

4. Site Area (ft²):_____

5. Description of SETTING:

The school sits in a farm with with buildings to the north, west and south with an open field to the east. There are many trees around the farm site.

Recorded By Kathy Wilner Date Recorded 2/10/2016 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Bolkan School

SITS# 32_GG_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418


Recorded By Kathy Wilner Date Recorded 2/10/2016 (First Name & Last Name) (mm/dd/year)



South Side



12




North Side

Bakkan School

10/30/2015

Kathy Wilner GG

East Side



.