331

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITE IDENTIFICATION		3113# 32_\	
Field Code Pretty Rock School	Site Name	retty ROCK	School
Map Quad Pretty Rock Butte. Map Quad	Site Name	<u>U</u>	
LTL TWP R SEC _	8 QQQ _ QQQ _ QQQ _	QQ QQ	Q <u>5</u> Q Q
UTMN	ZONE . NAD 19	927 NAD 1983	Subsection: 1 = N½
City: Elgin ND 58533			2 = E½ 3 = S½
Street Number: 8501	· · · · · · · · · · · · · · · · · · ·	_	4 = W½ 5 = NE¼
Street Name: 70th Ave SW			6 = SE½ 7 = SW¼
Urban Legal Description:			8 = NW1/4
SITE DATA			
Total # Architectural Features: 1			
Fieldwork Date:10/31/2012			
Reconnaissance Survey Intensi	ve Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Ecozone Ecozone	Verified Site Non-Site —	2.	2
Recorded By Kathy Wilne (First Name & Last Name)	r	Date Recorded	1/20/2013 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Pretty Roo	ck School	SITS# 32	GT
Complete one Page 2 for each architectural feature at the site.			
Architectural Featur	e#		
Construction Date	Feature Type	9 Condition 7	.
Feature Date 4	. Context 7	Plan Shape	5
Structural System 25	Primary Exterior	18 Style Other	Style
Original Owner's Ethnic	ity Secondary Exter	rior Architect/Bu	uilder
Other Information:			
Foundation Poured Cor	ncrete	Stories1	_
Roof/Cornice Gable with	h a modified hip on the entry and	shed roof on the addition to	the north
Window Double Hung			
Dating Method(s): Cour	nty records and owner		
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation			
Recorded By	Kathy Wilner	Date Recorded _	1/20/2013 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Pretty Rock School SITS# 32_	GT
---	----

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school in excellent shape. The school measures 25 feet north to south and 16 feet east to west. The entry measures 12 1/2 feet east to west and 8 feet north to south. The school has newer asphalt shingles on the roof of the main boday of the school, the entry, the north shed as well as the cupola. A metal ridge cap runs the length of the school roof. The soffits are all enclosed. There is a brick chimney at the north end of the school. The siding is vinyl over wood lap siding. There is a newer door leading into the north shed. The shed had the furnace in it and was used for fuel storage. The first heat source was coal/wood, later changed to fuel oil and today there it's electric base boards. The concrete foundation is in fair shape with a poured concrete step leading to the entry. The entry door is a newer door as well. There are two double hung windows in the entry, one to the south and another to the west. The main body of the school has 3 double hung windows on both the east and west walls. The flooring in the school is tongue and groove covered with tile. Interior walls are covered with wall board and there is no wainscoating. There are lights in the school, both flourescent and globe lights. Blackboards are on the north wall with the chimney coming from the shed on the north and into the school before going up and out the roof. There school is furnished with desks, pictures, books, maps and etc. This school was the last to close in Grant County. According to school records this school closed in 1969.

Recorded By	Kathy Wilner	Date Recorded	1/20/2013	
	st Name & Last Name)		(mm/dd/year)	

SITS# 32 GT

Field Code Pretty Rock School

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Complete one Page 4 for the entire site.
Owner's Contact Information: Karen Witkowski
Elgin ND 58533
3. Access (to rural areas):
Highway 21 at Elgin ND to 68th Ave SW. Drive south 15 miles to see the school on your right.
4. Site Area (ft²):
5. Description of SETTING :
There are buttes in the area, the school sits in prairie grass with trees north, south and west with prairie to the east.
Recorded By Kathy Wilner Date Recorded 1/20/2013 (First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Pretty Rock Scho	ool	SITS# 32	GT
6. Summary of ALL Site	Features & Evalua	tion of Significance:	
7. References/Comments:			
Kathy Wilner 366 43rd Ave SE			
Bowdon ND 58418			
Pagardad By	Kathy Wilner	Date Recorded_	1/20/2013
Recorded By(First Name & La	ast Name)	Date Necolueu_	(mm/dd/year)



East Side

Pretty Rock School

10/31/2012

Kathy Wilner

 GT

South Side





West Side

Pretty Rock School

10/31/2012

Kathy Wilner

 GT

North Side



PRETTY ROCK DIRECTORY R-89-W T-131-N 70TH AVE SW 69TH AVE SW **68TH AVE SW** 66TH AVE SW 84TH ST SW 71ST AVE SW JOHN 72ND AVE SW RAFTESETH 3 2 6 5 DAVID BRODEHL 85TH ST SW 12 9 10 11 8 JORDON **EDGAR** HEUPEL ROHR 86TH ST SW DARYL HEUPEL DOYLE HEUPEL 14 13 16 15 17 18 87TH ST SW BARBARA PAYNE 20 21 22 23 19 KEITH PAYNE 88TH ST SW 27 26 25 29 28 30 89TH ST SW 33 35 36 32 34 31 90TH ST SW Pretty Rock School 15/31/2012 Kathy Wilner BU BT BS BR BQ BP BO BN BM BL AM AB AV AD AP BK AO AF AE AW AL BJ BI AS BV AA AR AX AH BH AN AG AK BG BF AU BE

BD AQ AI AT AC BC BB BA AJ BW BX AY AZ