

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

SITS# 32 GT 335

SITE IDENTIFICATION

Field Code Janesburg School #3

Site Name

Site Name

Map Quad Paradise Flats

Map Quad

| | | | | | | | | | | | | |
|-----|-----|------------|---|-----------|-----|-----------|-----|----------|----|----------|---|----------|
| LTL | TWP | <u>132</u> | R | <u>87</u> | SEC | <u>20</u> | QQQ | <u>8</u> | QQ | <u>5</u> | Q | <u>7</u> |
| LTL | TWP | | R | | SEC | | QQQ | | QQ | | Q | |
| LTL | TWP | | R | | SEC | | QQQ | | QQ | | Q | |
| LTL | TWP | | R | | SEC | | QQQ | | QQ | | Q | |

UTM _____ N
UTM _____ EZONE _____
NAD 1927 _____ NAD 1983 _____

Subsection:

- 1 = N $\frac{1}{2}$
- 2 = E $\frac{1}{2}$
- 3 = S $\frac{1}{2}$
- 4 = W $\frac{1}{2}$
- 5 = NE $\frac{1}{4}$
- 6 = SE $\frac{1}{4}$
- 7 = SW $\frac{1}{4}$
- 8 = NW $\frac{1}{4}$

City: Carson ND 58529Street Number: Approx 8131Street Name: 58th Ave SW

Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 1Fieldwork Date: 10/31/2012Reconnaissance Survey ☒

Intensive Survey _____

Project Title & Supervisor:

Country Schoolhouse Project

Report Title & Author(s):

Additional Information: _____

SHSND USE

Area of Significance 2
Area of Significance _____
Area of Significance _____Ecozone 23
Ecozone _____Verified Site _____
Non-Site _____CR Type 2Recorded By Kathy Wilner
(First Name & Last Name)Date Recorded 1/18/2013
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature DataField Code Janesburg School #3SITS# 32 GT**Complete one Page 2 for each architectural feature at the site.****Architectural Feature #** _____

Construction Date _____

Feature Type 9Condition 4Feature Date 4Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Poured Concrete partial basement Stories 1Roof/Cornice Gable, school and entryWindow Double hung, mostly goneDating Method(s): School Records/County history**Feature Preservation Recommendation(s) (Check all that apply):**☐ Individual nomination☐ Contributes to a potential district☐ No nomination potential☐ Will not contribute to a district☐ Potential district—feature would be a contributing element if other properties constitute a district☐ Thematic nomination potential☐ Component of a historic site or landscape☐ Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility☐ Historical associations require further investigationRecorded By Kathy Wilner
(First Name & Last Name)Date Recorded 1/18/2013
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code Janesburg School #3SITS# 32 GT**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room school built off the beaten path, it sits in a picturesque area with a river, buttes and many trees. Janesburg School District #32 started building schools in 1917 and this was the last school to close in 1963. The building is nearly square, measuring 18 feet east to west and 20 feet north to south with an entry measuring 16 feet north to south and 8 feet east to west. The roof on the main body of the school is gable with slopes to the east and west, mostly covered by shakes. The entry is located at the east side of the school and that gable roof slopes to the north and south, again shakes on the roof. Metal roof cap finish both roof lines. Remains of the chimney can be seen on the south slope of the entry roof. The siding is 6 inch wood lap over board lumber and much of the lap siding is gone on the west side. The corners are finished with 4 inch corner trim boards. There is a wide trim board running under finished soffits at the peaks of the roof as well as at the top of the lap siding. The concrete is crumbling under the school and some is falling into what appears to be a basement. An opening on the south side and another on the west may have provided access for fuel delivery. There were three window openings on the south side with remnants of the frames and again 5 window openings on the west side with little framing left. Two windows and a door on the east side with little left of the windows or door. No step remains for entry into the school. The flooring is tongue and groove hard wood and the walls have some plaster remaining on the lathe. Much of the ceiling plaster has fallen in as well as the walls. Chains for light fixtures hang from the ceiling indicating the presence of electricity. The blackboards were on the north wall. The entry is fairly large and there is a door from the main body of the school into a closet that was built into the entry. One door comes into the school from the entry and it is near the north wall. Only one actual door remains in the school and many of the panels are missing.

Recorded By Kathy Wilner Date Recorded 1/18/2013
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code Janesburg School #3SITS# 32 GT**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

June Brinkman
8215 58th Ave SW
Carson ND 58529

3. Access (to rural areas):

Just east of Carson ND on Hwy 21 turn south on 56th Ave SW and drive approx. 12 1/2 miles south to what would approximate 81 1/2 St. From the north turn right and drive west 2.2 miles to a T in the road. Turn right again and drive north on 58th Ave SW about 1/2 mile. Roads here are curvy and hilly. It is the Cannonball River Valley.

4. Site Area (ft²): _____5. Description of **SETTING**:

Beautiful area as the school sites near the Cannonball River to the south, many trees all around and it is surrounded by buttes. There is a farm site about 3/4 of a mile to the southwest.

Recorded By Kathy Wilner Date Recorded 1/18/2013
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Janesburg School #3

SITS# 32 GT

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/18/2013
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



East

Janesburg School #3

10/31/2012

Kathy Wilner

GT

North





South

Janesburg School #3

10/31/2012

Kathy Wilner

MO

West




JANESBURG PLAT

T-132-N

CODE: AK

R-87-W



SMALL TRACT OWNERS

34-A GENE & CAROLYN WELLS LE - 20 ACRES

Janesburg School #3 10/31/2012 Kathy Wilner GT

bing Maps

8215 58th Ave SW, Carson, ND 58529

Janesburg School #3
132-87-Sec. 20
Kathy Wilner 10/31/2012
GT

On the go? Use m.bing.com to find maps, directions, businesses, and more

