State Historical Society of North Dakota

NDCRS 2009

	NDCRS AR	CHITECT PAGI		FORM		
		PAG	- 1	SITS# 32_G	i V	339
SITE IDENTIFICATION						
Field Code Haigh Schoo	1	Site N	ame <u>Haig</u>	h school		
Map Quad Carly I	l	Site N	ame		(Construction) and a second	
LTL TWP LTL TWP LTL TWP LTL TWP	R	SEC <u>23</u> SEC <u></u> SEC <u></u> SEC <u></u>		QQ QQ	Q <u>6</u> Q Q Q	
UTM UTM		N	ZONE NAD 1927	NAD 1983]
City: Golva		and a state of the			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$	
Street Number:					$4 = W\frac{1}{2}$ 5 = NE ¹ / ₄	
Street Name: 52nd St SV	V				6 = SE¼ 7 = SW¼	
Urban Legal Description:					8 = NW¼	
SITE DATA						-
Total # Architectural Fe	atures:1	1				
Fieldwork Date:6	/22/2016					
Reconnaissance Survey	✓	Intensive Surv	ey			
Project Title & Superviso Country Schoolhouse Pr						
Report Title & Author(s):						
Additional Information:					an da su da su	-
SHSND USE Area of Significance Area of Significance	Ecozone		prified Site	_ CR Type	_2	
Recorded By	Kathy V e & Last Name)	Vilner	Date	Recorded	1/26/2017 (mm/dd/year)	-
(rust Man	a a Last Hallej				(mmuuyedr)	

NDCRS 2009

State Historical Society of North Dakota

NDCRS	ARCH	ITE	CTURA	L SITE	FORM
	PAGE	2	⁻ eature	e Data	

FAGE 2—Feature Data					
Field Code Haigh School		SITS# 32	GV		
Complete one Page 2 fe	or each architectural fe	ature at the site.			
Architectural Feature #	1				
Construction Date 1911	Feature Type	Condition <u>3</u>	ations and a		
Feature Date 3	Context_7	Plan Shape	5		
Structural System 25	Primary Exterior	Style_Other Style	Style		
Original Owner's Ethnicity	Secondary Exterio	or Architect/Bu	ilder		
Other Information: Foundation <u>Rocks</u> Roof/Cornice Gable					
Window Openings with a bit o			gandan kangan kangan di mangan pangan pangan kangan kangan kangan kangan kangan kangan kangan kangan kangan ka		
Dating Method(s): School His					
Feature Preservation Rec Individual nomination Contributes to a poter No nomination potent Will not contribute to a Potential district—feat Thematic nomination	ntial district ial a district ture would be a contributing e		constitute a district		
Component of a historic site or landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation					
Recorded By	Kathy Wilner	Date Recorded	1/26/2017 (mm/dd/year)		

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Haigh School

SITS# 32 GV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a rock foundation. The gable roof of the school and entry are almost void of wood shakes, the planking is failing and the roof is collapsing. No chimney and the soffits are closed. The building measures 32 feet north to south and 18 feet east to west.

There is a wide trim board on the exterior wall under the soffits on the peak ends of the roof. The remaining siding is 6 inch wood lap with 6 inch wood corner trim. The walls have no paint and the east wall is falling away from the school. Much of the siding is falling off as well. The doors are all gone, the windows as well. There were three windows on both the east and west walls, openings only. A window on the south wall of the entry show a bit of framing. There is a covered opening on the west wall of the entry that may have been a fuel door. The walls of the entry and school are covered with beadboard with wainscot. The ceiling is entirely gone. The floor is hardwood. This building is leaning heavily to the east.

This school was built in 1911 and continued to operate until 1940.

Recorded By Kathy Wilner Date Recorded 1/26/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Haigh School

SITS# 32_GV_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Lucille Moen 16950 52nd St SW Golva ND 58632

3. Access (to rural areas):

South of Golva on Highway 16, 5 miles to 52nd A=St SW (also called Marmath Rd), turn right and drive 1 1/2 miles west to see the school on the right up the hill.

4. Site Area (ft²):_____

5. Description of SETTING:

This school is sitting on a hill, prairie grass in the immediate school yard and a farm to the south, pasture and some crop land other directions.

Recorded By Kathy Wilner Date Recorded (First Name & Last Name)

1/26/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Haigh School

SITS# 32_GV_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/26/2017 (First Name & Last Name) (mm/dd/year)



West Side

Haigh School6/22/2016Kathy WilnerGV

.....





East Side

Haigh School	6/22/2016	Kathy Wilner	GV
--------------	-----------	--------------	----

South Side




7/7/2016

Bing Maps - Directions, trip planning, traffic cameras & more

bing maps

Notes	
Haigh School	
6/22/2016	
Kathy Wilner	
GV	





Feature