NDCRS 2009

NDCRS AR		L SITE FORM		
	PAGE 1	SITS# 32	GV	343
SITE IDENTIFICATION				
Field Code Burkey School	Site Name	Buckey Scho	0	
Map Quad_ <u><i>Golva_</i></u> Map Quad		······································	annahisen parking ang ang ang ang ang ang ang ang ang a	
LTL TWP137 R105 LTL TWP R LTL TWP R LTL TWP R	SEC QQQ SEC QQQ	8 QQ 8 QQ QQ QQ QQ	Q <u>5</u> Q Q Q	
UTM5172619 UTM583223	N ZON E NAD	e <u>13N</u> 1927 NAD 1983 _]
City: Golva		Newpublication	$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$	
Street Number: 16444			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$	
Street Name: 49th St SW			6 = SE¼ 7 = SW¼	
Urban Legal Description:			8 = NW¼	
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date: 6/22/2016				
Reconnaissance Survey 📈	Intensive Survey			
Project Title & Supervisor: Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				-
SHSND USE Area of Significance Ecozone Area of Significance Ecozone	Verified Si		ре _2	
Recorded By Kathy Kathy	Wilner	Date Recorded	1/28/2017	-
(First Name & Last Name)			(mm/dd/year)	

NDCRS 2009

NDCRS	ARCH	ITEC7	URAL	SITE	FORM
	PAGE	2-Fe	ature l	Data	

		e Data			
Field Code Burkey School		SITS# 32_	GV		
Complete one Page 2 fo	er each architectural fea	<u>ture</u> at the site.			
Architectural Feature #	1				
Construction Date	Feature Type9	Condition <u>6</u>			
Feature Date 3	Context 7	Plan Shape	5		
Structural System 25	Primary Exterior 26	Style <u>Other S</u>	ityle		
Original Owner's Ethnicity	Secondary Exterior	Architect/Bui	lder		
Other Information: Foundation_Poured concrete		Stories1			
Roof/Cornice_Gable					
Window_Double hung, glass					
Dating Method(s): School histo	bry				
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					
No nomination potential					
Will not contribute to a district					
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
d Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility					
Historical associations require further investigation					
Recorded By	Kathy Wilner st Name)	Date Recorded	1/28/2017 (mm/dd/year)		

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Burkey School

SITS# 32 GV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The gable roof is covered with ribbed metal sheeting. At the peak near the south end is a bell tower. The base of the bell tower is wood with lap siding to finish, the four corner posts hold a pyramidal roof, also covered with metal sheeting. There is a bell in the tower. The chimney is gone. The soffits are closed. The building measures 32 feet north to south and 20 feet east to west.

There is a wide trim board on the wall under the soffits on the peak ends. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. The entry to the school is located at the north side, a 4 panel wood door with a window at the top leads into the entry from the east side. There is one small window to the right of the entry door and another smaller, double hung one the west wall of the entry. Yet one more small windows it on the north wall. There is a 4 panel door, at a concrete step, that gives entry on the south side. A closed in area above the door and other straight line wood cuts make we wonder what this looked like originally. The interior walls of the schoool are composite wall tiles. The ceiling has 12 inch composite tiles. The hardwood floor is covered with linoleum, failing in places. At the north end of the main room there is a stage that spans the room, side to side. A 5 panel wood door opens into the entry at the west end of the north wall. A blackboard covers the east half of the north wall. The windows in the main room are 4 sets of two double hung, two over two, windows with glass intact. Light fixtures, in and out, suggest electricity.

This school was built in 1907 and operated until 1929, closed and then opened again to serve area families from 1944 to 1964.

Recorded By Kathy Wilner Date Recorded 1/28/2017 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Burkey School

SITS# 32_GV____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Mel Bosserman 16444 49th St SW Golva ND 58632

3. Access (to rural areas):

From Golva, Highway 16 south 2 miles to 49th St SW, turn left and drive east 3 1/2 miles to the large farm on the right.

4. Site Area (ft²): _____

5. Description of SETTING:

This building is located on a large farm that has feedlots and many building. It sits at the north edge of the property and there are tree to the north. All around the site are farm fields.

Recorded By Kathy Wilner Date Recorded 1/28/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Burkey School

SITS# 32_GV_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/28/2017
(First Name & Last Name) (mm/dd/year)



Burkey School

6/22/2016

Kathy Wilner GV



West Side



North Side

Burkey School

6/22/2016 Kathy Wilner GV

East Side



7/7/2016

Bing Maps - Directions, trip planning, traffic cameras & more

bing maps

Notes	
Burkey School	
6/22/2016	
Kathy Wilner	
GV	





Feature