NDCRS ARCHITECTURAL SITE FORM PAGE 1

*		SITS# 32 (3V3
SITE IDENTIFICATION			- Int
Field Code Strahon School	Site Name Stra	ahon School	
Map Quad Alpha Map Quad	Site Name		
LTL TWP R SE LTL TWP R SE	C QQQ	QQ	Q <u>6</u> Q Q
UTM 5176331 N UTM 591149 E	ZONE <u>13N</u> NAD 1927	NAD 1983 <u>/</u>	
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			4 = W½ 5 = NE¼
Street Name: 47th St SW			6 = SE½ 7 = SW¼
Urban Legal Description:			8 = NW1/4
SITE DATA			
Total # Architectural Features: 1	ndenninsprakterida		
Fieldwork Date: 6/22/2016			
Reconnaissance Survey Inte	ensive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Ecozone Area of Significance Ecozone	Verified Site	CR Туре	2
Recorded By Kathy Wil (First Name & Last Name)	ner Da	te Recorded	1/28/2017 (mm/dd/year)
(i nor isalie or raor isalie)			(mmuduyear)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Strahon School	Micro And Control of C	SITS# 32_	GV
Complete one Page 2 <u>for each architectural feature</u> at the site.			
Architectural Feature #1	_		
Construction Date1909	Feature Type9	Condition 5	without pyrioninately
Feature Date 3	Context 7	Plan Shape	5
Structural System 25	Primary Exterior 26	Style Other S	Style
Original Owner's Ethnicity	Secondary Exterior	Architect/Bu	ilder
Other Information:			
		Stories 1	
Roof/Cornice Gable, shed on the ad			
Window_Double hung,			
Dating Method(s): School history			
Feature Preservation Recommendation(s) (Check all that apply):			
Individual nomination			
——Contributes to a potential district			
No nomination potential			
——Will not contribute to a district			
Potential district—feature would be a contributing element if other properties constitute a district			
Thematic nomination potential			
——Component of a historic site or landscape			
d Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility			
Historical associations require further investigation			
Recorded By Kat		te Recorded	1/28/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Strahon School	 SITS# 32 GV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a wood foundation. It was moved to this farm site for use as a shop/garage. The gable roof of the school and the shed roof of the entry are covered with metal sheeting. The chimney is gone and the soffits are closed. There building measures 34 feet north to south and 20 feet east to west.

There is a wide trim board on the wall under the soffits on all the peak ends. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. On the south wall of the buildling the wall has been opened up and a side sliding entry door was installed to give access to the interior. The north entry has a 5 panel wood door leading into what was a coat room. There is a wall to cut the entry in half. There are two doors leading from the entry into the main body of the school, both 5 panel wood doors. On the west wall of the school there are three shuttered, double hung, two over two, windows with intact glass. Three more double hung, two over two, windows are on the east wall have glass intact and are not shuttered. The walls in the building are lathe and plaster with beadboard wainscot. The ceiling is lathe and plaster with much of it falling in. The floor is hardwood. Light fixtures and wiring suggest electricity.

This school was built in 1909 and operated in the same location until 1958.

Recorded By	Kathy Wilner	Date Recorded	1/28/2017
(First Name & Last Name)			(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Fleid Code Stranon School	5115# 32_	O A
Complete one Page 4 <u>for the entire site</u> .		
 Owner's Contact Information: Max Schmeling 4761 County Road 11 Sentinel Butte 58654 		
3. Access (to rural areas):		
From Golva, straight east on Pipeline Road or 47th S	St SW. Farm on the north side of	the road.
4. Site Area (ft²):		
5. Description of SETTING :		
This building sits in a farm yard and is used for a sho operation at the site.	pp. There are buildings, bins, tree	s and a cattle
Recorded By Kathy Wilner (First Name & Last Name)	Date Recorded	1/28/2017
(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Strahon Scho	ol	SITS# 32_	GV
6. Summary of ALL Site Features & Evaluation of Significance:			
7. References/Comments: Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
DOWGOTT ND 30410			
v			
Recorded By(First Name &	Kathy Wilner Last Name)	Date Recorded	1/28/2017 (mm/dd/year)



South Side

Strahon School 6/22/2016 Kathy Wilner GV

West Side



bing maps

Notes

Strahon School

6/22/2016

Kathy Wilner

GV





Réature