**NDCRS 2009** 

	NDCRS ARC		L SITE FOI	RM		
		PAGE 1	SIT	S# 32_G\	/	347
SITE IDENTIFICATION						
Field Code Alpha Scho	ol	Site Name	Alpha S	chool	ana ang kanang kanang kan	
Map Quad_ <u>Alpha_</u> Map Quad						
LTL TWP137 LTL TWP LTL TWP LTL TWP	R SE R SE	C QQ( C QQ(	2 QQ 2 QQ		Q <u>6</u> Q Q	
UTM 5168 UTM 5902	605N 265E	ZON	ie <u>13n     </u> ) 1927 <u> </u>	0 1983 📈	Subsection: $1 = N\frac{1}{2}$	]
City:					$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$	
Street Number:			und and any second and and any second		4 = W½ 5 = NE¼	
Street Name: 160th Ave	SW				6 = SE¼ 7 = SW¼	
Urban Legal Description	1:	a Rughan ann an Anna an Anna ann an Anna Anna			8 = NW1⁄4	
SITE DATA						
Total # Architectural Fe	eatures:1					
Fieldwork Date:	6/22/2016					
Reconnaissance Surve	y 🖌 Inte	ensive Survey				
Project Title & Supervis Country Schoolhouse F						
Report Title & Author(s)	:					
Additional Information:				-		
SHSND USE Area of Significance Area of Significance	Ecozone Ecozone	- Verified S - Non-Site		CR Type .	2	
Recorded By (First Na	Kathy Wil me & Last Name)	ner	Date Reco	I GGG	/27/2017 (mm/dd/year)	-

**NDCRS 2009** 

NDCRS	<b>ARCHITECTURAL SITE FORM</b>	
	PAGE 2— <i>Feature Data</i>	

Field Code Alpha School		SITS# 32_	GV		
Complete one Page 2 for ea	ch architectural feature	at the site.			
Architectural Feature #1					
Construction Date 1909	Feature Type <u>9</u>	Condition 5			
Feature Date 3	Context 7	Plan Shape 5	i		
Structural System 25	Primary Exterior 26	Style <u>Other St</u>	yle		
Original Owner's Ethnicity	Secondary Exterior	Architect/Build	der		
Other Information: Foundation <u>Concrete</u>		Stories1			
Roof/Cornice_Gable					
Window Double hung, little glass go	ne				
Dating Method(s): School history					
Feature Preservation Recomm	strict	at apply):			
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
recreates original site, orien	e choices)—a) relocation occ tation, landscape, & spatial re d) relocation has damaged e	lationships; c) compa			
Historical associations require further investigation					
Recorded By Kat (First Name & Last Nam		Date Recorded	1/27/2017 (mm/dd/year)		

**NDCRS 2009** 

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Alpha School

SITS# 32\_GV

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The gable roof of the school and half hip roof of the entry are are partially covered with wood shakes with metal capping and finials. The chimney is gone. The soffits are closed. The building measures 32 feet north to south and 20 feet east to west, inclusive of the entry.

There is a wide trim board at the top of the wall under the soffits on the peak ends. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. There is siding filling in two window openings on the west side with a third double hung window near the north end of the school. Two square windows are on the north wall of the entry, the east one open, no glass and the other covered. There is a bank of 6 double hung windows on the east side, much of the glass is gone. On the south side of the school is another 5 panel wood door. There is a broken 5 panel wood door giving entry to the school. The west half of the entry has another 5 panel wood door leading into more coatroom space. There are two doors going into the school from the entry, near the outer walls. The walls in the entry are wallboard, beginning to fall away, and the interior of the school has beadboard walls. There is wainscot in the entry and the school room. The ceiling is also beadboard. The floor is tongue and groove hardwood. There several blackboards in the school room, a long one on most of the west wall that corners around to half of the south wall. There are blackboards on the north wall of the school room, either side of the fuel oil stove. Light fixtures suggest electricity. This building is used for storage today.

This school has many dates associated with it, it was built in 1909 and operated in the original location until 1918, moved in 1919 and operated at that location until 1947. It was closed for a few years and reopened in 1953 until 1956. It was struck by lightning and burned in 1956.

Recorded By Kathy Wilner Date Recorded 1/27/2017
(First Name & Last Name) (mm/dd/year)

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Alpha School

SITS# 32\_GV\_\_\_\_\_

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

David Sherman

Sentinel Butte ND 58654

3. Access (to rural areas):

South of Golva 5 miles to 52nd St SW, turn left and drive east 8 miles to 160th Ave SW, turn left to drive north 1/2 mile to see the farm site on the west side of the road.

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of SETTING:

The setting is a mishmash of buildings, a house to the northeast, a corral with goats to the south, more buildings to the north and farm fields and pasture all directions.

Recorded By Kathy Wilner Date Recorded 1/27/2017 (First Name & Last Name) (mm/dd/year)

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Alpha School

SITS# 32\_GV\_\_\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418


Recorded By Kathy Wilner Date Recorded 1/27/2017
(First Name & Last Name) (mm/dd/year)



Alpha School6/22/2016Kathy WilnerGV




East Side



South Side

Alpha School6/22/2016Kathy WilnerGV




### 7/11/2016

### Bing Maps - Directions, trip planning, traffic cameras & more

**bing** maps

Notes			
Alpha Schoo	1		
6/22/2016			
Kathy Wilne			
GV			





Feature