

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Colegrove School #1

SITS# 32HT 80

Map Quad White Butte East

Site Name Colegrove School #1

Map Quad

Site Name Mauzey School #3

LTL T. 139 N., R. 93 W., Sec. 25 QQQ 8 of the QQ 8 of the Q 8

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD UTM 5161322 Zone 13N

NAD UTM 705534

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City:

Street Number:

Street Name: Highway 8

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 8/18/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component Study Unit Verified Site CR Type

Component

Component

Recorded By: Kathy Wilner Date Recorded: 10/20/2021

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Colegrove School

SITS# 32 HT 80

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Good

Plan Shape _____

Style Other Style

Architect/Builder _____

Foundation Brick Stories 1

Roof/Cornice Hip

Window Double hung, all covered

Dating Method(s) Previous documentation

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner

Date Recorded: 10/20/2021

**NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data****Field Code** Colegrove School #1**SITS#** 32 **HT** 80**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school on a brick foundation. The hip roof is covered with asphalt shingles. There is a red brick chimney at the northwest corner of the roof. There is a hip roofed dormer located on the south slant of the roof. An opening has been boarded up.

The siding begins with a rake board under the eaves on all side of the school. The remaining siding is 6 inch wood lap with interesting corner trim. The corner trim is decorative with 8 inch wide boards on the corners topped with fancy woodwork. There is a waterboard about two feet up from the bottom of the siding. The entry steps have fallen into a pile under the door opening. Most of the door is covered with plywood. There are covered windows to either side of the door. Two more double hung windows are located on the north side of the school, one covered and one uncovered. A bank of 4 covered windows is located on the east side of the school. I have no information about the interior as everything is locked. A light fixture over the entry door would indicate electricity was present at some point in the past.

2. Owner's Contact Information:

Terrence and Diane Friedt
5740 Hwy 8
Mott ND 58646

Recorded By: Kathy Wilner **Date Recorded:** 10/20/2021

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description

Field Code Colegrove School

SITS# 32 HT 80

3. Site Area (ft²):

4. Description of Access and Site Setting:

This building is found north of Mott on Highway 8 13 1/2 miles. Look for 58th St SW or St. Michael's Road. The school is at the SE corner of the intersection. Farm land runs all directions from the school.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 10/20/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



South Side

Colegrove School #1

8/18/2021

Kathy Wilner

HT

West Side





North Side

Colegrove School #1

8182021

Kathy Wilner

HT

East Side





Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature

NDCRS SITE FORM
ARCHITECTURAL SITES

Page 1

SITS # 32 HT 80

Field Code DOT 94-24 Site Name MAUZEY SCHOOL NO. 3

Field Code _____ Site Name Colgrave School #1

Map Quad WHITE BUTTE EAST

Map Quad _____

LTL	<input type="checkbox"/>	Twp	<u>13.6</u>	R	<u>9.3</u>	Sec	<u>25</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

1. N $\frac{1}{2}$
2. E $\frac{1}{2}$
3. S $\frac{1}{2}$
4. W $\frac{1}{2}$
5. NE $\frac{1}{4}$
6. SE $\frac{1}{4}$
7. SW $\frac{1}{4}$
8. NW $\frac{1}{4}$
9. C

City _____

Street # _____

Street # _____

Street Name _____

Street Name _____

of Features 1

<u>0.1</u> Feature #	<u>9</u> Feature Type	<u>6</u> Condition
_____ Construction Date	<u>7</u> Context *	
<u>3</u> Feature Date	<u>2.6</u> Primary Exterior *	<u>5</u> Plan Shape *
<u>2.5</u> Structural System **	_____ Style *	_____ Secondary Exterior
<u>0</u> Ethnic		_____ Architect/Builder
<u>11/16/94</u> Fieldwork Date		_____ Other Information

<u>3.2.8</u> Soil Association	<u>2.3</u> Ecozone	<u>2</u> Area Signf	_____ MS Number
_____ Soil Association	_____ Ecozone	_____ Area Signf	_____ MS Number
<u>2</u> CR Type	<u>1</u> Verified Site	_____ Non-Site	<u>2</u> E C F <u>3</u> T F
_____ State Registry	<u>3</u> National Register		

Coder Jeani L. Borchert

Date Coded 11.17.94

Reconnaissance Survey x

Intensive Survey _____

Manuscript/Report Title: Resurfacing Project Memo at DOT NH-5-008(015)045

Author(s): Jeani L. Borchert

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM

Page 1A

Field Code: DOT94-24

Feature Number 1

SITS #: 32HT

DESCRIPTIVE SECTION

FOUNDATION

Brick

STORIES

1

ROOF TYPE/CORNICE

Gable

WINDOW CONDITION

Original Windows & Openings Intact

DATING METHOD

Professional Judgement

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination
- 2) Contributes to a potential district
- 3) No nomination potential
- 4) Will not contribute to district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential
- 7) Component of historic site/landscape

- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY: The site is a rural school, with a somewhat unusual style, but, as with so many others, was probably built shortly after the turn of the century and used into the 60s. The school building is rectangular with two windows on both the north and south walls and a series of boarded-up windows on the east; there are no windows on the west wall. The entrance faces south. The wood frame and sided building sits on a high (ca. 1 yard) brick foundation. The building was equipped, subsequent to original use, with electricity. A weathered sign above the entrance says MAUZEY DIST. SCHOOL NO. 3, however, on topographic coverage it is referred to as Colgrove School No. 1. It seems likely the school district name changed through time, as the building did not appear to have been moved in from elsewhere.

While there may have been minor changes to the schoolhouse through modernization and maintenance, these changes do not affect the

integrity of the building. The site retains integrity of location, setting, design, feeling, materials, workmanship, and association. The site is not considered significant in terms of National Register Criteria B & D, but may be significant under Criteria A & C. The site is associated with a significant event (Criterion A), homesteading/rural expansion and rural education. However, the significance of these events needs to be expounded, and the property type inventoried to allow for an adequate evaluation of an individual property. The site is not eligible for its association with a significant person (Criterion B). While historic associations have not been explored, a rural schoolhouse would not likely be associated with an individual's period of significance. The site may be significant under Criterion C, however, this would need to be further investigated by an architectural historian. The site is not significant under Criterion D, as it has little potential to yield information of significance to area history.

Urban Legal Description: NA

NDCRS ARCHITECTURAL SITE FORM

Page 3

Field Code: DOT94-24

SITS #: 32HT

OWNER'S NAME, ADDRESS, PHONE #: Private, unknown.

PROJECT TITLE: Resurfacing Project, DOT Project # NH-5-008(015)045.

REPORT TITLE: Resurfacing Project Memo


SITE AREA (in square feet): 1200


ACCESS: From Mott, ND proceed north on Hwy. 8 for 13.5 miles. The schoolhouse sits east of the highway right-of-way.

DESCRIPTION: The site is a rural school with a somewhat unusual style, but was likely build shortly after the turn of the century and used into the 60s. The schoolhouse is adjacent to Highway 8, between Mott and Richardton. Campbell Butte is ca. 1.5 miles to the northwest.

SUMMARY OF SITE FEATURES AND EVALUATION OF SIGNIFICANCE: The school building is rectangular with entrance to the south and windows on all sides except the west. The wood frame and sided building sits on a high (ca. 1 yard) brick foundation.

The site may be significant under Criterion A for its association with rural expansion and education, and Criterion C, as it is a relatively intact schoolhouse. The site is not significant under Criteria B or D.





Topographic coverage of DOT94-24. USGS 7.5' Series, White Butte East Quad, 10 ft contour interval.

NDCRS SITE FORM

Photograph

Field# DOT94-24

Site # 32HT

Photo I.D. Code: 11/16/94 K1; NH-5-008(015)045.

Storage Location: ND Department of Transportation, Bismarck.



Photographic coverage of DOT94-24. Top photo taken facing north;
Bottom photo taken facing northwest.

NDCRS SITE FORM

Photograph

Field# DOT94-24

Site # 32HT

Photo I.D. Code: 11/16/94 K1; NH-5-008(015)045.

Storage Location: ND Department of Transportation, Bismarck.



Photographic coverage of DOT94-24. Top photo taken facing north, window detail; Bottom photo taken facing northwest, corner detail.

NDCRS SITE FORM

Photograph

Field# DOT94-24

Site # 32HT

Photo I.D. Code: 11/16/94 K1; NH-5-008(015)045.

Storage Location: ND Department of Transportation, Bismarck.



Photographic coverage of DOT94-24. Photo taken facing south.