÷

| NDCRS ARCHITECTURAL SITE FORM | | | | | | |
|---|---------------------------------------|------------|---|--|--|--|
| | PAGE 1 | SITS# 32_ | нт 186 | | | |
| SITE IDENTIFICATION | 11 | | 3 | | | |
| Field Code Odessa School #1 | Site Name | | # | | | |
| Map Quad Mark Butte SW Map Quad | Site Name | | | | | |
| LTLTWPRSEC | 17 000 8 000 000 000 000 | QQ | 0 <u>8</u> 0 0 0 | | | |
| UTMN UTME | ZONE NAD 1927 _ | NAD 1983 | - 1 11/2 | | | |
| City: Mott ND | <u> </u> | | $2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$ | | | |
| Street Number: Approx. 8280 | · · · · · · · · · · · · · · · · · · · | | 4 = W ¹ / ₂ 5 = NE ¹ / ₄ | | | |
| Street Name: 56th St SW | | | 6 = SE¼ 7 = SW¼ | | | |
| Urban Legal Description: | | | 8 = NW¼ | | | |
| SITE DATA | | | | | | |
| Total # Architectural Features:1 | | | | | | |
| Fieldwork Date: 10/30/2012 | | | | | | |
| Reconnaissance Survey <u></u> Intens | sive Survey | | | | | |
| Project Title & Supervisor: Country Schoolhouse Project | | | | | | |
| Report Title & Author(s): | | | | | | |
| Additional Information: | | | | | | |
| SHSND USE Area of Significance Area of Significance Area of Significance | Verified Site Non-Site | CR Typ | e <u>2</u> | | | |
| Recorded By Kathy Wilne (First Name & Last Name) | er Dat | e Recorded | 11/18/2012 (mm/dd/year) | | | |

ð

| NDCRS | ARCHITECTURAL SITE | FORM |
|-------|---------------------|------|
| | PAGE 2—Feature Data | |

| Field Code Odessa School #1 | | SITS# 32_ | <u>HT</u> | | |
|---|----------------------------|---------------------|----------------------------|--|--|
| Complete one Page 2 for each architectural feature at the site. | | | | | |
| Architectural Feature #1 | | | | | |
| Construction Date | Feature Type <u>9</u> | Condition 5 | | | |
| Feature Date | Context 7 | Plan Shape <u>-</u> | 5 | | |
| Structural System 25 | Primary Exterior <u>26</u> | Style Other S | tyle | | |
| Original Owner's Ethnicity | Secondary Exterior | Architect/Buil | der | | |
| Other Information: | | | | | |
| Foundation Poured concrete | | Stories1 | _ | | |
| Roof/Cornice_Gable | ····· | | | | |
| Window Replaced windows, with double | hung in the entry | | <u></u> | | |
| Dating Method(s): profession | estimate à | m | | | |
| Feature Preservation Recommendation(s) (Check all that apply): | | | | | |
| Individual nomination | | | | | |
| Contributes to a potential distric | rt | | | | |
| No nomination potential | | | | | |
| | | | | | |
| Potential district—feature would be a contributing element if other properties constitute a district | | | | | |
| Thematic nomination potential | | | | | |
| Component of a historic site or landscape | | | | | |
| Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility | | | | | |
| Historical associations require further investigation | | | | | |
| Recorded By Kathy (First Name & Last Name) | Wilner Dat | e Recorded | 11/18/2012 (mm/dd/year) | | |

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Odessa School #1

SITS# 32 HT

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school that measured 26 feet east and west and 22 feet north to south with a 8 foot by 10 foot entry on the east side. The school has shakes on the roof of the school and entry. There is a stove pipe chimney at the west end of the south facing slope of the roof. The building has a wide trim board under the overhang on the peaked ends and the soffit on the north and south side is open. 6 inch lap siding covers the school with 6 inch corner trim boards. The windows on the south wall were all replaced and they are much smaller slidin windows. There is one 6 pane, double hung, window in the entry that looks to be original. Two more multipane double hung windows are at either side of the entry on the east end of the building. Electrical wire can be see running to the east end of the school have wainscoting on lathe and plaster walls. Blackboards are on the north wall and either side of the chimney pip on the west wall. There is small furnace at the west end. The floor is narrow hardwood.

Recorded By Kathy Wilner Date Recorded 11/18/2012 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Odessa School #1

SITS# 32_HT_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Vesta Stelter LE

. 1

1

3. Access (to rural areas):

School is located at 56th St SW and 83rd Ave SW. The school is straight north of Burt on 83rd Ave SW 15 miles.

4. Site Area (ft²):

5. Description of SETTING:

There is a farm up the hill to the north, field and trees to the east, fields to the south and west. It is hilly and I would say it is down in a little glen.

Recorded By Kathy Wilner Date Recorded 11/18/2012
(First Name & Last Name) (mm/dd/year)

۰,

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Odessa School #1

SITS# 32_HT_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 11/18/2012 (First Name & Last Name) (mm/dd/year)



· · . •

(c) COPYRIGHT 2000 GREAT PLANS DIRECTORY SERVICE



East Side

Odessa School #110/30/2012Kathy WilnerHT

North Side





South Side

| Odessa School #1 | 10/30/2012 | Kathy Wilner | HT |
|------------------|------------|--------------|----|
| | | | |

West

