100

NDCRS ARCHITECTURAL SITE FORM PAGE 1

OUTS IDENTIFICATION					SITS# 32	HI /	0 /
SITE IDENTIFICATION			5	den	6.1.	1 41	
Field Code Solon School #1		Site Nar	ne <i></i> ne	<u> </u>	sineo	77	_
Map Quad Burt NW Map Quad		Oile Ivai					_
LTL TWP R LTL TWP R LTL TWP R LTL TWP R	SEC SEC SEC		<u>QQQ 6</u> QQQ QQQ QQQ		QQ <u>1</u> QQ QQ	Q 7 Q Q	- -
UTM			ZONE _ NAD 192	27	NAD 1983 _	Subse	½
City: Mott ND				_		$2 = E^{1/2}$ $3 = S^{1/2}$	2
Street Number: approx 8251						4 = W1 5 = NE	1/4
Street Name: 70th St SW				_		6 = SE 7 = SV	V1/4
Urban Legal Description:				_		8 = NV	V1⁄4
SITE DATA							
Total # Architectural Features:	1	_					
Fieldwork Date:10/30/2012	_						
Reconnaissance Survey	Intensive	e Surve	<i></i>				
Project Title & Supervisor: Country Schoolhouse Project							
Report Title & Author(s):							
Additional Information:							
SHSND USE Area of Significance Ecozone Area of Significance	23		fied Site . -Site		CR Ty	/pe	
Recorded By Kathy (First Name & Last Name)	Wilner			Date R	Recorded _	11/19/20 (mm/dd/y	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Solon School #1		SITS# 32 HT
Complete one Page 2 for each	architectural feature at th	e site.
Architectural Feature #1		
Construction Date	Feature Type9	Condition 7
Feature Date	Context 7	Plan Shape 5
Structural System 25	Primary Exterior 26 18	Style Other Style
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder
Other Information:		
Foundation Poured concrete	<u></u>	Stories 1
Roof/Cornice_Gable		
Window New fixed pane	A	
Dating Method(s): <u>Professiona</u>	estimate	
Feature Preservation Recommend	dation(s) (Check all that app	ly):
Individual nomination		
——Contributes to a potential distric	et	
No nomination potential		
Will not contribute to a district		
Potential district—feature would	be a contributing element if other	er properties constitute a district
Thematic nomination potential		
Component of a historic site or	landscape	
recreates original site, orientation	noices)—a) relocation occurred won, landscape, & spatial relations relocation has damaged eligibility	hips; c) compatible in context
Historical associations require f	urther investigation	
Recorded By Kathy	Wilner Date F	Recorded 11/19/2012

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Solon School #1		SITS# 32 HT

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school that was moved from Section to section 20 of Solon Township. The school has shakes on the roof with no indication of chimney placement. The siding was been replaced, it is some type of permanent siding, perhaps vinyl. Windows were all replaced with multipane, fixed windows, two on the east, two on the west and two at the south, either side of the door. There is a new metal door for entry at both the north and south ends of the school. There are railroad ties for steps at both doors. The inside of the school retains some of the originality with lather and plaster walls in the entry at the south end of the building and there is also wainscott on the walls. Entry to the main body of the school was through doors at either side of the entry wall and blackboard was on the school room side of the entry wall. More blackboards were located on the north wall. No wainscott on the walls in the main body of the school. I did not go into the school but could see through the west windows that the east windows were installed in two of four window opening. The other window openings are covered with the new siding. Perhaps there were four windows on the west wall as well. The flooring is tongue and groove hardwood. The building is being used for storage.

Recorded By	Kathy Wilner	Date Recorded	11/19/2012
•	me & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Solon Sch	ool #1	SITS# <u>32</u>	HI
Complete one Page	e 4 <u>for the entire site</u> .		
2. Owner's Contact Infor Esther Kuehn General Delivery Mott ND 58646	mation:		
3. Access (to rural areas	s):		
	rt drive north on 83rd Ave SW 2 Perhaps 1/4 mile off the road.	miles and you will see the sc	hool in a farm yard
4. Site Area (ft²):			
5. Description of SETTII	NG:		
	n yard with fenced in areas to the and open field south. Rolling cro		
Recorded By	Kathy Wilner	Date Recorded	11/19/2012 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Solon School	#1	SITS# 32	нт
6. Summary of ALL Si	te Features & Evaluation	on of Significance:	
7. References/Comments:			
Kathy Wilner 366 43rd Ave SE			
Bowdon ND 58418			
	17 (1)47		4414010040
Recorded By (First Name 8	Kathy Wilner	Date Recorded _	11/19/2012 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



South Side

Solon School #1

10/30/2012 Kathy Wilner

HT

East Side





West Side

Solon School #1 10/30/2012 Kathy Wilner HT

North Side



