NDCRS ARCHITECTURAL SITE FORM PAGE 1

| | PAGE 1 | SITS# 32_H | т /93 |
|--|------------------------------|----------------|--|
| SITE IDENTIFICATION Field Code Runkle School Map Quad Plum Butte Map Quad | Cita Mama | unkle Seheol | |
| LTL TWP R SE LTL TWP R SE | C 21 QQQ - QQQ - QQQ - QQQ - | QQ | Q _ <u>k</u> Q Q |
| UTM N UTM E | ZONE _ NAD 19 | 27 NAD 1983 | Subsection: 1 = N½ 2 = E½ |
| Urban Legal Description: | | | 3 = S½ 4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¼ |
| Total # Architectural Features: 1 Fieldwork Date: 10/30/2012 | | | |
| Project Title & Supervisor: Country Schoolhouse Project | ensive Survey | | |
| Report Title & Author(s): | | | |
| Additional Information: | | | |
| SHSND USE Area of Significance Area of Significance Ecozone Ecozone | Verified Site Non-Site | CR Type | 2 |
| Recorded By Kathy Wi | Iner | Date Recorded1 | 1/19/2012 (mm/dd/year) |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

| ield Code Runkie School | | SITS# 32 | SITS# 32_H1 | |
|---|---|---------------------------|----------------------------|--|
| Complete one Page 2 | for each architectural feat | ure at the site. | | |
| Architectural Feature # _ | 1 | | | |
| Construction Date | Feature Type9 | _ Condition 6 | | |
| Feature Date | Context 7 | Plan Shape | 5 | |
| Structural System 25 | Primary Exterior 26 | Style Other | Style | |
| Original Owner's Ethnicity | Secondary Exterior | Architect/Bu | uilder | |
| Other Information: | | | | |
| Foundation Concrete block b | pasement | Stories1 | _ | |
| Roof/Comice Gable with a sl | hed roof on the rear addition | | | |
| Window Multipane double hu | ung | | | |
| , | ecommendation(s) (Check al | 1 | | |
| Contributes to a pote | | | | |
| No nomination poter | | | | |
| Will not contribute to | | | | |
| | ature would be a contributing ele | ment if other properties | constitute a district | |
| Thematic nomination | - | proportion | | |
| ——Component of a hist | | | | |
| Moved (specify all a recreates original sit ——with neighboring stru | pplicable choices)—a) relocation ie, orientation, landscape, & spatiuctures; d) relocation has damagens require further investigation | al relationships; c) comp | | |
| Recorded By(First Name & | Kathy Wilner | Date Recorded | 11/19/2012 (mm/dd/year) | |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

| Field Code Runkle School | SITS# 32 <u>HT</u> |
|--------------------------|--------------------|
|--------------------------|--------------------|

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school. This building is located in Merrill Township. The roof of the main school building is covered with asphalt shingles. There is a newer looking brick chimney at the west end of the roof and also a vent pipe on the south slope of the roof nearer the east end of the builidng. An eaves trough is attached to the south side of the roof. The shed roof is covered with metal sheeting. The shed has a 5 horizontal panel door for entry and there is no door into the school from that shed. The shed is not on the basement. The siding is 6 inch lap with 6 inch corner trim boards. 5 large multipane, double hung windows run along the south wall of the school. Some of the glass has broken and is caught behind screening that covers all the windows. There is also a vent of some sort at the bottom of the siding at the southeast corner of the school. Also on the south side are windows for the basement, the east one is glass block and the other is simply covered. There is a concrete step/ porch at the east end of the building with a handrail to the south. There is a light fixture about the entry door and electrical wires on the northeast corner indicative of power. Two multipane, double hung windows are either side of the entry door, which is a solid, locked door. According to an area farmer the school had a full apartment in the basement along with two bathrooms and a shower. The teacher lived at the school. Just inside the door was a coat room to the left and the stairway immediatly to the right. The blackboards were on the north wall. He also spoke of attic space, apparently they stored stuff up there and he speculated about what might still be there.

| Recorded By | Kathy Wilner | _ Date Recorded | 11/19/2012 |
|-------------|--------------------------|-----------------|--------------|
| , | (First Name & Last Name) | | (mm/dd/vear) |

Field Code Runkle School

Recorded By (First Name & Last Name)

11/19/2012

(mm/dd/year)

Date Recorded

SITS# 32 HT

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

| Complete one Page 4 for the entire site. |
|--|
| 2. Owner's Contact Information: |
| Ron Swindler 2026 6th St W Mott ND 58656 |
| 3. Access (to rural areas): |
| From Mott 8 miles south on (I think) 93rd Ave SW 9 miles, go east on 82nd St SW about 5 miles the school will be on the left/north side of the road. |
| |
| 4. Site Area (ft²): |
| 5. Description of SETTING : |
| Trees to the north and west, a farm and field to the east and open field to the south. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

Kathy Wilner

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

| Field Code Runkle School SITS# 32 HT | | | нт |
|---|--------------------------|---------------|----------------------------|
| 6. Summary of ALL Site Features & Evaluation of Significance: | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 7. References/Comments: | | | |
| 366 43rd Ave SE | | | |
| Bowdon ND 58418 | | | |
| | | | |
| Recorded By(First Name & | Kathy Wilner | Date Recorded | 11/19/2012 (mm/dd/year) |
| Kathy Wilner 366 43rd Ave SE Bowdon ND 58418 | Kathy Wilner Last Name) | Date Recorded | 11/19/2012 (mm/dd/year) |

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



East Side

Runkle School

10/30/2012 Kathy Wilner HT

South Side





West Side

Runkle School

10/30/2012

Kathy Wilner

10/30/2012

North Side



T-132-N

MERRIL DIRECTORY

CODE: AU

R-92-W

