

# NDCRS ARCHITECTURAL SITE FORM

## PAGE 1

Field Code \_\_\_\_\_ SITS# 32 KD 110

### SITE IDENTIFICATION

Map Quad Tappen North Site Name Crystal Springs #2  
Map Quad \_\_\_\_\_ Site Name \_\_\_\_\_

LTL \_\_\_ TWP 139 R 71 SEC 10 QQQ 6 QQ 8 Q 8  
LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_  
LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_  
LTL \_\_\_ TWP \_\_\_\_\_ R \_\_\_\_\_ SEC \_\_\_\_\_ QQQ \_\_\_\_\_ QQ \_\_\_\_\_ Q \_\_\_\_\_

UTM 451679 N ZONE 14N  
UTM 5191656 E NAD 1927 \_\_\_ NAD 1983

Subsection:  
1 = N $\frac{1}{2}$   
2 = E $\frac{1}{2}$   
3 = S $\frac{1}{2}$   
4 = W $\frac{1}{2}$   
5 = NE $\frac{1}{4}$   
6 = SE $\frac{1}{4}$   
7 = SW $\frac{1}{4}$   
8 = NW $\frac{1}{4}$

City: Tappen

Street Number: \_\_\_\_\_

Street Name: 1st St NE

Urban Legal Description: \_\_\_\_\_

### SITE DATA

Total # Architectural Features: 1

Fieldwork Date: 12/17/2009

Reconnaissance Survey \_\_\_ Intensive Survey

Project Title & Supervisor:

Country Schoolhouse Project

Report Title & Author(s):

Additional Information: \_\_\_\_\_

### SHSND USE

Area of Significance 2 Ecozone 19 Verified Site 1 CR Type 2  
Area of Significance \_\_\_ Ecozone \_\_\_ Non-Site \_\_\_  
Area of Significance \_\_\_ Ecozone \_\_\_

Recorded By Lorna Meidinger Date Recorded 12/21/2009  
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 2—Feature Data**

Field Code \_\_\_\_\_ SITS# 32 KD \_\_\_\_\_  
 Complete one Page 2 for **each** architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_ Feature Type 9 Condition 7  
 Feature Date 3 Context 7 Plan Shape 5  
 Structural System 25 Primary Exterior 26 Style Other Style  
 Original Owner's Ethnicity \_\_\_\_\_ Secondary Exterior 27 Architect/Builder \_\_\_\_\_

Other Information:

Foundation concrete Stories 1  
 Window double hung  
 Roof/Cornice hip  
 Dating Method(s): professional estimate

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Lorna Meidinger Date Recorded 12/21/2009  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM**  
**PAGE 3—Feature Data**Field Code \_\_\_\_\_ SITS# 32 KD \_\_\_\_\_**1. Feature Description, Integrity, Eligibility:**

There is an entrance on either end of the south side of Crystal Springs #2 with five large 3 over 6 double hung windows between them. The western entrance no longer has steps and the cantilevers hood is deteriorating. The eastern entrance has concrete steps with metal poles as handrails. On the east and west ends, there are two breaks in the concrete foundation. Haadem and Iszler thought those were from when the building was moved and then they were filled in with concrete block. The building never had a basement. The east and west ends also have two windows, smaller than the front windows. Chimney block extends up from near the hip on the east end. The north side would not photograph but was a solid wall broken only by one window near the west end that appeared to be the same size as the windows on the ends.

Crystal Springs #2 was originally located on the northwest corner of 40th St SE and 46th Ave SE before being moved onto the Tappen school grounds in 1959. In Tappen it became known as the white elephant and operated as a music room. Due to loss of integrity in some materials, location, and setting, this building is not individually eligible for the National Register of Historic Places but may contribute to a district with the other school buildings on the property.

Recorded By Lorna Meidinger Date Recorded 12/21/2009  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 4—SITE DESCRIPTION**

Field Code \_\_\_\_\_

SITS# 32   KD   \_\_\_\_\_

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

4. Site Area (ft<sup>2</sup>): \_\_\_\_\_

5. Site Description:

Crystal Springs #2 is now located on the Tappen school grounds with other school buildings to the east and a basketball court to the north. There are many trees around the building so that it cannot be easily seen on aerial photos.

Recorded By           Lorna Meidinger            
(First Name & Last Name)

Date Recorded           12/21/2009            
(mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM  
PAGE 5—SITE DESCRIPTION**

Field Code \_\_\_\_\_ SITS# 32 KD \_\_\_\_\_

**6. Summary of All Site Features & Evaluation of Site Significance:**


The other school features on this site were not evaluated so a determination of eligibility for the site is not possible at this time.

**7. References/Comments:**

Norlyn Iszler, personal interview, 17 December 2009.  
Tilman Haadem, personal interview, 17 December 2009.

Recorded By Lorna Meidinger Date Recorded 12/21/2009  
(First Name & Last Name) (mm/dd/year)

*Instructions to complete a digital version of this form:* (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



# NDCRS SITE FORM ATTACHMENTS SECTION

Field Code

SITS# 32 KD



Feature 1 south southwest ↑

Feature 1 east ↓



Recorded By Lorna Meidinger  
(First Name & Last Name)

Date Recorded 12/21/2009  
(mm/dd/year)

Field Code

SITS# 32 KD



Feature 1 west

Recorded By Lorna Meidinger  
(First Name & Last Name)

Date Recorded 12/21/2009  
(mm/dd/year)