

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

SITS# 32 KD 129

SITE IDENTIFICATION

Field Code Clear Lake School

Site Name Clear Lake School
Site Name _____

Map Quad Robinson
Map Quad _____

LTL	TWP	<u>142</u>	R	<u>73</u>	SEC	<u>12</u>	QQQ	<u>5</u>	QQ	<u>5</u>	Q	<u>6</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
UTM _____ E NAD 1927 _____ NAD 1983 _____

City: Robinson ND 58478

Street Number: 1955

Street Name: 30th Ave SE

Urban Legal Description: _____

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

SITE DATA

Total # *Architectural* Features: 1

Fieldwork Date: 8/31/2012

Reconnaissance Survey Intensive Survey

Project Title & Supervisor:
Country Schoolhouse Project

Report Title & Author(s): _____

Additional Information: _____

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>19</u>	Verified Site _____	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By Kathy Wilner Date Recorded 10/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code Clear Lake SchoolSITS# 32 KD

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9Condition 6Feature Date 2Context 7Plan Shape 5Structural System 25Primary Exterior 26Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation Concrete Blocks Stories 1Roof/Cornice GableWindow Double hungDating Method(s): professional estimate

Feature Preservation Recommendation(s) (Check all that apply):

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigation

Recorded By Kathy Wilner Date Recorded 10/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**Field Code Clear Lake SchoolSITS# 32 KD**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

The feature is a wood framed one room school sitting on concrete blocks in a farm yard. Shakes cover the roof of the main body of the school as well as the entry/porch. There is a metal ridge cap running the length of both roofs. Under the peak of the roof of the main body of the school and the entry are 8 inch trim boards. The school is sided with 6 inch lap with 4 inch corner trim boards. There is a light fixture to the left of the door that indicates electricity. There are two windows to the west and 4 windows along the south wall. There are also two windows in the entry, one to the south and another on the east end next to the door. On the north wall of the entry is a boarded up opening that was most likely the fuel door. There wood porch has fallen away from the building. This school, measuring 30 feet east to west, 18 feet north to south with the entry measuring 8 feet by 10 feet, was moved to this farm from the original location 1 mile west. It was used for a house by the owner's sister some years ago.

Stepping into the school there is a small room to the right that is finished inside with board lumber and no paint. Looks like the fuel room. Doors going into the entry and the main body of the school are 5 panel wood doors, could be original. The walls in the entry are lathe and plaster above wainscoting, all painted bluish green. All the door and window trim was painted white at some point and all the paint is crackling. The trim for those windows is wide and ornate across the tops. Inside the main body of the school the floor is hardwood tongue and groove and the walls appear to be a mixture of lathe and plaster and wallboard. The north and south walls of both the entry and main body curve in to the ceiling. There is wainscoting in the main body of the school. Blackboards used to be on the north wall.

Schools in this area closed 1957/1958.

Recorded By Kathy Wilner Date Recorded 10/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code Clear Lake SchoolSITS# 32 KD**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

August Olson
1955 30th Ave SE
Robinson Nd 58478

3. Access (to rural areas):

Highway 36 east of Robinson ND to 30th Ave. Go south approx. 1/2 mile to see a farm on the west side of the road. The school is in the farm yard.

4. Site Area (ft²): _____5. Description of **SETTING**:

This school sits in a farm yard with buildings south, west and north. There is a pasture to the east and mostly pasture all around the farm yard.

Recorded By Kathy Wilner Date Recorded 10/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Clear Lake School

SITS# 32 KD

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 10/19/2012
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



Clear Lake Township School

East Side

8/31/2012

Kathy Wilner KD

Clear Lake Township School

North Side

8/31/2012

Kathy Wilner KD





Clear Lake Township School West Side 8/31/2012 Kathy Wilner KD

Clear Lake Township School South Side 8/31/2012 Kathy Wilner KD



MAP OF CLEAR LAKE




TOWNSHIP: 142 N

MIDLAND ATLAS CO. INC. COPYRIGHT 1999

RANGE: 73 W

CODE: CL



Feature

HERB