State Historical Society of North Dakota

NDCRS 2020

NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Moch Farm	SITS# 32KD 173
Man Quad	Site Name Baker Township School #1 4 #2.
Map Quad Map Quad	Site Name Second any Class standard School
LTLT. <u>137</u> N., R. <u>74</u> W., Sec. <u>32</u>	
LTL TN., RW., Sec	QQQ of the QQ of the Q $1 = N\frac{1}{2}$
LTL TN., RW., Sec	
LTL TN., RW., Sec	QQQ of the QQ of the Q 3 = 5½
NAD	7 4 = W½
NAD <u>1983</u> UTM 5165151 NAD UTM 419698	_ Zone _ <u>14N</u> 5 = NE%
NADUTM419090	
City:	7 = SW¼
	8 = NW¼
Street Number:	
54th Ct CE	
Street Name:54th St SE	
Linhan Logal Department	
Urban Legal Description:	
Total Number of Architectural Features:	3
Fieldwork Date:10/7/2021	
Reconnaissance Survey _	Intensive Survey
Project & Principal Investigator:	
Country School House Project	
Kathy Wilner	
366 43rd Ave SE	
Bowdon ND 58418	
547	
Contracting Firm or Agency Completing the F	orm:
Additional Information:	
SHSND USE	
Component 2 Study Unit 19	Verified Site CR Type
Component	
Component	

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Baker Township School #1	SITS# 32 KD
Complete one Page 2 for <i>each</i> architectural feature at the site.	
Architectural Feature #	
Construction Date	
Feature Date <u>1900-1915</u>	
Structural System Wood Frame	
Original Owner's Ethnicity	
Feature Type <u>9 - School; Church school</u>	
Context <u>Education</u>	
Primary Exterior <u>Wood, Horizontal Siding</u>	
Secondary Exterior <u>Metal, Sheet</u>	
Condition <u>Poor</u>	
Plan Shape <u>Rectangular</u>	
Style <u>Other Style</u>	
Architect/Builder	
	1
Roof/Cornice Gable	
Window Replacements	
Dating Method(s)	ũ –
Miscellaneous Information	
Feature Preservation Recommendation(s) (Check all that apply):	
Individual nomination	
Contributes to a potential district	
No nomination potential	
Will not contribute to a district	
Potential district—feature would be a contributing element if or	ther properties constitute a district
Thematic nomination potential	
Component of a historic site or landscape	
Moved (specify all applicable choices)—a) relocation occurred site, orientation, landscape, and spatial relationships; c) comp relocation has damaged eligibility	
Historical associations require further investigation	

Recorded By: Ka

Kathy Wilner

Date Recorded: ____

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Baker Township School #1

SITS# 32 KD

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. This building was moved to the farm for use as a shop. The gable roof is covered with metal sheeting. There is a concrete chimney at the west end at the peak of the roof. The soffits are closed.

The siding is 6 inch wood lap with 4 inch wood corner trim. The addition to the north has both wood (east and west sides) and horizontal metal siding (north). The north wall of the school was removed to expand into the shed addition. There is a new door leading into the school from the east side. There are also two overhead doors, one installed into the school and the other into the shed addition. There are four replacement windows on the south side and one on the west side in the shed addition. The floor is concrete. The ceiling and walls are mostly covered with beadboard. Electricity is present.

2. Owner's Contact Information: Tracy & Paula Moch 1993 54th St SE Braddock ND 58524

Recorded By:

Kathy Wilner

NDCRS ARCHITECTURAL FORM

Field Code Moch Farm	
Field Code Moch Farm # 2	SITS# 32 KD
Complete one Page 2 for each architectural feature at the site.	
Architectural Feature #	
Construction Date	
Feature Date <u>1900-1915</u>	
Structural System <u>Wood Frame</u>	
Original Owner's Ethnicity	
Feature Type <u>9 - School; Church school</u>	
Context Education	
Primary Exterior <u>Wood, Horizontal Siding</u>	
Secondary Exterior	
ConditionFair	
Plan Shape <u>Rectangular</u>	
Style Other Style	
Architect/Builder	
	<u> </u>
Roof/Cornice Hip	
Window Removed	
Dating Method(s)	
Miscellaneous Information	
Feature Preservation Recommendation(s) (Check all that apply)	
Individual nomination	
Contributes to a potential district	
No nomination potential	
Will not contribute to a district	
Potential district—feature would be a contributing element if of	other properties constitute a district
Thematic nomination potential	
Component of a historic site or landscape	
Moved (specify all applicable choices) —a) relocation occurre site, orientation, landscape, and spatial relationships; c) com relocation has damaged eligibility	

____Historical associations require further investigation

Recorded By:	Kathy Wilner	Date Recorded:	11/9/2021

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Moch Farm School #2

SITS# 32 KD

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room school on a concrete foundation. The building was moved to this location for use as a garage. The hip roof is covered with failing asphalt shingles with some metal capping. There is not chimney. Soffits are closed.

The siding begins with a rake board under the eaves on all four sides of the school. The remainder of the siding is 6 inch wood lap with 6 inch corner trim that has a decorative top just under the rake board. The west side has a door that has a multipane window on the top and wood bottom. On the south side there are three overhead doors that lead into the building. The floor is concrete. The interior walls and ceiing were all stripped to the studs. The rafters show that the ceiling was angled. There is electricity.

2. Owner's Contact Information: Tracy & Paula Moch 1993 54th St SE Braddock ND 58524

Recorded By:

Kathy Wilner

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Secondary Class Standart School	SITS# 32	2 KD	
Complete one Page 2 for each architectural feature at the site			
Architectural Feature #3			
Construction Date			
Feature Date <u>1900-1915</u>			
Structural System Wood Frame			
Original Owner's Ethnicity			
Feature Type <u>9 - School; Church school</u>			
Context Education			
Primary Exterior <u>Wood, Horizontal Siding</u>			
Secondary Exterior			
Condition			
Plan Shape <u>Rectangular</u>			
Style Other Style			
Architect/Builder			
	ries 1		
Roof/Cornice Hip			
Window Double hung, glass			
Dating Method(s)			
Miscellaneous Information			
Feature Preservation Recommendation(s) (Check all that app	ly):		
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing element	t if other prope	rties constitute a distr	ict
Thematic nomination potential			
Component of a historic site or landscape			
Moved (specify all applicable choices)—a) relocation occu site, orientation, landscape, and spatial relationships; c) co relocation has damaged eligibility			
Historical associations require further investigation			

11/9/2021

Date Recorded: _____

Kathy Wilner

Recorded By: ___

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Secondary Class Standart School

SITS# 32 KD

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room praire school on a concrete foundation. It was moved to this location for storage. The hip roof is covered with wood shakes with some metal capping. The chimney is gone. The soffits are closed.

The siding begins with a rake board under the eaves on all four sides. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. There is an 5 panel wood entry door on the east side near the south end. Also on the east side is a bank of 6 double hung windows with intact glass. A single similar window is on the south side and three more are located on the north side. All the windows have decorative cornices. The inside walls of the school are all beadboard. There is also wainscot. The beadboard ceiling is angled. The west wall shows where a blackboard was and there is a small blackboard to the west of the three north windows. The floor is hardwood. Walls near the entry end have been removed. Electricity was present at some point.

2. Owner's Contact Information: Tracy & Paula Moch 1993 54th St SE Braddock ND 58524

Recorded By:

Kathy Wilner

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Moch Farm

SITS# 32 KD

3. Site Area (ft²):

4. Description of Access and Site Setting:

Reach this school from Braddock. Go north on 16th Ave SE 1/2 mile, east on 58th ST SE 1 mile and north on 17th ave SE4 miles to 54h St SE. Turn right and go 1/2 mile to see the farm on your left. Is it the second driveway to the old farm. The school sits in a farm yard with buildings all around. Beyond that farm fields in all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By: _

Kathy Wilner



Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature

Featurez



West Side

Featurel

Baker Township School #1

10/7/2021

Kathy Wilner





North Side



East Side


Baker Township School #110/7/2021Kathy WilnerKD


South Side






South Side





North Side






Secondary Class Standard School


10/7/2021

Kathy Wilner

EM KD



South Side



North Side

Secondary Class Standard School

10/7/2021

Kathy Wilner



West Side