NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCHITECTURAL	SITE	FORM		
PAGE 1				117
		SITS# 32.	LO	117

SITE IDENTIFICATION	
Field Code Highlander #1	Site Name Highlander #1
Map Quad_ <u>/AIKaline_LaKe_SW</u> Map Quad	Site Name
LTL TWP R R SEC LTL TWP R SEC LTL TWP R SEC LTL TWP R SEC	
UTM <u>5151525</u> N UTM <u>451967</u> E	ZONE <u>14N</u> NAD 1927 NAD 1983 ✓ Subsection: 1 = N½ 2 = E½
City: Napoleon	
Street Number: <u>3191</u>	5 = NE¼
Street Name: Hwy 34	6 = SE¼ 7 = SW¼
Urban Legal Description:	8 = NW1⁄4
SITE DATA	
Total # Architectural Features:1	
Fieldwork Date: 5/11/2017	
Reconnaissance Survey 🖌 Inter	sive Survey
Project Title & Supervisor: Country Schoolhouse Project	
Report Title & Author(s):	
Additional Information:	
SHSND USE Area of Significance Area of Significance Area of Significance	Verified Site CR Type Non-Site
Recorded By Kathy Wiln (First Name & Last Name)	er Date Recorded5/15/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data			
Field Code Highlander #1		SITS# 32_LO	
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature #1			
Construction Date	Feature Type9	Condition 4	

Construction Date	Feature Type <u>9</u>	Condition 4	
Feature Date 2	Context 7	Plan Shape <u>5</u>	
Structural System 25	Primary Exterior <u>26</u>	Style Other Style	
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder	
Other Information:			
Foundation Concrete Blocks		_ Stories1	
Roof/Cornice_Hip			
Window Double hung, some glass gone			

Dating Method	(s):	Estimate	
---------------	------	----------	--

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- -Contributes to a potential district
- ___No nomination potential
- -Potential district—feature would be a contributing element if other properties constitute a district
- ____Thematic nomination potential
- ____Component of a historic site or landscape
- Moved (specify all applicable choices)-a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context ____with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	5/15/2017	
(First N	ame & Last Name)		(mm/dd/year)	

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Highlander #1

SITS# 32_LO____

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a large, one room prairie school, moved to the current farmsite location for use as a storage building. The hip roof roof has remnants of asphalt shinglesand wood shakes on wood sheathing. The roof has many holes. There is a dormer on the east slope of the roof. There are pieces of metal capping along some of the seams. The chimney is gone. The soffits were closed with beadboard and there are holes here as well.

The siding is wood lap and horizontal lumber with no paint left. A wide trim board runs along all four walls at both the top and bottom with a waterboard at the bottom trim board. The soffits were closed with beadboard and some of that has fallen away. The corner trim is metal capping. Both the north and south side have 4 double hung windows. It looks like some of the framing remains and little or no glass. The framing that remains looks to be aluminum and is perhaps outer windows added at a later date. There is an opening near the east end of the south wall that is covered, another window. A corresponding window on the north side is also covered. The east wall has two covered windows. There is a door opening on the east wall. The floor is tongue and groove and there are holes. The walls are covered with a mixture of lathe and plaster and wallboard. The ceiling was lathe and plaster and most of the plaster is now lying on the floor. The floor is tongue and groove hardwood. There are no blackboards in the building. No wainscot and no evidence of electricity.

Recorded By Kathy Wilner Date Recorded 5/15/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Highlander #1

SITS# 32_LO_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Joey and Carol Brunner 3791 Hwy 34 Napolean ND 58561

3. Access (to rural areas):

This school is located on a farm site on the north side of Highway 34, 7 miles east of Napolean.

4. Site Area (ft²): _____

5. Description of SETTING:

The school sits at the south side of a farm yard with bins, house and other storage buildings to the north and northwest, there is a slough to the east and farm land all directions.

Recorded By Kathy Wilner Date Recorded 5/15/2017 (First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code_Highlander #1

SITS# 32_LO_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 5/15/2017
(First Name & Last Name) (mm/dd/year)




West Side

Highlander School #1

5/11/2017 Kathy Wilner LO

South Side




East Side

Highlander School #1

5/11/2017

Kathy Wilner

LO



North Side

5/12/2017

bing maps

Notes Highlander School #1 (previous name Dixon Twsp. School)

5/11/2017

Kathy Wilner

LO

34

Feature

b bing

@ 2017 Microsoft Corporation @ 2017 HERE

17 HERE

39th Ave SE

