

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 XME 733

SITE IDENTIFICATION

Field Code 32-ME-A006a Site Name Schoolhouse
Site Name _____

Map Quad Golden Valley NW
Map Quad _____

LTL	TWP	<u>145</u>	R	<u>90</u>	SEC	<u>8</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>7</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM 5252679 N ZONE 13N
UTM 712513 E NAD 1927 _____ NAD 1983

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: n/a
Street Number: n/a
Street Name: n/a
Urban Legal Description: n/a

SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 11/22/2013

Reconnaissance Survey Intensive Survey _____

Project Title & Supervisor:
Project Title: Antelope Valley Station to Naset 345-kV Transmission Project.
Project Supervisor: Dr. Kimball Banks, Metcalf Archaeology, Bismarck, ND

Report Title & Author(s):
"Visual and Historic Sensitivity Analysis For the Proposed Antelope Valley Station (AVS) to Naset 345-kV Transmission Project," by Joe Trnka, AICP, CEP; Omaha, NE

Additional Information: _____

SHSND USE				
Area of Significance	<u>2</u>	Ecozone	<u>23</u>	Verified Site
Area of Significance	_____	Ecozone	_____	Non-Site
Area of Significance	_____			CR Type
				<u>2</u>

Recorded By Joe Trnka, AICP, CEP Date Recorded 4/24/2013
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code 32-ME-A006a

SITS# 32

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date 1910

Feature Type 9

Condition 5

Feature Date 3

Context 7

Plan Shape 3

Structural System 25

Primary Exterior 26

Style Utilitarian

Original Owner's Ethnicity

Secondary Exterior

Architect/Builder

Other Information: building appears to have been partially secured against the weather.

Foundation concrete

Stories 1

Roof/Cornice end gable with projecting front gable ell entrance

Window boarded - not visible

Dating Method(s): estimated

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By Joe Trnka, AICP, CEP
(First Name & Last Name)

Date Recorded 4/24/2013
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



Location 32-ME-A006a, looking northeast. This unoccupied schoolhouse is not in use but it is fenced and posted. Some steps have been taken to secure it, such as boarding the windows.

