NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITS# 32 MH H5(a

SITE IDENTIFICATION			0110# 52 <u></u>	
Field Code Balfour Township School				
Map Quad Map Quad		me		
LTL TWP52 R77 LTL TWP R LTL TWP R LTL TWP R	SEC SEC SEC SEC	QQQ <u>6</u> QQQ QQQ QQQ	QQ <u>6</u> QQ QQ QQ	Q 6 Q Q
UTM UTM	N E	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$
City:				$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:				$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 40th St NE				6 = SE¼ 7 = SW¼
Urban Legal Description:				8 = NW ¹ ⁄ ₄
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date: 6/6/2016				
Reconnaissance Survey 🖌	Intensive Surve	У		
Project Title & Supervisor: Country Schoolhouse Project				
Report Title & Author(s):				•
Additional Information:				
SHSND USE Area of Significance Z Ecozone Area of Significance Ecozone Z		fied Site	. CR Type	2
Recorded ByKathy (First Name & Last Name)	Wilner	Date F	Recorded	1/19/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS	ARCHITECTURAL SITE FORM
	PAGE 2— <i>Feature Data</i>

Field Code Balfour Township School		SITS# 32_MH		
Complete one Page 2 <u>for <i>each</i> architectural feature</u> at the site.				
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition <u>6</u>		
Feature Date 2	Context 7	Plan Shape <u>5</u>		
Structural System <u>25</u>	Primary Exterior <u>26</u>	Style <u>Other Style</u>		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information: Foundation <u>Poured concrete and rocks</u>		Stories <u>1</u>		
Roof/Cornice_Gable		5		
Window_Double hung, some glass		5		
Dating Method(s): Estimated				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context _____with neighboring structures; d) relocation has damaged eligibility

____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	1/19/2017
(First Na	me & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Balfour Township School

SITS# 32 MH

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairies school sitting on a poured concrete foundation. The gable roof is covered with wood shakes with many missing. There is a red and yellow brick chimney neart the north end of the peak of the roof. Some of the bricks have fallen away. The soffist are closed. There is a flag pole at the south end of the gable roof. This building measures 30 feet north to south and 20 feet east to west.

There is a wide trim board under the soffits at the peak ends of both the north and south walls. All other siding is 6 inch wood lap with 6 inch wood corner trim. The south wall shows lack of paint in a shape that would lead me to believe there was an entry there at some point. A large set of concrete steps leads to a 5 panel wood door. To either side of the entry door there are double hung windows, 2 over 2, with some glass on the right window and shutter over the left window. On the east wall there is a window opening that have been sided over. On the west side there are six double hung, 2 over 2, windows with little glass and 4 are shuttered. Conduit on the south wall as well as a light fixture over the door suggest electricity. The interior walls are beadboard as is the ceiling. Some of the ceiling is falling in. No blackboards hang in the school but is evident that they were on the east wall and 1/2 of the north wall. There is a door on the north wall. A furnace sits at the north end of the school room. Wainscot is on the lower third of the wall. The floor is narrow hard wood.

Recorded By

Kathy Wilner (First Name & Last Name)

_ Date Recorded _

1/19/2017 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Balfour Township School

SITS# 32_MH_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

From Drake drive to the northwest on Highway 52 to Highway 14 going north, drive nearly 5 miles north to 40th St NE. Turn left and drive one mile west to 5th Ave NE intersection ad you will see the school on your right.

4. Site Area (ft²):_____

5. Description of SETTING:

There is an abandoned farm site to the east and farmland all other directions.

Recorded By Kathy Wilner Date Recorded 1/19/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Balfour Township School

SITS# 32 MH

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner

____ Date Recorded

1/19/2017 (mm/dd/year)



South Side

Balfour Township School

6/16/2016

Kathy Wilner

MH

East Side





West Side

Balfour Township School6/16/2016Kathy WilnerMH



7/6/2016

bing maps

Notes	
Balfour Township School	
6/16/2016	
Kathy Wilner	
МН	



Feature

