

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Boe School #2

SITS# 32 ML 309

Map Quad Turtle Lake

Site Name Boe School #2

Map Quad \_\_\_\_\_

Site Name \_\_\_\_\_

LTL    T. 148 N., R. 80 W., Sec. 29 QQQ 6 of the QQ 6 of the Q 6

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5273987 Zone 14N

NAD 1983 UTM 358148

City: \_\_\_\_\_

Street Number: \_\_\_\_\_

Street Name: 13th St NW

Urban Legal Description: \_\_\_\_\_

Total Number of **Architectural** Features: 1

Fieldwork Date: 05/31/2021

Reconnaissance Survey

Intensive Survey \_\_\_\_\_

Project & Principal Investigator:

Country School House Project

Kathy Wilner

366 43rd Ave SE, Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component \_\_\_\_\_ Study Unit \_\_\_\_\_ Verified Site \_\_\_\_\_ CR Type \_\_\_\_\_

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Kathy Wilner Date Recorded: 06/06/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM  
PAGE 2 – Feature Data

UPDATE

Field Code Boe School #2

SITS# 32 ML 309

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date \_\_\_\_\_

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood Frame

Secondary Exterior \_\_\_\_\_

Condition Fair

Plan Shape Rectangular

Style Other Style

Architect/Builder \_\_\_\_\_

Foundation Poured concrete Stories 1.0

Roof/Cornice Gable

Window Double hung openings, no glass

Dating Method(s) Estimate

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 06/06/2021

**NDCRS ARCHITECTURAL FORM****PAGE 3 – Feature Data****UPDATE****Field Code** Boe School #2**SITS# 32 ML 309****Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

This feature is a one room prairie school on a poured concrete foundation. The gable roof of the school and entry are covered with failing asphalt shingles over wood shakes. There is a flag pole at the peak of the entry roof on the east end of the school. The chimney is gone and the soffits are closed. The large part of the school measures 30 feet east to west and 18 feet north to south. The entry measures 10 feet by 10 feet.

The siding begins with with a rake board under the eaves at the peak ends of the school. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. There is an entry on the east end of the school with broken 5 panel wood door leading inside on the south wall. A single concrete step leads to the door. One double hung window opening faces east and another north in the entry. There is an opening with no door leading from the entry into the main body of the school. An old oil burning stove with stove pipe leading into the chimney space sits in the northeast corner of the school room. There are two sets of three double hung window openings with some framing intact and no glass. The walls are covered with wall board. The ceiling has wallboard panels over beadboard. Light fixtures indicate the prescence of electricity at some point. One blackboard covers the entire west wall of the school room and two more smaller blackboards are located on the north wall. The floor is tongue and groove hardwood.

**2. Owner's Contact Information:**

Marjean Boe  
1259 17th Ave NW  
Turtle Lake 58575

**Recorded By:** Kathy Wilner **Date Recorded:** 06/06/2021

**NDCRS ARCHITECTURAL FORM****PAGE 4 – Site Description****UPDATE****Field Code** Boe School #2**SITS# 32 ML 309**3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

This school sits on a corner with fields in all directions. A slough sits to the northeast. To reach this school you go north of Turtle Lake ND about 6 1/2 miles to 13th St NW. Turn right (east) and go 1 mile to see the school on the north side of the road.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

**Recorded By:** Kathy Wilner **Date Recorded:** 06/06/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Boe School #2

5/31/2021

Kathy Wilner

ML

North Side





South  
Side

Boe School #2

5/31/2021

Kathy Wilner

ML

West Side





Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2021

Feature