	UPDATE NOCRS SITE FORM ARCHITECTURAL SITES Page 1
	SITS # 32 M.L. 8.9.1.
	Field Code Site Name Site Name
÷	Map Quad <u>CASHRURN</u> , S.W., 1. N. 1. N. 1. N. 2. Et
	LTL Q. Twp
	City
	Street # Street #
	Street Name Street Name
	# of Features 4
	Soil Association 1.9 Ecozone 2 Area Signf MS Number
	Soil Association Ecozone Area Signf MS Number CR Type Verified Site ONon-Site SECF STF State Registry INational Register
	Coder J. Ferry Date Coded 3/6/07
	Reconnaissance Survey Intensive Survey
	Manuscript/Report Title: Falkirk: A Cultural Resource Inventory of 20,000 Heres County North Author(s): John Boughton Lyneik Peterson, Scottwagers Daton

SITE DATA

•

.

SIISND USE FEATURE DATA

NDCRS ARCHITECTURAL SITE FORM

Page 2

Field Code: None

.

×.

SITS #: 32ML891

DESCRIPTIVE SECTION

FOUNDATION: Concrete

STORIES: 1

ROOF TYPE/CORNICE: Gable

WINDOW CONDITION: Most windows and openings intact DATING METHOD(S): Estimate

PRESERVATION RECOMMENDATION (Check all that apply):

- 1) _____Individual nomination
 2) _____Contributes to a potential district
- 3) X No nomination potential 4) Will not contribute to district
- 5)_____Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) _____Thematic nomination potential
 7) _____Component of historic site/landscape
- 8)_____Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) Relocation occurred within historic period. B) Recreates original site, orientation, landscape and spatial relationships. C) Compatible in context with neighboring structures. D) Relocation has damaged eligibility.
- 10)____Request comparative study of neighboring properties
- 11)____Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY:

Feature 1 is the old Conkling school building, identified as a large maintenance building with garage and office/shop areas in 1997. The school building was located in Conkling School District #12, and was named after Rosco Conkling. There is a small, enclosed entryway on the north elevation and two large overhead doors and a panel door on the south elevation. The building has an irregular plan, and inside are pew-style benches. The south end area is 32×36 feet, and the rest of the building area is 25×64 feet. The two areas have separate gable roofs.

The entire building is on a raised concrete foundation. Siding is horizontal wood clapboards. The interior walls in the shop area are covered with fiberboard. The roof is covered with composition rolled roofing. Most of the windows have been broken out but those that remain area double hung, 8/8.

NDCRS ARCHITECTURAL SITE FORM

Page 6

Field Code: None

SITS #: 32ML891

FEATURE DATA

OWNER'S NAME, ADDRESS, PHONE #:

PROJECT TITLE:

REPORT TITLE: Results of Class II and Class III Cultural Resource Inventories for Upgrades to Telecommunication Lines: The Washburn Exchange

SITE AREA: 285,000 sq ft

ACCESS: From North Dakota 200 on the north side of Washburn, go west on County Road 17 for 7.5 miles. Turn north and go 1.75 miles. Turn west and go 2.7 miles. The site is on the south side of the road.

DESCRIPTION: Three standing buildings, a windmill, three concrete foundations, a concrete cistern, a depression, and five recent granary foundations were recorded at this site. The site is abandoned.

Historic Information: Records on file at the McLean County Register of Deeds Office indicates that Alfred Svenson received a patent from the United States for land containing the site on May 5, 1904. Anna Kristina Johanson, Svenson's sister, inherited the property on February 21, 1921. Johanson sold the property to George Swanson on November 30, 1925. Victor Leidholm purchased the land on January 14, 1926. Today Lloyd Leidholm owns the property.

References:

Boughton, John, Lynelle Peterson, and Scott Wagers2006 Falkirk: A Cultural Resource Inventory of 20,000 Acres in McLean County, North Dakota.

Rottwell, Sarah J., Thomas K. Larson, and Dori M. Penny

1997 Results of Class II and Class III Cultural Resource Inventories for Upgrades to Telecommunication Lines: The Washburn Exchange

NDCRS ARCHITECTURAL SITE FORM

Page 7

Field Code: None

.

SITS #: 32ML891

SUMMARY OF SITE FEATURES AND EVALUATION OF SIGNIFICANCE:

Feature 1 – Conkling school building

Feature 2 – Garage

Feature 3 – House


Feature 4 – Windmill

Statement of Integrity:

The site is reflective of a mid-1900s farm outbuildings and schoolhouse; however, six of the structures associated with the property have either been torn down or have been removed from the property. The overall condition and integrity of the site is poor to fair.

Statement of Significance:


The site is recommended not eligible for listing to the National Register of Historic Places (NRHP) under any of the established criteria. Most of the structures associated with the property have either been torn down or removed from the property. The four standing structures (Features 1-4) are unable to reflect any historic association and is recommended not eligible under Criterion A. The site is not associated with any person of local, regional, state, or national importance, and is recommended not eligible under Criterion B. The features at the site are not representative of a unique architectural style or method of construction and recommended not eligible under Criterion C. The site would not likely provide further information through archaeological investigation of the historic features and is recommended not eligible under Criterion D. No further work is recommended at the site.



RECORDED BY: Scott Wagers

.

DATE: <u>5/28/06</u>



NDCRS ARCHEOLOGICAL SITE FORM

Page 1

Field Code: 32ML891

SITS #:



Feature 1, view to the northwest



Feature 1, view to the southeast

NDCRS SITE FORM ARCHITECTURAL SITES Page 1

	SITS # <u>32</u> <u>ML</u> <u>.89</u>					
	Field Code <u>9.7.0.9./.9.c6.</u> Site Name <u></u> Field Code <u>6.7.0.9./.9.c6.</u> Site Name <u></u>					
SITE DATA	Map Quad Unitside 1. Ni Map Quad					
FEATURE DATA	# of reducts					
SHSND USE	3.55 Soil Association 23 Ecozone Area Signf MS Number Soil Association Ecozone Area Signf MS Number CR Type Verified Site Non-Site E C F T F State Registry National Register					
	Coder $T.$ LarsonDate Coded $11-20-97$ Reconnaissance SurveyIntensive SurveyXManuscript/Report Title:SeePage 3					
	Author(s):					

FIELD MANUAL NDCRS ARCHITECTURAL SITE FORM

Makery

Cannery

Creamery

Cenetery

City Hall

Courthouse

Orphanage

Pest House

Bulk Plant

Gas Well

19.

20.

21.

22.

23.

24.

25.

26.

27.

28.

29.

20.

22.

23.

24.

25.

26.

27.

28.

29.

30.

31.

32.

33.

34.

35.

STYLES

Pole

Stone, Cut

Tarpaper

Wood Frame

Prairie Style

Shingle Style

Other Style

Romanesque

Ranch/Split Level

Stick Style Ethnic/Vernacular

Hipped Roof Box

Modular/Lustron

Plain Residential

Other Contemporary

Mansardic/Second Empire

Transitional Brick Comm.

Queen Anne

Thatch

Other

Stone, Uncut

Stucco/Plaster

Wood, Horizontal siding

Wood, Shingles/Shakes

Wood, Vertical Siding

AGRICUL TURE 13 Dam 17 Tower Animal Shelter/Stable 62 Barn FOOD SERVICE 92 Blacksmith Shop Un Chicken Coop/Poultry House Clinic, Animal/Veterinarian Corral/Enclosure/Pen 66 28 Bar/Tavern 24 43 24 70 Experiment Station 90 5 Farm, Dairy 25 Farm/Farmstead 1 97 Granary/Bin 61 97 Greenhouse/Nursery Matchery, Anm'1/Bird/Fish Ice/Smoke House/Root Cellar 91 25 12 26 67 90 64 Line Shack 27 Pump/Well 14 23 Pump House/Well House 25 Ranch FUNERARY Silo/Silage Pit 61 29 13 Stock Dam 78 Gravestone Storage Building 15 78 Hemortal Storage Yard Summer Kitchen 16 78 Honument 69 Hortuary 29 Well/Pump 14 GOVERNMENT Windmill 17 37 Work shop 71 30 ARTS AND ENTERTAINMENT 84 75 Auditorium/Lecture Hall 59 Cinema/Theater 74 32 75 Lecture Hall **9**9 Museum/Gallery 59 75 **Opera House** 86 73 Studio, Photo/Art/Sculpt 86 Theater 33 COMMERCE 32 Bank/S & L/Financial General Store 76 18 68 10 47 Shopping Center/Mall Store, Retail 10 47 32 68 Trading Post 73 15 Warehouse COMMUNICATIONS 98 HEALTH CARE Newspaper Office Print Shop 87 87 33 Radar Facility 85 86 Radio/TV Station 93 INDUSTRIAL Teleph./Telegr. Facil. Tower, Radio/TV/Microwave 89 11 17 88 EDUCATION 34 Business College 19 31 75 Class Room/Lecture Hall 36 19 College/University 38 70 Laboratory 34 20 Library 96 School 96 Seminary 19 14 Trade/Technical School 19 11 ENGINEERING 36 Bridge/Trestle 71 37 22 Canal/Flume 37 STRUCTURAL SYSTEM/EXTERIOR MATERIALS Metal, Sheet Perma Stone Asbestos Siding/Shingle 16. 1. Asphalt Siding/Shingles 17. 2. Brick Plastic, Vinyl 3. 18.

4.

5.

6.

7.

8.

9

10.

11.

12.

13.

14.

15.

1.

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.

16.

17.

Clay Tile

Earth/Clay

Log

Earthen Brick

Glass, Block

Metal, Frame

Bungalow

Craftsman

Glass, Pigmented

Composition Board

Concrete, Poured/Cast

Metal, Decorative Wood

Metal, Horizontal Siding

American Foursquare/Cube

Beaux Arts/Neo Classical

Boomtown/False Front

International Style

Early Brick Commercial

Mission/Pueblo Revival

Elizabethan/Tudor Revival

Eastern European Revivals

Chicago School Colonial Revival

Gothic Revival

Gabled Front

Italianate

Moderne

Concrete Block

FEATURE TYPE 35 96 58 96 14 011 We11 Bottling Plant Brewery/Distillery Butcher Shop 96 Pipeline 71 Repair Shop 16 38 Tipple 15 Warehouse Dairy Processing Plant Frozen Food Locker 92 Grocery Store 78 Fountain **Meat Packing Plant** Garden 78 Mill, Grist/Flour Honument 78 Restaurant/Cafe/Mess Hall 39 Park Sugar Refinery MILITARY Armory 79 60 79 Bast Ion 79 Blockhouse 44 B 79 Border Crossing Station 8 79 Correctional Facility/Jail 79 Pall1sade 39 Customs House 59 Fire Station 79 Government Office 51 Indigent Home 68 48 Tra11 Police Station 45 Post Office/Mail Station 45 Bustness Sanitary Land Fill Sewage Treatment Plant Sheriff's Office 80 80 Lodge 45 Township Hall 46 Water Treatment Plant 80 Social RECREATION/SPORTS 33 Clinic/Dispensary 52 Hospital/Infirmary 32 Nursing Home 57 51 Brick Manufacturing Plant 91 Concrete Hfg. Plant Elect. Gener. Facility Elect. Transform. Facility 51 52 51 Elect. Transmiss. Facility 51 Resort Factory/Foundry Gas Storage 95 Gas Transmission Facility **R**1 RELIGIOUS Grain Storage, Commercial 54 Lumber Yard 9 Mill, Saw Mill, Stamp/Minerals Refin. 53 0. Unknown 1. African 2. American Indian

Hine/Quarry Oil Refinery Oil Tank Battery Oil Transmission Facility Storage Yard Welding/Blacksmith Shop LANDSCAPE ARCHITECTURE Battlefield Camp Site, Temporary Camp, Semi-Permanent Defensive Works Fort/Cantonment/Post/Base Missile Site Parade Ground Post/Base Exchange(PX/BX) Powder Magazine Rifle Range Sutler's Store OFFICE/HEADQUARTERS Administrative Fraternal/Sororal Organizational Professional Arcade/Lasino Billiard Parlor/Pool Hall Boat Landing, Recreational Camp/Picnic Grounds Fairgrounds Grandstand Play ground Recreation Area, Indoor Recreation Area, Outdoor **Rodeo Grounds** Sport Facility, Indoor Sport Facility, Outdoor Chapel, Non-Denom. Church School Church, Catholic 63 Church, Protestant

42 Convent/Monastery Fellowship Hall Parsonage/Hanse/Rectory 30 40 19 Seminary Shrine 78 64 Synagog RESIDENTIAL Barracks/Dorm./Bunk House 47 Bernacks/Joint/Sunk Hou Dwelling, Double Unit Dwelling, Multiple Unit Dwelling, Single Unit Garage/Carriage House Hotel/Motel/Inn 41 40 65 64 65 Nobile Home 50 Pr1vy TRANSPORTATION 49 Airport/Airfield/Land, Fld. Boat Landing, Com'c'l/Steam Boat Landing, Recreational Bridge/Trestle 56 67 21 Depot/Terminal Ferry 82 82 Ford Freight Yard Fuel Station/Yard, 72 88 Coal/Wood, etc. Gasoline Station 55 Hanger Highway 48 62 Livery 70 Loading Platform Railroad Grade/Tracks 48 56 Rest Stop 48 Road 73 Roundhouse Siding 48 78 Signal 62 Stable Spur Stage Station 48 56 Switch Yard 72 Trail 48 **B**2 Tunne l 83 Turn-around MISCELL ANE DUS Accident/Disaster Site 10 Dump 73 Spring Spring House 77 17 Tower Town/City/Colony/Settlement 99 Other

,

11

FFATURE DATE CONTEXTS Aviation 1. pre-1880 1 2. 1880-1900 2 Bridges 3. 1900-1915 3 Colonization 4. 1915-1930 Commerce 3. Arabic 5. 1930-1945 Communications 5 4. British/Celtic 6. post-1945 Depression, the Great 6 5. Canadian Education 6. Czech/Bohemian CONDITION 8 Energy Development 7. Danish Destroyed 1. 9 Entertainment 8. Dutch Inundated 2. 10 Exploration 9. Finnish Very Poor Farming, Bonanza Farming, Dairy 3. 11 10. French Poor 4. 12 11. German/Austrian/Swiss 5. Fair 13 Farming 12. German-Russian 6. Good 14 Fur Trade 13. Greek Government, National Government, Territorial Government, State Excellent 7. 15 14. Icelandic 16 15. Irish 16. Italian Government, Local 18 PLAN SHAPE 17. Jewish 19 Horticulture Not Applicable 0. 19. Norwegian Industrial Development 20 Circular 20. Oriental 1. Irrigation and Conservation Richardsonian Romanesque 21. Polish 21 2. Irregular Military 22 22. Russian 3. L-Shaped Mining, Coal 23 Polygonal 23. Scot 4. 24 Petroleum 24. Spanish 5. Rectangular 25 Railroads Square 25. Swedish 6. Ranching, Open Range 26 T-Shaped 26. Ukrainian 7. 27 Ranching, Fee Simple U-Shaped 8. Religion Roads, Trails, and Highways Rural Settlement 27. Other 28 ۹. Other 29 30 Urban Settlement 31 32 Water Navigation

NDCRS ARCHITECTURAL SITE FURM page 1A

Field Code 970919c-6

Feature Number /

SITS # 32 ML

DESCRIPTIVE SECTION

FOUNDATION	STORIES	ROOF TYPE/CORNICE	
Concrata	1	996/2	
WINDOW CONDITION		DATING METHOD	
most windows + openings	intact	estimule	
PRESERVATION RECOMMENDATION	(check all t	that apply):	

Individual Nomination 2) Contributes to a potential district No nomination potential 4) Will not contribute to district 1) 3) Potential district not known at this time: feature would be a contributing 5) element if neighboring properties constitute a district Thematic nomination potential 7) Component of historic site/landscape 6) ******* ****** ******************** Feature has an important physical, spatial, functional, historic or 8) architectural relationship to the site/complex/farmstead Moved: A) relocation occurred within historic period. B) recreates original 9) site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility. Request comparative study of neighboring properties 10) Historical associations require further investigation 11)

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature 1 is a large maintenance building with a garage area at the south end and office/shop space at the north end. There is a small enclosed entryway on the north elevation and two large overhead garage doors and a panel door on the south elevation. The building has an irregular plan. The garage area is 32-by-36 feet. The main shop area is 15-by-64 feet. There is a 12-by-12 addition on the east side of the shop area. The garage and shop areas have separate gable roofs. The addition to the shop area has a shed roof.

The entire building is on a raised concrete foundation. Siding is horizontal wood clapboards. The interior walls in the shop area are covered with fiber board. The roof is covered with composition rolled roofing. Most of the windows have been broken out but those that remain are double hung, 8/8.

This building has an unusual appearance to be part of a farmstead. Although it cannot be substantiated by the historic records consulted, it seems likely that Feature 1 was moved to its present location from some commercial or industrial area. Likely candidates for the building's original location are nearby coal mines and the Garrison Dam construction site near Riverdale (Feature 1 has the general characteristics of World War II era temporary military buildings). The building is in a poor state of repair and does not appear to have any significant architectural characteristics. It is not believed to be eligible for nomination to the National Register of Historic Places.

Urban Legal Description n/a

SEE CONTINUATION SHEET

Field Code 970916c - 6

SITS No.

OWNER'S NAME, ADDRESS, PHONE # Lloyd Leidholm, address unknown.

PROJECT TITLE 970919c

REPORT TITLE Results of Class II and Class III Cultural Resource Inventories for Upgrades to Telecommunication Lines: The Washburn Exchange.

SITE AREA (in square feet) 87,940

ACCESS From North Dakota 200 on the north side of Washburn, go west on County Road 17 for 7.5 miles. Turn north and go 1.75 miles. Turn west and go 2.7 miles. The site is on the south side of the road.


DESCRIPTION Three standing buildings, a windmill, a poured concrete basement, a trash dump, and five recent granary foundations were recorded at this site. The site is abandoned.

Records on file at the McLean County Register of Deeds Office indicates that Alfred Svenson received a patent from the United States for land containing the site on May 5, 1904. Anna Kristina Johanson, Svenson's sister, inherited the property on February 21, 1921. Johanson sold the property to Geo. E. Swanson on November 30, 1925. Victor Leidholm purchased the land on January 14, 1926. The property is still in the Leidholm family.

SUMMARY OF SITE FEATURES AND EVALUATION OF SIGNIFICANCE Feature 1 is a large garage and shop area. Feature 2 is a two stall garage. Feature 3 is a house. Feature 4 is a windmill (see also, Archeological and Historical Site Form). None of the buildings or the windmill are in use.


The features on this site are unusual for a farmstead. In particular, there is evidence for at least two houses (Feature 2 and archeological Feature 5) and no evidence of a barn. Rather than a farmstead, this site may be the remains of some type of small rural community. This is not, however, indicated by the deed information.

This site will be avoided by the proposed telecommunications project. As a result, the significance of the site was not fully evaluated. The individual buildings do not appear to be architecturally significant.



• •

• ٠ ÷





Feature 1, north and west elevations, view to the southeast; 970919c, Roll 100, Negative 18.



Feature 1, south and east elevations, view to the northwest; 970919c, Roll 100, Negative 20.