## NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Kost Sch	ool	_	5	SITS# 32 ML	1253
Map Quad Turtle Creek S Map Quad	:W	Site		School	
LTL T144 N., R LTL TN., R LTL TN., R LTL TN., R	81 W., Sec. 8 W., Sec W., Sec	_ QQQ <u>8</u> of _ QQQ of _ QQQ of	the <b>QQ</b> <u>8</u> the <b>QQ</b>	of the <b>Q</b> <u>8</u> of the <b>Q</b> _ of the <b>Q</b>	Subsection 1 = N½ 2 = E½ 3 = S½
NAD 1983 UTM NAD 1983 UTM	5242125 577 S SW Rural Ctural Features:		_		4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾
Fieldwork Date: 09/2  Reconnaissance Survey	4	Intensive Su	rvey		
Project & Principal Investi Apex Discovery Wind Proj		storian			
Contracting Firm or Agen Quality Cultural Resource	-	Form:			
Additional Information:					
SHSND USE  Component  Component  Component	Study Unit	Verified S	Site	_ CR Type	
Recorded By:	Kristyn Wa	ırd	Date R	ecorded:	09/20/2023

### NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

UPDATE

Field Code Kost Sc	hool	SITS# 32 ML	1253
Complete one Page 2 f	for <i>each</i> architectural feature	at the site.	
Architectural Feature # _	1		
Construction Date			
Feature Date			
Structural System			
Original Owner's Ethnici	ity		
Feature Type			
Secondary Exterior			
Condition Fair			
Plan Shape			
	on		
	Recommendation(s) (Check a		
Individual nomin		ш шасарріу).	
	potential district		
✓ No nomination p	•		
Will not contribu			
Potential district	—feature would be a contributi	ng element if other properties o	constitute a district
Thematic nomin	ation potential		
Component of a	historic site or landscape		
site, orientation,	all applicable choices)—a) relocation landscape, and spatial relation amaged eligibility		
Historical associ	ations require further investiga	tion	
Recorded By:	Kristyn Ward	Date Recorded:	09/20/2023

## NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

П	D		Λ	т	
 u	г	u	н	М	

Field Code Kost School	SITS# 32 ML 1253

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

[2023] The north and west facade have updated corrugated sheet metal siding that covers the windows and double door mentioned in the site from from 2011. Wood block and sheet metal patches are on the eastern facade. A flat roofed addition was added to the south side of the schoolhouse. Walls on the south and west portion of the addition are enclosed with corrugated sheet metal. The east side is open. This addition appears in the photographs from the 2011 report but were not addressed in the description. The roof on both the original structure and the addition are missing roofing pieces and have deteriorated further in comparison with the photographs in the 2011 report.

Since the original location of this school house cannot be determined but we do know it does not originate at this site this building does not retain integrity of location, setting, feeling, or association. The updated materials on the exterior and the addition of the lean-to and electricity mean this structure also does not retain integrity for design, materials, or workmanship. This feature is recommended not eligible for the National Register of Historic Places.

2. Owner's Contact Information:

<b>Recorded By:</b>	Kristyn Ward	<b>Date Recorded:</b>	09/20/2023

## NDCRS ARCHITECTURAL FORM PAGE 4 - Site Description

		PAGE 4 –	Site Description	UPDATE
Fi	ield Code Kost School		SITS# 32 ML	1253
3.	Site Area (ft²):			
4.	Description of Access and Site	e Setting:		
			d 0th Street SW proceed for miles. The farmstead will b	
5.	Summary of ALL Site Feature	s and Evaluation of S	ignificance:	
	the farmyard where the school	house is located. None	ed in 2011. 14 additional features of the additional structures are s National Register of Historic Plac	ignificant or distinct
c	Deferences/Comments			
ο.	References/Comments:			
R	ecorded By:	Kristyn Ward	Date Recorded:	09/20/2023

### NDCRS ATTACHMENT SECTION

Field Code Kost School

**SITS# 32** ML\_ 1253\_\_\_\_\_



Figure 2. Feature 1 facing east. K. Ward 09/20/2023.



Figure 3. Feature 1 facing northwest. K. Ward 09/20/2023.

Recorded By: Kristyn Ward Date Recorded: 09/20/2023

### NDCRS ATTACHMENT SECTION

Field Code Kost School

**SITS# 32** ML\_ 1253\_\_\_\_\_



Figure 4. Feature 1 facing west. K. Ward 09/20/2023.



Figure 5. Feature 1 facing southwest. K. Ward 09/20/2023.

Recorded By: Kristyn Ward Date Recorded: 09/20/2023

### NDCRS ATTACHMENT SECTION

Field Code Kost School

**SITS# 32** ML\_ 1253\_\_\_\_



Figure 6. Feature 1 facing southeast. K. Ward 09/20/2023.



Figure 7. Feature 2 facing south. K. Ward 09/20/2023.

Recorded By: Kristyn Ward Date Recorded: 09/20/2023

# NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 ML 1253

SITE IDENTIFICATION					
Field Code Kost School			ame Kost School		
Map Quad Turtle Cve	ek sw	Site N 	ame		_
LTL TWP R. LTL TWP R. LTL TWP R. LTL TWP R.		SEC SEC SEC SEC	QQQ <u>8</u> QQQ QQQ	QQ QQ	Q <u>8</u> Q Q Q
UTM		N E	ZONE NAD 1927	NAD 1983	Subsection: 1 = N½ 2 = E½
City: Washburn ND 58577					3 = S½
Street Number: 708					4 = W½ 5 = NE¼
Street Name: 23rd Ave SW	/				6 = SE¼ 7 = SW¼
Urban Legal Description:_					8 = NW1/4
SITE DATA					
Total # Architectural Feat	ures:	1			
Fieldwork Date:8/9	9/2011				
Reconnaissance Survey	✓_	Intensive Surv	ey		
Project Title & Supervisor:					
Country Schoolhouse Pro	ject				
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Area of Significance Area of Significance	Ecozone		erified Site on-Site	_ CR Type	_2_
Recorded By(First Name	Kathy & Last Name)	Wilner	Date	Recorded	8/9/2011 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Rost School		SI1S# 32.	IAIL
Complete one Page 2	2 for each architectural fo	eature at the site.	
Architectural Feature #	11		
Construction Date	Feature Type	9 Condition <u>5</u>	<u> </u>
Feature Date 2	Context 7	Plan Shape	5
Structural System 25	Primary Exterior	26 Style Gab	le Front
Original Owner's Ethnicity	Secondary Exteri	or Architect/Bu	ilder
Other Information:			
Foundation Poured Concre	ete	Stories1	<u>-</u>
Roof/Cornice Gable Roof			
Window boarded	penings		
	e of building and lack of insulati		
Individual nominatContributes to a portion of a his contribute to a portion pote to a portion of a his contribute to a portion of a his component of a his corrected original secretates original secretates.	ential  to a district  feature would be a contributing  on potential  storic site or landscape  applicable choices)—a) relocat site, orientation, landscape, & s	element if other properties of the control of the c	c period; b)
with neighboring s	tructures; d) relocation has dam	aged eligibility	
	and require faithful invocagation		
Recorded By	Kathy Wilner	Date Recorded	8/9/2011

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Kost School	SITS# 32 <u>ML</u>
------------------------	--------------------

### Complete a Page 3 for each feature.

### 1. Feature Description, Integrity, Eligibility:

This small building has been on the Kost farmsite for many years and nothing is known about the original location of the building. It measures 16 feet north to south and 20 feet east to west. It has two windows on the north wall and one on the south wall along with the entry door. It has wood lap siding on the outside and wood siding inside with about 1/3 of the bottom of the wall simple wainscoating. The ceiling is tongue and groove and the floor is a simple wood floor. The owner doesn't know when it was moved onto the farm but he does know that It sits on concrete foundation that was poured by Rudy and Ruth Kost about 1940. I think it is a much older school as there is no insulation. It did not have electricity before it was moved to the farm to be used for storage. The west side of the bulding has a double door for easier access to the inside. The building is beginning to list to the south. The roofing is very tired and looks to be old asphalt and the chimney is almost gone.

Recorded By	Kathy Wilner	Date Recorded	8/9/2011	
_	ne & Last Name)		(mm/dd/year)	

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Kost School		SITS# 32_	ML
Complete one Page 4	for the entire site.		
2. Owner's Contact Informa	ation:		
Dennis and Betty Kost 708 23rd Ave SW Washburn ND 58577			
3. Access (to rural areas):			
Hwy 83 at Washburn, Cou farm will be on the right.	nty Rd. 22 to 1.7 miles east a	and turn left (north) and drive 2	miles. The Kost
4. Site Area (ft²):			
5. Description of <b>SETTING</b>	:		
The school sits in the midd corral and beyond that field		the north, west and south. To	the east there is a
Recorded By (First Name)	Kathy Wilner	Date Recorded	8/9/2011

**Recorded By** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Kost School	SITS# 32 ML	
6. Summary of ALL Site Features & Evaluation	on of Significance:	
7. Deferences/Comments		
7. References/Comments: Kathy Wilner		
366 43rd Ave SE Bowdon ND 58418		

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

Date Recorded

8/9/2011

(mm/dd/year)

**Kathy Wilner** 

(First Name & Last Name)



Address McLean ND





Small One Room School (Kost School)

Hathy Wilner

ML





Top – Dennis Kost Farm 8/9/2012 Bottom – Dennis Kost Farm 8/9/2012

North Side West Side Kathy Wilner Kathy Wilner

ML ML



Top – Dennis Kost Farm 8/9/201 Bottom – Dennis Kost Farm 8/9/201

East Side South Side

Kathy Wilner Kathy Wilner

ML ML