

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

SITS# 32 ML 1267

SITE IDENTIFICATION

Field Code Josephson School Site Name Josephson School

Map Quad Turtle Creek SW Site Name _____

Map Quad _____

LTL	TWP	<u>144</u>	R	<u>81</u>	SEC	<u>8</u>	QQQ	<u>8</u>	QQ	<u>8</u>	Q	<u>8</u>
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

UTM _____ N ZONE _____
 UTM _____ E NAD 1927 _____ NAD 1983 _____

Subsection:
1 = N $\frac{1}{2}$
2 = E $\frac{1}{2}$
3 = S $\frac{1}{2}$
4 = W $\frac{1}{2}$
5 = NE $\frac{1}{4}$
6 = SE $\frac{1}{4}$
7 = SW $\frac{1}{4}$
8 = NW $\frac{1}{4}$

City: Washburn ND 58577

Street Number: 708

Street Name: 23rd Ave SW

Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 1

Fieldwork Date: 8/9/2011

Reconnaissance Survey Intensive Survey _____

Project Title & Supervisor:

Country Schoolhouse Project

Report Title & Author(s):

Additional Information: _____

SHSND USE

Area of Significance <u>2</u>	Ecozone <u>19</u>	Verified Site _____	CR Type <u>2</u>
Area of Significance _____	Ecozone _____	Non-Site _____	
Area of Significance _____			

Recorded By Kathy Wilner Date Recorded 8/9/2011
 (First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data**

Field Code Josephson School

SITS# 32 ML

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Type 9

Condition 4

Feature Date 3

Context 7

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Other Style

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information:

Foundation It sits on concrete blocks Stories 1

Roof/Cornice Hip roof

Window Double hung

Dating Method(s): McLean County History

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By Kathy Wilner
(First Name & Last Name)

Date Recorded 8/9/2011
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**

Field Code Josephson School

SITS# 32 ML

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

This school building was built in Satterlund School District #3. It was moved 1/2 mile north of its original location to the Kost farm. Today is it used for storage. The building is of wood construction with horizontal lap siding. Most of the paint is gone and the building is pretty tired. I can see that it was a stately school in its day, it has a dormer on the roof above the entry. At one time there was a window in the dormer but it is boarded up today. The roof has some shakes, bare wood and holes. There are two covered windows on the west side, either side of the door. Once upon a time there was a transom window above the door. On the south side of the school I see a small, hinged door that was used to unload fuel into the school. The coal room is to the right as you go into the building. The south side also has three sets of two windows each, some covered and some with glass broken out and these are not covered. The coat room was to the left as you entered the school with the door into the main body of the building at the north end of the interior wall. The main room has a very high ceiling, mostly falling in today. It was lather and plaster with pressed tin over the plaster. The north wall still has the blackboard on it. The walls look to be mostly lathe and plaster with some type of siding in some areas, perhaps repairs along the way. At the top of the wall there is cornice molding. The west wall has built in book cases, have not seen many of these in other schools. The chimney used to be on the west wall. The floor is tongue and groove wood and there is wainscoating along the walls. Today the building sits on concrete blocks. There is electricity evidenced by wires and etc. on the west end of the building. There is also a small light fixture above the door. According to school records this school closed at the end of the 1953/53 school year.

Recorded By Kathy Wilner Date Recorded 8/9/2011
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

Field Code Josephson School

SITS# 32 ML

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Dennis and Betty Kost
708 23rd Ave SW
Washburn ND 58577

3. Access (to rural areas):

Hwy 83 at Washburn, County Rd. 22 to 1.7 miles east and turn left (north) and drive 2 miles. The Kost farm will be on the right.

4. Site Area (ft²): _____

5. Description of **SETTING**:

There is open farm land to the south of the school, to the north and northeast there are a number of farm buildings, to the east are trees. The land is slightly rolling.

Recorded By Kathy Wilner
(First Name & Last Name)

Date Recorded 8/9/2011
(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

Field Code Josephson School

SITS# 32 ML

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 8/9/2011
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



Address McLean ND

Get Google Maps on your phone
Text the word "GMAPS" to 466453




Josephson School

Kathy Wilner

ML

Dennis Kost Farm



Josephson School 8/9/2011 South Side Kathy Wilner ML

Josephson School 8/9/2011 West Side Kathy Wilner ML





Josephson School 8/9/2010 North Side Kathy Wilner ML

Josephson School 8/9/2010 East Side Kathy Wilner ML

