NDCRS 2009

State Historical Society of North Dakota

NDCRS	ARCHITECTURAL	SITE	FORM	
	PAGE 1			
			SITS# 3	2

	PAG		SITC# 22	<u>ml 1301</u>
SITE IDENTIFICATION			5115# 52	ML 1201
Field Code Sverdrup District #9				
Map Quad Washburn Map Quad	Site	Name		
LTL TWP R LTL TWP R LTL TWP R LTL TWP R	SEC		QQ QQ	
UTM	N E	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:				3 = S½
Street Number:				$4 = W\frac{1}{2}$ 5 = NE ¹ / ₄
Street Name: 3rd St SW				6 = SE¼ 7 = SW¼
Urban Legal Description:				8 = NW ¹ / ₄
SITE DATA				
Total # Architectural Features:	1			
Fieldwork Date: 5/26/2014				
Reconnaissance Survey 🖌	Intensive Su	rvey		
Project Title & Supervisor: Country Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Ecozone Area of Significance Ecozone		Verified Site Non-Site	_ CR Type	2
	/ Wilner	Date	Recorded	5/26/2014
(First Name & Last Name)				(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2Feature Data				
Field Code Sverdrup District #9		SITS# 32	ML	
Complete one Page 2 for each	architectural feature at th	e site.		
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition 5		
Feature Date 2	Context 7	Plan Shape 5		
Structural System 25	Primary Exterior <u>26</u>	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Concrete and skids	_ Stories1			
Roof/Cornice_Gable				
Window All covered				
Dating Method(s): McClean County sch	nool records		<u> </u>	

Feature Preservation Recommendation(s) (Check all that apply):

- ____Individual nomination
- ____Contributes to a potential district
- ____No nomination potential
- Will not contribute to a district
- ____Potential district—feature would be a contributing element if other properties constitute a district
- -----Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	5/26/2014
	(First Name & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Sverdrup District #9

SITS#	32		MI

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

A one room prairie school sitting on concrete and skids. It was moved from its original location to a farm site to be used for grain storage. The roof has remnants of asphalt shingle over wood shakes. The chimney is gone and the hole sealed up. Eight inch moulding runs under the roof line on either end of the building, undrer the peak of the roof. There is a metal ridge cap with ball finials topping the peak of the roof. The school measures 18 feet north to south and 22 feet east to west.

The walls are 6 inch wood lap with little paint left. Wood corner trim is 4 inches wide. All the windows have been covered and boards are attached to the north and south walls for for anchors and cables to connect to to hold the building together. The west end has wood without seams offset, at one time there was an entry connected to the building at that point. Two doors were added to south side of the building, neither were entry doors for the school. There also two high openings, one at either end of the building, that open for augering grain into the building.

Much of the interior of the building was gutted with the exception of the wainscoating and some of the upper parts of the walls were covered with board lumber. The west wall still has as blackboard. There is no electricity. A wall was built in the middle of the building to make two sections.

Recorded By Kathy Wilner Date Recorded 5/26/2014
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Sverdrup District #9

SITS# 32_____ML

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Brad and/or Tom Sheldon 327 23rd Ave SW Washburn ND 58577

3. Access (to rural areas):

This building is located 1/2 miles west of 23rd Ave SW or Highway 200A on 3rd St SW.

4. Site Area (ft²):

5. Description of SETTING:

The school sits at a bin site. Formerly it was an operating farm. There is a field directly south, trees and buildings all other directions.

Recorded By Kathy Wilner Date Recorded 5/26/2014
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Sverdrup District #9


SITS# 32 _____ ML ___

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 5/26/2014 (First Name & Last Name) (mm/dd/year)






South Side

Sverdrup District #95/26/2014Kathy WilnerML

West Side



North Side Sverdrup District #9 5/26/2014 Kathy Wilner ML East Side