# NDCRS ARCHITECTURAL FORM PAGE 1

| Field Code Meller Scho   | ool            | _   | SITS# 32 ML  | 1400             |  |  |
|--|----------------|---|--|------------------|--|--|
| Map Quad Kongsberg   |                | Site Name   | Meller School  |                  |  |  |
| Map Quad   |                |   |  |                  |  |  |
| LTL T. 150 N., R. 79 LTL T. N., R. LTL T. N., R. LTL T. N., R. LTL T. N., R. NAD 1983 UTM NAD 1983 UTM |                | QQQ of the Q<br>QQQ of the Q<br>QQQ of the Q<br>Zone <u>14N</u> | <b>Q</b> of the <b>Q</b><br><b>Q</b> of the <b>Q</b> | 1 = N½<br>2 = E½ |  |  |
| City:  |                |   |  | 8 = NW1/4        |  |  |
| Street Number:   |                |   |  |                  |  |  |
| Street Name: Highway 53  | 3              |   |  |                  |  |  |
| Urban Legal Description:   |                |   |  |                  |  |  |
| Total Number of <b>Architectu</b>  | ıral Features: | 1   |  |                  |  |  |
| Fieldwork Date:05/31   | /2021          |   |  |                  |  |  |
| Reconnaissance Survey  | <u></u>        | Intensive Survey _  |  |                  |  |  |
| Project & Principal Investiga  | ator:          |   |  |                  |  |  |
| Country School House Proje<br>Kathy Wilner<br>366 43rd Ave SE, Bowdon, N                               |                |   |  |                  |  |  |
| Contracting Firm or Agency Completing the Form:  |                |   |  |                  |  |  |
| A LPS and S  |                |   |  |                  |  |  |
| Additional Information:  |                |   |  |                  |  |  |
| SHSND USE  Component S  Component  | Study Unit     | Verified Site   | CR Type  |                  |  |  |
| Recorded By:   | Kathy Wilne    | er Da   | ite Recorded:  | 06/05/2021       |  |  |

### NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

| Field Code Meller S           | chool                             | SITS# 32 <u>M</u>              | <u>L</u> <u>1400</u>  |
|-------------------------------|-----------------------------------|--------------------------------|---|
| Complete one Page 2 f         | or each architectural feature     | at the site.                   |   |
| Architectural Feature # _     | 1                                 |                                |   |
| Construction Date             |                                   |                                |   |
| Feature Date <u>1900-1</u>    | 915                               |                                |   |
| Structural System Wo          | ood Frame                         |                                |   |
| Original Owner's Ethnici      | ty                                |                                |   |
| Feature Type <u>9 - Schoo</u> | l; Church school                  |                                |   |
| Context Education             |                                   |                                |   |
| Primary ExteriorWoo           | od, Horizontal Siding             |                                |   |
| Secondary Exterior            |                                   |                                |   |
| Condition Fair                |                                   |                                |   |
| Plan Shape L-Shape            | ed                                |                                |   |
| Style Other Style             |                                   |                                |   |
|                               |                                   |                                |   |
| Foundation Poured Co          | oncrete                           | Stories 1.0                    |   |
| Roof/Cornice Gable            |                                   |                                |   |
| Window Double hung,           | framing, no glass, some covere    | d                              |   |
| Dating Method(s)Esti          | mate                              |                                |   |
| Miscellaneous Information     | on                                |                                |   |
| <i>Feature</i> Preservation R | Recommendation(s) (Check a        | Il that apply):                |   |
| Individual nomina             | . , ,                             | ,                              |   |
| Contributes to a              | potential district                |                                |   |
| No nomination p               | otential                          |                                |   |
| Will not contribut            | e to a district                   |                                |   |
| Potential district-           | -feature would be a contributing  | ng element if other properties | constitute a district   |
| Thematic nomina               | ation potential                   |                                |   |
| Component of a                | historic site or landscape        |                                |   |
| site, orientation,            |                                   |                                | ric period; b) recreates original<br>kt with neighboring structures; d) |
| Historical associ             | ations require further investigat | tion                           |   |
|                               |                                   |                                |   |
| Recorded By:                  | Kathy Wilner                      | Date Recorded:                 | 06/05/2021  |

## NDCRS ARCHITECTURAL FORM PAGE 3 - Feature Data

|    |  | PAGE 3  | – Feature Data  |  |  |  |
|----|--|---|---|--|--|--|
| Fi | eld Code Meller School   |   | SITS# 32 ML   | 1400   |  |  |
| Co | Complete one Page 3 for <i>each</i> architectural feature at the site.   |   |   |  |  |  |
| 1. | Feature Description, Integrity   | , Eligibility:  |   |  |  |  |
|    | -  | red with failing asphalt s  | coured concrete foundation. The shingles with metal capping and fir osed.   | •  |  |  |
|    | corner trim. It looks like they the building has two double h windows on the north side wh There are three more window | moved two similar school<br>ung window openings of<br>nich butts up to trees. Of<br>son the west wall, most | remaining siding is 6 inch wood la<br>of buildings together to make a ho<br>in both the south and east walls. The<br>ne window faces east on the west<br>try covered, no glass in any of the<br>wood door. I don't see any indicate | me. The east end of here are more part of the building. windows. The entry |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
|    |  |   |   |  |  |  |
| 2. | Owner's Contact Information  | :   |   |  |  |  |
|    | Reuben & Alvin Meller<br>Garland Texas   |   |   |  |  |  |
| Re | ecorded By:  | Kathy Wilner  | Date Recorded:  | 06/05/2021   |  |  |

#### NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

|  | PAGE 4 – S                | Site Description   |            |
|--|---------------------------|--|------------|
| Field Code Meller School   |                           | SITS# 32 ML  | 1400       |
| 3. Site Area (ft²):  |                           |  |            |
| 4. Description of Access and Si  | te Setting:               |  |            |
| _  | th. To reach this prop    | h, a barn and other small b<br>perty you go west on Highw<br>e of the farm site. | =          |
| 5. Summary of ALL Site Feature   | res and Evaluation of Siç | gnificance:  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
|  |                           |  |            |
| C. Defenses and Comments.  |                           |  |            |
| 6. References/Comments:  |                           |  |            |
| Photos courtesy of Karen Hei<br>Kathy Wilner<br>366 43rd Ave SE<br>Bowdon ND 58418 | man.                      |  |            |
| Recorded By:   | Kathy Wilner              | Date Recorded:   | 06/05/2021 |



West Side

Meller School 5/31/2021 Kathy Wilner ML

### Southeast Side





East Side

Meller School 5/31/2021 Kathy Wilner ML



Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 200 ft

Feature